Costs for WO #02-60456-0 AND ALL ASSOCIATED SUBS

MO.NO.....	Description.....	Part No	Part Noun Qual.....	Part Qty Issued	Tot Material Act	Act Tot Labor Cost	Actual Tot Cost
		6612	ANTI-SEIZE, HI TEMP	0			
		D	HOSE, FLEXIBLE, SS, WITH 304 SS BRAID ON OUTSIDE, 316 SS CORE TUBE, AND 1/2" TUBE CONNECTOR ON BOTH ENDS, 1,500 DEG F WORKING TEMPERATURE, > 250 PSI PRESSURE RATING, SSP P/N 8CF1632FN32FNS6-23"	0			
		D	DESLAGGER, AUTOMATIC PORT, SYN-FAB P/N MSS0034	0			
		D	WALLBOX, HD, SYN-FAB P/N SAM0007	0			
		49988	PLATE, CHECKER	0			
		7739	CAP, 02.00 THREADED	0			
		25443	PIPE, SEAMLESS	0			
		57539	THERMOCOUPLE, TYPE E	0			
		57175	FITTING, BRASS CONNECTOR	0			
		77301	TUBING, 00.500 OD	0			
		2627	BOARD, FOXBORO (CCS)	0			
		D	TUBE FIXTURE, TWO T8, FLUORESCENT, WITH REFLECTOR, LITHONIA P/N AF-2-32-277	0			
		D	LAMP, FLUORESCENT, 48", PHILLIPS P/N F32T8/TL735/ALTO, CODALE P/N 126804, GE P/N F32T8/SP35/ECO	0			
02-60456-06	SEND OUT FOR REBUILD, BREAKER, 80 AMPS, 3 POLES, 600 VOLT MOLDED CASE, WESTINGHOUSE #HFB3080.	D	REPAIR AND RETURN, BREAKER, CIRCUIT, MOLDED CASE, 80 AMPS, 3 POLE, 600 VOLT, WESTINGHOUSE #HFB3080. REBUILD TO LIKE NEW CONDITION, TEST AND RETURN.	0	0.00	0.00	0.00
02-60456-07	INSTALL SCAFFOLDING AS PER DARWIN BILLS NEEDS AND INSTRUCTIONS, CONTACT DARWIN			0	0.00	599.00	599.00
02-60456-08	UNIT 1 PREOUTAGE: DISCONNECT AND REMOVE ELECTRICAL FROM N/S 9TH FL WALL BLOWERS.			0	0.00	618.97	618.97
02-60456-09	REPBUILD AND/OR REPAIR 0050.0 AMP BREAKER.			0	0.00	0.00	0.00
02-60456-10	UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER"	76469	ICE, CUBED	440	4,756.51	459.36	5,215.87

IP7_039439