Schoenbauer Furniture Service, Inc.
P.O. Box 833
Charlotte Hall, MD 20622
Office: (800) 955-7603
Fax: (301) 884-3672
SFS Account Manager: Katie Schoenbauer Morgan, x109
Email: katie@schoenbauer.com
Commercial, Furniture

Invoice

Date Billed	Order Number
06/05/17	52796
COMPLETE BILLING	

Federal Tax ID Number: 52-2183688

Billed To:
US EPA Headquarters
WJC West, Room B200M
1301 Constitution Ave NW
Washington DC 20004

Contact: Severa Wilson
Phone:
Cell:

Customer:
US EPA Headquarters
WJC West, Room B200M
1301 Constitution Ave NW
Washington DC 20004

Alternate Contact:
Pornthida Praphanpoj

Cell: 202-564-3787

Date of Order	*Work Order Type*	*Claim #*	*Claim Type*	*Date of 1st Appointment*	*Inspection Fee Status*
05/22/17	Repair Per Estimate		Furniture		

Piece #	*Inventory #*	*Weight*	*Item Name*	*Cash Out Amount*	*Estimated Charges*	*Total Charges*
1			EXECUTIVE DESK		$2,075.00	$2,075.00

Estimate to refinish executive desk, changing color to match customer's provided sample as closely as possible.
*Will need physical color sample to match.
ADDED: Remove front center panel between double pedestals. $175
5/22/17 - Desk was delivered to our shop.
6/2/17 - Desk and color sample were picked up from our shop.

All estimates are good for 6 months from the date of this report. DC residents may be subject to sales tax.
Bill Schoenbauer - 4th Generation Craftsmanship
See a list of our specialized services at Schoenbauer.com

Totals:	*$2,075.00*
Total Repair Costs:	**$2,075.00**
SubTotal:	**$2,075.00**
DC Tax:	**$0.00**
Total:	**$2,075.00**
Prior Payments:	**$0.00**
Total Estimated Balance:	**$2,075.00**

ACCEPTANCE OF PROPOSAL

The above prices and specifications are satisfactory and are hereby accepted. Schoenbauer Furniture Service, Inc. is authorized to do the work specified.

The above estimates are based on performing all of the above work. Estimate fee will be applied only if authorized repairs exceed $500. The above estimates are guaranteed for six months from the date of this report. After six months a re-inspection will be required and a second inspection fee will be charged.

SIGNED (b)(6) Signature [redacted] DATE 5/24/12