FLOW CHART #2: PROCESSING Cl_2 CYLINDERS




Close vacuum valve
Disconnect cylinder
Check for vacuum
(Finger test)
No vacuum
Connect to De-gas station
Repeat process
Vacuum
Remove Valve
Internal inspection
Corroded
Scrap
Hydrostatic test
Passes
Process
Passes
Install new or rebuilt valve
Paint cylinder & bonnet
Fill cylinder
(see Flow Chart #3)
Sediment
Invert & Remove
Wet inside
Mark "Dirty"
Clean
Re-inspect
Process

JCI JONES CHEMICALS, INC.
BLOCK FLOW DIAGRAM
CHLORINE BLOW & VACUUM SYSTEMS
Milford, Virginia Branch



JOI JONES CHEMICALS, INC.
BLOCK FLOW DIAGRAM
CHLORINE PIPING SYSTEM
Milford, Virginia Branch