Flying B-29 EPA ID: WA10589
1611 S. Canyon Rd
Ellensburg, WA 98926

Potential Violations noted on 4/18/12 UST inspection:

(1) WAC 173-360-335 (2)(a): Failure to monitor tanks at least every 30 days.

(2) WAC 173-360-350 (3): Failure to provide any release detection on underground piping.

(3) WAC 173-360-310 (3): Failure to install cathodic protection for metal piping upgrade requirements.

AIRFORCE.COM 1-800-423-USAF
U.S. AIR FORCE
CROSS INTO THE BLUE

5-8-12
Received fax from facility
(1) Tank + pipes SIR for Feb 12 + Mar 12
(2) LTT + ALCD test (2011)
(3) CP test on I.C. (5/11)

Provide additional documentation to:

Ben Horwitz
US EPA
1200 Sixth Ave
Suite 900 OCE-082
Seattle WA 98101

or horwitz.benjamin@epa.gov

B. 4-18-12