6/16/16 Blount

Tina, Greg G, Paul, Jerry

- 10 days discontinue use, to be absent from batch so no influence the stack test.
- No problem w/ that. Not about chosing to operate
- 2 week - 4 week turnaround for test results
- ADI has a determination regarding HEPA
  - monitoring was identified as improper