MODULE E – PROJECT PLANS

GSDT TAB: TESTING AND MONITORING

Module E.1 Testing and Monitoring Plan Attachment Quality Assurance and Surveillance Plan (QASP)

The Quality Assurance and Surveillance Plan (QASP) (attachment to the Testing and Monitoring Plan in Module E "Project Plans" is provided as CBI. The QASP is submitted as a document called "1 QASP.pdf" and is located in the "6 Testing and Monitoring Plan" folder.

Please Note: The "*QASP"* narrative has been submitted as Confidential Business Information (CBI). This document has been submitted to meet the requirements of the "Testing and Monitoring" tab in Module E of the Geologic Sequestration Data Tool (GSDT).