4254500 13041 100382

~~Please print~~ or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 020767815 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Site Address (if different than mailing address)
Generator's Phone: ~~(219) 399-3189~~

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name
U.S. EPA ID Number

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu
Signature:
Month 09 Day 04 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: William Hovorka
Signature:
Month 09 Day 04 Year 19

Transporter 2 Printed/Typed Name
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

18b. Alternate Facility (or Generator) Manifest Reference Number:
U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name:
Signature:
Month 09 Day 04 Year 19

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

4265500 13041 100450

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 020767816 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA, LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinsho
Signature:
Month 9 Day 9 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: William Howorka
Signature:
Month 09 Day 09 Year 19

Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Leonard Fry
Signature:
Month 09 Day 09 Year 19

GENERATOR — INT'L — TRANSPORTER — DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

426600 / 13041 100476

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of: 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 020767817 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: ~~(219) 399 3189~~
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trentinshu
Signature:
Month Day Year: 09 10 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: William Horarka
Signature:
Month Day Year: 09 10 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year:

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator) U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator) Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Leonard F. Itoy
Signature:
Month Day Year: 09 10 19

GENERATOR / INT'L / TRANSPORTER / DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. DESIGNATED FACILITY TO GENERATOR

426720 | 13041 | 100501

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 020767818 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: ~~(219) 399-3189~~
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Marwa Trenkinsho
Signature:
Month Day Year: 09 11 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: William Hovorka
Signature:
Month Day Year: 09 11 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year:

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator) U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Leonard R Story
Signature:
Month Day Year: 09 11 19

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. DESIGNATED FACILITY TO GENERATOR

1057 427 1800 13041 100524

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
	IND 005 462 601	1	(219) 399-2492	020767808 JJK

5. Generator's Name and Mailing Address
ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC. — U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name — U.S. EPA ID Number:

8. Designated Facility Name and Site Address
ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	G	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu — Signature: [signature] — Month 09 Day 12 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: William Hovorka — Signature: [signature] — Month 09 Day 12 Year 19
Transporter 2 Printed/Typed Name — Signature — Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator) — U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator) — Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Dennis Glowacki — Signature: [signature] — Month 9 Day 12 Year 19

GENERATOR — INT'L — TRANSPORTER — DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. DESIGNATED FACILITY TO GENERATOR

427100 13041 L005P

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
	IND 005 462 601	1	(219) 399-2492	020767819 JJK

5. Generator's Name and Mailing Address
ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: ~~(219) 399-3189~~

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name
U.S. EPA ID Number

8. Designated Facility Name and Site Address
ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu
Signature
Month Day Year: 09 12 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: William Hovorka
Signature
Month Day Year: 09 12 19
Transporter 2 Printed/Typed Name
Signature
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Stan Pale
Signature
Month Day Year: 09 12 19

GENERATOR — INT'L — TRANSPORTER — DESIGNATED FACILITY

427290 13041 100246

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 020767807 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399 3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) ~~(if I am a small quantity generator)~~ is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu
Signature:
Month 09 Day 13 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: William Hoover Jr
Signature:
Month 09 Day 13 Year 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator) U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator) Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Leonard K Stoy
Signature:
Month 09 Day 13 Year 19

GENERATOR — INT'L — TRANSPORTER — DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. DESIGNATED FACILITY TO GENERATOR

427400 13041 101565

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
IND 005 462 601	1	(219) 399-2492	020767822 JJK

5. Generator's Name and Mailing Address
ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: ~~(219) 399-3189~~

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC. — U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name — U.S. EPA ID Number:

8. Designated Facility Name and Site Address
ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinsho — Signature: [signature] — Month 09 Day 16 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: William Hoorka — Signature: [signature] — Month 09 Day 16 Year 19
Transporter 2 Printed/Typed Name — Signature — Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator) — U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) — Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Chinan K Tony — Signature: [signature] — Month 09 Day 16 Year 19

GENERATOR / INT'L / TRANSPORTER / DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. **DESIGNATED FACILITY TO GENERATOR**

4275500 13041 100190

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of: 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 020767824 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: ~~(219) 399-3189~~
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY
Box # 9736

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu
Signature:
Month 09 Day 17 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S.
Port of entry/exit:
Transporter signature (for exports only):
Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Laurence Venditti
Signature:
Month 09 Day 17 Year 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Leonard K Illy
Signature:
Month 09 Day 17 Year 19

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

4276900 13041 100607

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of: 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 020767823 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: ~~(219) 399 3189~~
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY
BOX-9735

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinsho
Signature:
Month 9 Day 18 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month 9 Day 18 Year 19

Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Sean Pike
Signature:
Month 09 Day 18 Year 19

GENERATOR — INT'L — TRANSPORTER — DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. DESIGNATED FACILITY TO GENERATOR

427700 13041 100620

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of: 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 020767825 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Site Address (if different than mailing address):
Generator's Phone: ~~(219) 399-3189~~

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY
BOX 9730

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshio
Signature:
Month 9 Day 19 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month 9 Day 19 Year 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Sean Rabe
Signature:
Month 9 Day 19 Year 19

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

427920 — 13041 — 100411

Form Approved. OMB No. 2050-0039

Please print or type.

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 020767826 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Site Address (if different than mailing address):
Generator's Phone: ~~(219) 399-3199~~

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Marina Trenkinshu
Signature:
Month Day Year: 09 20 19

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S.
Port of entry/exit:
Date leaving U.S.:
Transporter signature (for exports only):

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: William Hourka
Signature:
Month Day Year: 09 20 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year:

DESIGNATED FACILITY

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
U.S. EPA ID Number:
18b. Alternate Facility (or Generator)
Facility's Phone:
Month Day Year:
18c. Signature of Alternate Facility (or Generator)

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Leonard F Troy
Signature:
Month Day Year: 09 20 19

DESIGNATED FACILITY TO GENERATOR

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

4294800 13041 100619

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
	IND 005 462 601	1	(219) 399-2492	021079668 JJK

GENERATOR

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name
U.S. EPA ID Number

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY
Box-9729

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu
Signature
Month Day Year: 9 23 19

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature
Month Day Year: 9 23 19
Transporter 2 Printed/Typed Name
Signature
Month Day Year

DESIGNATED FACILITY

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Leonard E. Long
Signature
Month Day Year: 09 23 19

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. DESIGNATED FACILITY TO GENERATOR

4286700 / 13041 100678

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021079667 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY
Box-2856

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Marina Trentinsku
Signature:
Month Day Year: 9 24 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stoneb Rlcer
Signature:
Month Day Year: 9 24 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year:

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator) U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Steve Paine
Signature:
Month Day Year: 09 24 19

GENERATOR — INT'L — TRANSPORTER — DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

4289100 13041 100720

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of: 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021079666 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY
BOP-9269

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Marsha Trenkinshu
Signature:
Month Day Year: 9 26 19

16. International Shipments: ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month Day Year: 9 26 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year:

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator) U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name:
Signature:
Month Day Year: 09 26 19

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. **DESIGNATED FACILITY TO GENERATOR**

429280 13041 100748

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021079665 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu
Signature:
Month Day Year: 12 27 19

GENERATOR

16. International Shipments ☐ Import to U.S. ☐ Export from U.S.
Transporter signature (for exports only):
Port of entry/exit:
Date leaving U.S.:

TRANSPORTER INT'L

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: William Howorka
Signature:
Month Day Year: 12 27 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year:

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

DESIGNATED FACILITY

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Howard K Hong
Signature:
Month Day Year: 04 27 19

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

4294500 13041 100759

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of: 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021079664 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Marius Trentinshu
Signature:
Month 09 Day 30 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: William Houska
Signature:
Month 09 Day 30 Year 19

Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

18b. Alternate Facility (or Generator) Manifest Reference Number:
U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Leonard E. Gray
Signature:
Month 09 Day 30 Year 19

GENERATOR — INT'L — TRANSPORTER — DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR