4334800 13041 101705

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021081198 JJK

GENERATOR

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: ~~(219) 399-3189~~
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
. 13041 / LMF DUST FROM LADLE MELT FACILITY
Box-2856

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Marwa Trenkinshu
Signature:
Month 11 Day 1 Year 19

INT'L

16. International Shipments ☐ Import to U.S. ☒ Export from U.S.
Port of entry/exit:
Transporter signature (for exports only):
Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials

Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month 11 Day 1 Year 19

Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

DESIGNATED FACILITY

18. Discrepancy

18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

Manifest Reference Number:

18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a

Printed/Typed Name: Leonard K Fry
Signature:
Month 11 Day 01 Year 19

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

4336000 13041 101230

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
IND 005 462 600	1	(219) 399-2492	021081531 JJK

5. Generator's Name and Mailing Address
ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address
ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	06	Y	D006	D007	D008
						D01[illegible]		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Marilyn Trenkinshu
Signature:
Month Day Year: 11 04 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Rich Mysliwc
Signature:
Month Day Year: 11 04 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year:

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Dennis Glowacki
Signature:
Month Day Year: 11 4 19

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

432500 13041 101744

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021081551 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
13041 / LMF DUST FROM LADLE MELT FACILITY
Box - 9735

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Marina Trenkinshu
Signature:
Month 11 Day 5 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month 11 Day 5 Year 19

Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: LEONARD F. FOY
Signature:
Month 11 Day 07 Year 19

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. DESIGNATED FACILITY TO GENERATOR

4341500 13041 101 275

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021081271 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY
Box - 9248

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu
Signature:
Month 11 Day 6 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month 11 Day 6 Year 19

Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Gerard F. Hoy
Signature:
Month 11 Day 06 Year 19

GENERATOR — INT'L — TRANSPORTER — DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

4342400 13041 101276

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021081892 JJK

GENERATOR

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1. RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY
Box-9730

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu
Signature:
Month 11 Day 7 Year 19

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month 11 Day 7 Year 19

Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

DESIGNATED FACILITY

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Leonard K Troy
Signature:
Month 11 Day 07 Year 19

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

437990 13041 101297

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
	IND 005 462 601	1	(219) 399-2492	021081893 JJK

GENERATOR

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	06	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Marina Trentinshi
Signature:
Month 11 Day 8 Year 19

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: RICH MYSLIVE
Signature:
Month 11 Day 8 Year 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

DESIGNATED FACILITY

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Dennis Glowacki
Signature:
Month 11 Day 8 Year 19

4295600 13041 101306

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
IND 005 462 601	1	(219) 399-2492	021081894 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16[illegible] CENTER AVE.
HA[illegible]Y, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY
BOX-9735

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu
Signature:
Month Day Year: 11 11 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month Day Year: 11 11 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year:

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator) U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: LEONARD K [illegible]
Signature:
Month Day Year: 11 11 19

GENERATOR INT'L TRANSPORTER DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. DESIGNATED FACILITY TO GENERATOR

4302900 13041 101326

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021081895 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
. 13041 / LMF DUST FROM LADLE MELT FACILITY

Box-9730

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshiu
Signature:
Month 11 Day 12 Year 19

16. International Shipments
☐ Import to U.S. ☐ Export from U.S.
Port of entry/exit:
Date leaving U.S.:
Transporter signature (for exports only):

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month 11 Day 12 Year 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
18b. Alternate Facility (or Generator)
Manifest Reference Number:
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Leonard K Fling
Signature:
Month 11 Day 14 Year 19

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

4348300 13041 101360

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 604
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021081896 JJK

GENERATOR

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

Box # 9248

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Marya Trenkinshu
Signature:
Month 11 Day 14 Year 19

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Laurence Venditti
Signature:
Month 11 Day 14 Year 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

DESIGNATED FACILITY

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Dennis Glowacki
Signature:
Month 11 Day 14 Year 19

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. DESIGNATED FACILITY TO GENERATOR

4347500 13041 10/4/12

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021081897 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
. 13041 / LMF DUST FROM LADLE MELT FACILITY
Box -9736

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable International and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu
Signature:
Month 11 Day 19 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month 11 Day 19 Year 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator) U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: LEONARD R ITON
Signature:
Month 11 Day 19 Year 19

GENERATOR / INT'L / TRANSPORTER / DESIGNATED FACILITY

4354700 13041 101441

Form Approved. OMB No. 2050-0039

Please print or type.

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021081898 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	06	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Marina Trenkinshu
Signature:
Month Day Year: 11 20 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Rich Mustaine
Signature:
Month Day Year: 11 20 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year:

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
U.S. EPA ID Number

18b. Alternate Facility (or Generator)
Facility's Phone:
Month Day Year

18c. Signature of Alternate Facility (or Generator)

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Dennis Glowack
Signature:
Month Day Year: 11 20 19

GENERATOR | INT'L | TRANSPORTER | DESIGNATED FACILITY

DESIGNATED FACILITY TO GENERATOR

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

105 4357700 / 13041 101470

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
	IND 005 462 601	1	(219) 399-2492	021081899 JJK

5. Generator's Name and Mailing Address ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name
U.S. EPA ID Number

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY
Box#9737

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu
Signature
Month 11 Day 22 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Brandon Short
Signature
Month 11 Day 22 Year 19
Transporter 2 Printed/Typed Name
Signature
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: LEONARD K. ITON
Signature
Month 11 Day 22 Year 19

GENERATOR / INT'L / TRANSPORTER / DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

4358200 13041 101481

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
	IND 005 462 601	1	(219) 399-2492	021081900 JJK

5. Generator's Name and Mailing Address
ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189

Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name
U.S. EPA ID Number

8. Designated Facility Name and Site Address
ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY
Box-9735

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Marya Trenrinshu
Signature:
Month 11 Day 22 Year 19

INT'L
16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER
17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month 11 Day 22 Year 19
Transporter 2 Printed/Typed Name
Signature
Month Day Year

DESIGNATED FACILITY
18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Dennis Glowacki
Signature:
Month 11 Day 22 Year 19

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. DESIGNATED FACILITY TO GENERATOR

4359300 13041 101500

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
	IND 005 462 601	1	(219) 399-2492	021081901 JJK

5. Generator's Name and Mailing Address ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC. — U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name — U.S. EPA ID Number:

8. Designated Facility Name and Site Address ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY
Box-9736

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu — Signature: [signature] — Month 11 Day 25 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker — Signature: [signature] — Month 11 Day 25 Year 19
Transporter 2 Printed/Typed Name — Signature — Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator) — U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) — Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: LEONARD K TOM — Signature: [signature] — Month 11 Day 27 Year 19

GENERATOR — INT'L — TRANSPORTER — DESIGNATED FACILITY

4360900 13041 101530

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator ID Number	2. Page 1 of	3. Emergency Response Phone	4. Manifest Tracking Number
	IND 005 462 601	1	(219) 399-2492	021081902 JJK

5. Generator's Name and Mailing Address ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC. — U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name — U.S. EPA ID Number:

8. Designated Facility Name and Site Address ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY Box 3730

15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu — Signature: [signature] — Month 11 Day 26 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Brandon Short — Signature: [signature] — Month 11 Day 26 Year 19
Transporter 2 Printed/Typed Name — Signature — Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator) U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Edward E Sroka — Signature: [signature] — Month 11 Day 26 Year 19

GENERATOR / INT'L / TRANSPORTER / DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. DESIGNATED FACILITY TO GENERATOR

435610W 13041 101534

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021082351 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

Box # 9248

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu
Signature:
Month 11 Day 26 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Laurence Venditti
Signature:
Month 11 Day 26 Year 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator) U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator) Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Dennis Glowacki
Signature:
Month 11 Day 26 Year 19

GENERATOR / INT'L / TRANSPORTER / DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

4360603 13041 1 of 58

Please print or type. Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021082352 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY

Box 737

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Marnya Trenkinsho
Signature:
Month 11 Day 27 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Brandon Shaw
Signature:
Month 11 Day 27 Year 19

Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator)
U.S. EPA ID Number:
Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Dennis Glowacki
Signature:
Month 11 Day 27 Year 19

GENERATOR — INT'L — TRANSPORTER — DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete. DESIGNATED FACILITY TO GENERATOR

1364400 13041 101560

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021082353 JJK

GENERATOR

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1 RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	1	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
13041 / LMF DUST FROM LADLE MELT FACILITY
Box 2856

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinsho
Signature:
Month 11 Day 27 Year 19

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Brandon Short
Signature: Brandon Short
Month 11 Day 27 Year 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

DESIGNATED FACILITY

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1.	2.	3.	4.
H110			

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Dennis Glowacki
Signature: Dennis Glowacki
Month 11 Day 27 Year 19

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

4364900 13041 11/15/

Please print or type.

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: IND 005 462 601
2. Page 1 of: 1
3. Emergency Response Phone: (219) 399-2492
4. Manifest Tracking Number: 021082354 JJK

5. Generator's Name and Mailing Address: ARCELORMITTAL USA LLC
3001 DICKEY ROAD
EAST CHICAGO, IN 46312
Generator's Phone: (219) 399-3189
Generator's Site Address (if different than mailing address)

6. Transporter 1 Company Name: ENVIRITE OF ILLINOIS, INC.
U.S. EPA ID Number: ILD 000 666 206

7. Transporter 2 Company Name:
U.S. EPA ID Number:

8. Designated Facility Name and Site Address: ENVIRITE OF ILLINOIS, INC.-USE
16435 S. CENTER AVE.
HARVEY, IL 60426
Facility's Phone: (708) 596-7040
U.S. EPA ID Number: ILD 000 666 206

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
X	1RQ, NA3077, Hazardous waste, solid, n.o.s. (cadmium, chromium),, 9, PGIII, (D006), ERG #171	001	CM	6	Y	D006	D007	D008
						D010		
	2.							
	3.							
	4.							

14. Special Handling Instructions and Additional Information
1. 13041 / LMF DUST FROM LADLE MELT FACILITY
Box-9283

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Mariya Trenkinshu
Signature:
Month 11 Day 30 Year 19

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Adam Stonebraker
Signature:
Month 11 Day 30 Year 19
Transporter 2 Printed/Typed Name:
Signature:
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:
18b. Alternate Facility (or Generator)
U.S. EPA ID Number
Facility's Phone:
18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. H110 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Lorraine K Fry
Signature:
Month 12 Day 02 Year 19

GENERATOR | INT'L. | TRANSPORTER | DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 12-17) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR