Export To Excel

Project Number	Project Name	Type of Need	Reasons for Need	NRHE	C/F	Reg/Sec	Design Cap.	Diameter	Length	Number Needed	Cost Estimate	Date of Cost	Doc.
1000	Well Rehabilitation #1	R2	A1	H	C	4A	0.58 MGD			1			6,10
1001	Abandon Inactive Well #2	R5	A1	N	C	4A	0.76			1			6,10
1002	Well Rehabilitation #3	R2	A1	H	F	4A	1.44 MGD			1			6,10
1003	Well Rehabilitation #4	R2	A1	H	F	4A	2.3 MGD			1			6,10
1004	Well Rehabilitation #5	R2	A1	H	F	4A	1.46 MGD			1			6,10
1005	Groundwater Treatment for Well #3	T22	A6	R	F	1B	1.44 MGD			1			6,10
1006	Groundwater Treatment for Well #4	T22	A6	R	F	1B	2.3 MGD			1			6,10
1007	Groundwater Treatment for Well #5	T22	A6	R	F	1B	1.46 MGD			1			6,10
1008	Rehab Rice Rd Plant Aerator	T33	A6	H	F	1B	1.15 MGD			1			6,10
1009	Rehab Rice Rd Plant	T20	A6	H	F	1B,2B	1.15 MGD			1			6,10
1010	Rehab Elevated Storage Tank	S1	A1	H	F	4A	1 MG			1			6,10
1011	Rehab Elevated Storage Tank	S1	A1	H	F	4A	0.3 MG			1			6,10

1012	Rehab Rice Rd Plant Building	R3	A1	H	F	4A				1			6,10
1013	New Well Eastside	R1	A2	R	F	4A	2.88 MGD			1	$2,000,000.00	4/1/2010	2
1014	New Well Clarkdale Rd	R1	A2	R	F	4A	2.88 MGD			1	$2,000,000.00	4/1/2010	2
2000	Existing Distribution Improve.	M1	A1	R	F	4A		6	30474.44 ft				6,10
2001	Existing Distribution Improve.	M1	A1	R	F	4A		8	18763.12 ft				6,10
2002	Existing Distribution Improve.	M1	A1	R	F	4A		10	4128.84 ft				6,10
2003	Existing Distribution Improve.	M1	A1	R	F	4A		12	5284.6 ft				6,10
2004	Existing Distribution Improve.	M1	A1	R	F	4A		16	305.52 ft				6,10
2005	Existing Distribution Improve.	M1	A1	R	F	4A		24	15.32 ft				6,10
2006	Existing Distribution Improve.	M1	A1	R	F	4A		36	37.92 ft				6,10
2007	Old Canton from Green Oak to Pearl River Church Ro	M1	A11	N	F	4A		16	11500 ft		$775,000.00	4/1/2010	2
2008	Old Canton & Twelve Oaks Rd	M1	A11	N	F	4A		12	9500 ft		$800,000.00	4/1/2010	2
3000	Water Meter Replacement	M8	A1	R	F	4A		0.75	4467 ft				6,10