From:	Valdez, Heather
To:	"Brian.English@deq.idaho.gov"
Cc:	Douglas.Tanner@deq.idaho.gov; Robert.Bullock@deq.idaho.gov
Subject:	RE: Pond 16S
Date:	Thursday, July 07, 2016 10:09:00 AM
Attachments:	image001.png image002.png image003.png image004.png image005.png image006.png

---

Thanks Brian, yes I agree.

Heather Valdez
Chemical Engineer, Project Manager
RCRA Corrective Actions, Permits and PCBs Unit
EPA Region 10
1200 6th Ave, Suite 900, AWT-150, Seattle WA, 98101
(206) 553-6220
valdez.heather@epa.gov

From: Brian.English@deq.idaho.gov [mailto:Brian.English@deq.idaho.gov]
Sent: Thursday, July 07, 2016 8:49 AM
To: Valdez, Heather <Valdez.Heather@epa.gov>
Cc: Douglas.Tanner@deq.idaho.gov; Robert.Bullock@deq.idaho.gov
Subject: Pond 16S

I suggest that in addition to adding the unit on the south perimeter pipe you tell FMC to add a second unit to the north perimeter pipe. The extracted volumes are quite low when compared to the volume under the cap and you want the PH3 numbers to go down. At the current extraction rates FMC could operate a second unit for at least a month without causing a GES unit to operate below capacity.