From: Brian.English@deq.idaho.gov
To: Valdez, Heather
Cc: Douglas.Tanner@deq.idaho.gov; Robert.Bullock@deq.idaho.gov
Subject: Pond 16S
Date: Thursday, July 07, 2016 8:49:34 AM
Attachments: removed.txt
BRIAN ENGLISH.vcf

I suggest that in addition to adding the unit on the south perimeter pipe you tell FMC to add a second unit to the north perimeter pipe. The extracted volumes are quite low when compared to the volume under the cap and you want the PH3 numbers to go down. At the current extraction rates FMC could operate a second unit for at least a month without causing a GES unit to operate below capacity.