From: Valdez, Heather
To: "Susan Hanson"; Kelly Wright
Subject: RE: UPRR work lines in front of FMC [WARNING: SPF validation failed]
Date: Friday, August 12, 2016 9:44:00 AM

Thanks Susan, I will raise this questions to them.

Heather Valdez
Chemical Engineer, Project Manager
RCRA Corrective Actions, Permits and PCBs Unit
EPA Region 10
1200 6th Ave, Suite 900, AWT-150, Seattle WA, 98101
(206) 553-6220
valdez.heather@epa.gov

-----Original Message-----
From: Susan Hanson [mailto:susanh@ida.net]
Sent: Friday, August 12, 2016 7:54 AM
To: Valdez, Heather <Valdez.Heather@epa.gov>; Kelly Wright <kwright@sbtribes.com>
Subject: UPRR work lines in front of FMC [WARNING: SPF validation failed]

Hi Heather,

I understand UPRR and their contractors recently replaced all the lines in front of FMC. I would like to check and ensure FMC properly trained and provided notice to all these workers concerning phosphine and other toxic gas emissions. Specifically, if monitors were provided, (do/did they need to? this may be something for future also) was notice was provided of potential gases and exposures and to ensure they did not communicate only folks in doors needed to have monitors or be concerned of toxic gas exposure.

Susan Hanson