PIPE OUTLETS FROM FMR ELECTRIC HOSE + RUBBER CO. INTO BRANDYWINE CREEK

ORIGINAL

SDMS DocID 2228480




FM
?
814-5394


1750
1575
1400
1225
1050
875
700
350
175
Original
Door
dripping
W1
collapse beneath
clogged
piped
drip some sed.
trails
numerous under shed
hollow by dirt
by floating dock
running from inside of flapper valve open
SED
low
low
Low seepage sediment
tide gate
bottom shear roofing material?
PFE ORIGINAL

SKETCH MAP BASED ON AERIAL PHOTO
ELECTRIC HOSE + RUBBER



Photo date
4/7/50

Towle
12/21/01

PFE ORIGINAL

SKETCH MAP BASED ON AERIAL PHOTO
ELECTRICAL HOSE + RUBBER

ORIGINAL



PHOTO DATE
8/14/54

TOWLE
12/21/00

PFE ORIGINAL

SKETCH MAP BASED ON ACTUAL PHOTO
ELECTRIC HOSE + RUBBER

ORIGINAL



PHOTO DATE
3/23/59

Toule
12/20/80

PFE ORIGINAL

SKETCH MAP BASED ON AERIAL PHOTO
ELECTRIC HOSE & RUBBER

ORIGINAL



PHOTO DATE

5/15/77

Towle
12/

ORIGINAL

12th STREET LANDFILL/DUMP SITE
SKETCH MAP OF APPROXIMATE LOCATION OF DISTURBED GROUND VISIBLE ON 4/7/50 AERIAL PHOTO
M. Towle