pg 1

Shaffer Equipment Co.
Facts + Statistics Sheet

prepared 5-7-85
[redacted]

SEMS DocID 2261279

1. Red Dog 3640 tons backfilled

	loads	tons
a) water line	12	96
b) Behind Property	165	1320
c) Shaffer Property	24	192
d) Shaffer Driveway	254	2030
	455	3640

2. Stone

	tons
a) water line	289
b) Sediment runoff	44
c) Driveway	290
	633 — tons

ORIGINAL (Red)

3. Water Treated

Date Discharged	Quantity
3/5	33,750
3/7	27,450
3/11	37,750
3/16	57,375
3/22	48,825
	205,150 gallons

4- Quantity of Soil

131' x 45' x 20 → 117,900 ÷ 27 = 4366 cu yds

Conv. w Bob Maynor
1-22-85 Garrett
Relayed to Caron
0930

Thurs. aft (b) (4) [redacted]
Fayette Tribune also → [redacted]

name of paper = Beckley Post Herald [redacted]
date Sat 19th, 1985
Author. Sara Crickenberger
Phone # of paper 255-4400
Person in article (People's Justice committee) (b) (4) [redacted] Treasurer

100 days passed since authorities have known.
88 before phase 9 can begin.
½ year passed to deadly contamination
Demand immediate
Synanyon Times Beach of WV

(b) (4) [redacted] from Phone Book.

ORIGINAL (Red)

WESTON
DESIGNERS CONSULTANTS

BY _____ DATE 12/27/84 DIV _____ SHEET _____ OF _____
CHKD BY _____ DATE _____ DEPT _____ W.O. NO. _____
PROJECT _____
SUBJECT _____

1. Staging of capacitors - transformers / palletize / plastic
2. Fencing + signs
3. Inventory - name plates, drums, etc.
4. Run-off diversions - containment → sedimentation pond
5. Hot spots - soils
6. Site security - equipment / materials.
7. Excavations minor.

Jan 3rd Inventory

8. Analytical Support.

9. Measuring + Sampling Plan.
   1. extent of contamination
   2. on creek
   3. filtered H_2O samples - (Stream) up/down / at site.

10. Ponded run-off w/ overflow mechanism trapping oil + PCBs -

1. Non financially viable responsible party maybe → No recovery actions.

Dibenzyl furan / Dioxin =

ORIGINAL

RFW 338-5-81

WESTON
DESIGNERS CONSULTANTS

BY _____ DATE 12/27/84 DIV _____ SHEET _____ OF _____

CHKD BY _____ DATE _____ DEPT _____ W.O. NO. _____

PROJECT _____

SUBJECT _____

Wed. Jan 2, 85 Mobilize ERCS command post.
Rubber Track Backhoe

ORIGINAL
(Red)

RFW 338-5-81

WESTON
DESIGNERS CONSULTANTS

BY _____ DATE _____ DIV _____ SHEET _____ OF _____
CHKD BY _____ DATE _____ DEPT _____ W.O. NO. _____
PROJECT _____
SUBJECT _____



RFW 338-5-81