Site: SANGAMO
Break: 13.1 v.2
Other:

Public Mtg Scope - RI

On Site Landfill
761.75
Monitoring wells historically dry
Should satisfy groundwater monitoring requirements
Is permitted TSCA facility
There is an available groundwater interface
which can be reached - Wells just not deep enough

Unsaturated zone monitoring?

SW evaluating whether wells will put in
Asks for justification that landfill is TSCA
landfill

Name of site
SW name attached to municipal landfill
Strong impression as to scope of RI

* Will list separate name
* SW will present a proposal

Check comments to see how SW commented
at name of site.

10726898