REDACTED VERSION

ecology and environment, inc.

International Specialists in the Environment

Job Number KJ6103

WEST BANK ASBESTOS
REMOVAL ASSESSMENT
JEFFERSON PARISH, LOUISIANA
TDD # S06-9607-0012
PAN # 017301SFXX
LOGBOOK 29 of

90055112

E & E Job Number KJ6103

Telephone Code Number

Site Name Westbank Asbestos

City/State Jefferson, Orleans, Plaquemines Parishes, LA

TDD S06-96-07-0012

PAN 017301SFXV

SSID

Start / Finish Date 09/5/98 / 1/6/99

Book 29 of

7/26/99

E & E Emergency Response Center: (716) 684-8940
E & E Corporate Center: (716) 684-8060
MEDTOX Hotline: (501) 370-8263
E & E Safety Director (Home): (716) 655-1260

9/15/98 SOG-9607-0012

0800 START JEFF WRIGHT, KOEBY JOHNSON & TINA STANSEL ARRIVE AT COMMAND POST.

0810 START CONDUCTS DAILY SITE SAFETY MEETING SEE SITE SAFETY FORM. CLEAR HIGH IN MID 80'S

0830 STARTS T. STANSEL & K. JOHNSON IN FIELD TO CONDUCT UNDER HOUSE SURVEY.

0905 J. WRIGHT INPUTTING DATA.

1150 STARTS ON LUNCH BREAK.

1300 FIELD SURVEY CONTINUES.

1655 STARTS OFF SITE FOR THE DAY.

SOL-9607-0012 9/16/98

0755 STARTS JEFF WRIGHT, KOEBY JOHNSON & TINA STANSEL ARRIVE AT COMMAND POST.

0820 START CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER PARTLY CLOUDY 76°F.

0835 T. STANSEL & K. JOHNSON IN FIELD TO CONDUCT ~~DAILY~~ JIN 9/16/98 UNDER HOUSE SURVEY.

0845 J. WRIGHT INPUTING DATA & COORDINATING FILES.

1000 FIELD WORK CONTINUES

1200 STARTS ON LUNCH BREAK

1245 FIELD WORK CONTINUES

1705 STARTS OFF SITE FOR THE DAY.

9/17/98 SOG-9607-0012

0750 STARTS JEFF WRIGHT, KOEBY JOHNSON & TINA STANSEL ARRIVE AT COMMAND POST.

0805 K. JOHNSON CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER CLEAR HIGH IN MID 80's

0815 STARTS T. STANSEL & K. JOHNSON IN FIELD TO CONTINUE UNDER HOUSE SURVEY.

0820 J. WRIGHT COORDINATING FILES & INPUTTING DATA.

1150 STARTS ON LUNCH BREAK

1245 START, RESUME FEILD WORK.

1630 STARTS BACK AT CP COMPLETING PAPERWORK.

1705 STARTS OFF SITE FOR THE DAY.

S06-9607-0012 9/18/98

0815 STARTS JEFF WRIGHT, KOBBY JOHNSON & TINA STANSEL ARRIVE AT CP.

0830 START K. JOHNSON CONDUCT DAILY SITE SAFETY MEETING. PARTLY CLOUDY 65°F FOR A HIGH.

0840 - CORRECTION - START T. STANSEL NOT ON SITE. SHE IS A MOTEL, SICK.

0845 J. WRIGHT & K. JOHNSON IN CP FILEING PAPERWORK AT INPUTING DATA.

1000 OFFICE WORK CONTINUES.

1200 START ON LUNCH BREAK AND WILL CHECK OUT OF MOTEL.

1315 START BACK AT CP, INCLUDING T. STANSEL.

1400 HEAVY RAIN CONTINUES. START DOING PAPERWORK IN CP.

1600 STARTS OFF SITE FOR THE DAY DUE TO BAD WEATHER.

9/21/98 S06-96-07-0012

0800 START Greg Day arrives at CP
0909 START Jody Shires, Reed Lyday, Tina Stansel, and Erin Warner arrive at CP. GRD
0915 SSM - see meeting form weather partly cloudy, humid, hot, temp 80° GRD
0930 Giving briefing to crews GRD
1000 Crews checking sites. GRD
1145 Lunch break. GRD
1245 Lunch break over, returning to work. Crews and Lyday and Stansel and Shires and Warner. START Day remains at CP.
1345 Work continues as above ~~as above~~ GRD 9/21/98
1445 Work continues as above ~~as~~ GRD 9/21/98
1545 Work continues as above GRD
1615 Lyday and Stansel return to CP
1625 Lyday & Stansel depart CP to completed GRD 9/21/98 Harvey GRD
1643 Shires and Warner return to CP GRD
1653 Lyday and Stansel return to CP GRD
1730 STARTS Depart CP GRD

Gregory R Day

9/22/98 SØ6-96-Ø7-ØØ12

Ø73Ø STARTS Greg Day, Reed Lyday, Tina Stansel, Erin Warner and Jody Shires arrive at CP.

Ø74Ø SSM see meeting form, weather warm partly cloudy temp 8Ø° expecting hi 9Ø's — GRD

Ø745 Teams depart CP to do survey work. Teams are Lyday and Stansel and Warner & Shires. Day in CP. Will finish Harvey, Gretna, Algiers & Terrytown today.

ØØØØ COE contractors Alan Townsend and Jody Yates arrive at CP to pick up supplies to do survey work.

Ø81Ø COE contractors depart CP. Will work in Marrero. Stansel & Lyday will work in Westwego after completing Harvey. — GRD

ØØØØ Work continues as above — GRD

Ø93Ø START Day and C.O.E Denzie White check site 726 and get signed access.

1ØØØ Return to CP — GRD

1Ø45 Teams return to CP. — GRD

1Ø5Ø Shires & Warner depart CP to check on a site

112Ø Shires + Warner return to CP — GRD

113Ø Lunch break — GRD

123Ø Lunch break completed, crews returning to the field, Day continues with CP work

133Ø Work continues as above — GRD

143Ø Work continues as above — GRD

153Ø Work continues as above — GRD

163Ø Crews return to CP — GRD

17ØØ All START except Day depart CP — GRD

1730 Day departs CP — GRD

Gregory R Day

9/23/98 S06-~~96~~ 96-07-0012

GRD 9/23/98

0725 START Greg Day at CP.

0744 START Reed Lyday arrives at CP

0749 STARTS Jody Shires, Tina Stansel, and Erin Warner arrive at CP ——— GRD

0800 SSM see meeting form weather, Clear sunny warm temp ~80°F. Todays crews — Warner + Stansel in Westwego, Lyday + Shires in Marrero. ——— GRD

0810 COE contractors from OMNI pick their forms — Jody Yates + Alan Townsend, they will also be in Marrero ——— GRD

0820 Crews depart CP ——— GRD

0900 Work continues as above ——— GRD

1000 Work continues as above ——— GRD

1100 Work continues as above ——— GRD

1145 Lunch break ——— GRD

1245 Lunch break completed ——— GRD

1300 Work continues as above ——— GRD

1400 Work continues as above ——— GRD

1500 Work continues as above ——— GRD

1600 COE contractors return to CP, 41 sites done.

1630 Shires and Lyday return to CP ——— GRD

1700 Warner and Stansel return to CP ——— GRD

1714 Warner, Stansel, and Lyday depart CP for the day.

1718 Shires departs CP ——— GRD

1800 Start Day departs CP

Gregory R Day

9/24/98 S06-96-07-0012

0730 START Greg Day arrives at CP
0740 START's Tim Stansel and Erin Warner arrive at CP
0747 COE contractors Alan Thompson and Joey Yates at CP. GRD
0750 Warner and Stansel depart CP. GRD
0754 START's Reed Lyday and Jody Shires arrive at CP
LATE ENTRY SSM - see meeting form weather clear warm humid temp ~80°F GRD
0800 Lyday & Shires depart CP to conduct inspections
0802 Thompson and Yates depart CP GRD
0900 Work continues as above. Day working in CP
1000 Work continues as above GRD
1100 Work continues as above GRD
1125 Shires & Lyday return to CP GRD
1145 Lunch break GRD
1245 Lunch break over GRD
1300 Work continues as above GRD
1400 Work continues as above GRD
1500 Work continues as above GRD
1600 Work continues as above GRD
1610 Yates & Thompson return to CP, all assigned sites completed
1630 Crews return to CP
1700 Stansel and Warner depart CP
1730 START depart CP

Gregory R Day

9/25/98 SØ6-96-Ø7-ØØ12

Ø73Ø START Greg Day arrives at CP
Ø745 START Jody Shires arrives at CP, the remaining START members are demobilizing this morning
Ø75Ø SSM - see meeting ~~9/25/98~~ form weather - clear sunny warm temp ~80°F
ØEØØ Filing survey forms ——— GPS
Ø9ØØ Depart CP to complete surveys
1ØØØ Work continues as above
11ØØ Return to CP ——— GPS
114Ø all forms filed ——— GPS
11Ø5 Depart CP for the day

Gregory Day

S06-9607-0012 9/30/98

0945 START JEFF WRIGHT ARRIVES AT WESTBANK COMMAND POST TO MEET WITH OSC JOHN MARTIN.

1010 J. WRIGHT COORDINATING FILES

1200 OSC JOHN MARTIN ON SITE.

1245 US COC DENNIS WHITE IS ON SITE.

1345 OSC MARTIN DISCUSSES FUTURE PLANS:

> COMFORT LETTERS TO BE SENT OUT (W/ SITE SKETCH & NOTICE TO PROCEED)

> REVIEW ALL SIT REPS.

> UNDER HOUSE SURVEY INFO

- FIELD SHEETS OF SITE W/ ACM
- PRINT OUT ADDRESS LIST OF SITES W/ ACM UNDER HOUSE.

> LABEL FILES FOR SCANNING.

1430 J. WRIGHT LOADING BOXES OF IT FILES, TO BE STORED IN BATON ROUGE.

1600 J. WRIGHT OFF SITE FOR THE DAY.

10/20/98 S06-9607-0012

1520 START JEFF WRIGHT ARRIVES AT COMMAND POST.
OSC JOHN MARTIN ALSO ON SITE. J. WRIGHT &
J. MARTIN WILL GO OVER SITE FILES AND
DISCUSS FUTURE PLANS.

1615 J. WRIGHT & J. MARTIN OFF SITE

S06-9607-0012 10/21/98

0740 START JEFF WRIGHT & JOHN MARTIN ARRIVE AT COMMAND POST.

0800 WILL WORK ON SITE FILES. INPUT DATA

1000 CET BRIAN SULLIVAN ON SITE.

1130 LUNCH BREAK.

1210 BACK AT CP. CET SULLIVAN OFF SITE

1215 COMMAND POST ACTIVITIES CONTINUE

1630 J. WRIGHT & J. MARTIN OFF SITE.

10/26/98 SØ6-96Ø7-ØØ12

1Ø1Ø START Greg Day arrives at CP, unable to find START Lead Lyday at New Orleans airport.

113Ø START Lyday called in, he was at airport, we just did not meet up, will take shuttle in from airport. — GRD

123Ø START Lyday arrives at CP — GRD

1233 COE Denzie White arrives at CP — GRD

124Ø SSM see meeting form weather warm, sunny, breezy temp 8Ø's — GRD

125Ø Lunch break — GRD

135Ø Lunch break completed

14ØØ Depart CP to begin marking sites

15ØØ Work continues — GRD

16ØØ Work continues — GRD

17ØØ Returned to CP — GRD

173Ø Depart CP for the day — GRD

Gregory R Day

10/22/98 SOC-9687-0812

0745 JEFF WRIGHT & JOHN MARTIN ARRIVE AT COMMAND POST.

0845 J. WRIGHT & J. MARTIN ENROUTE TO MEET WITH RESIDENT OF SITE 2021. WILL ALSO INVESTIGATE CLAIM OF BROKE FENCE ON (b) (6) [redacted]

1135 BACK AT COMMAND POST

10/27/98 SØ6-96-Ø7-ØØ12

Ø74Ø Starts Greg Day & Reed Lyday arrive at CP
Ø8ØØ SSM see meeting form - weather cool, sunny
temp ~62°F expecting 82°F.
Ø81Ø Depart CP to mark GRD
ØØØØ Work continues on ~~AC~~ GRD 10/27/98 ACM marking
1ØØØ Work continues on marking
~~1Ø3Ø~~ GRD 10/27/98 Return to CP GRD
11ØØ Lunch break. GRD
12ØØ Lunch break completed GRD
13ØØ Work continues as above
14ØØ ~~Work~~ GRD 10/27/98 Work continues as above
1449 Return to CP to work on files
153Ø Work continues as above
163Ø Depart CP for the day

Gregory R Day

10/28/98 S06-96-07-0012

0740 START Greg Day and Reed Lyday arrive at CP
0745 SSM - see meeting form. Weather cool, some fog, sunny temp ~62°F expecting low 80s
0806 Depart CP to continue marking & access
0900 Return to CP GRD
0915 Depart CP for meeting with property owner
0920 Met with property owner GRD
0930 Depart site for N.O. Airport to pick up OSC GRD
0955 arrive at N.O. Airport, cant locate OSC. COE Denzie White also at airport to pick up OSC GRD
1000 START leaves airport GRD
1040 Return to CP.
1100 Spoke with property owner's daughter about access. She will speak to her mother and call back later.
1125 Lunch break GRD
1225 Lunch break completed GRD
1245 OSC arrives at CP GRD
1300 Depart CP after briefing OSC about current standing on all things going on.
1400 Work continues on site marking & GRD 10/28/98
1500 work continues on site marking & getting reprints of some photos as requested by the OSC GRD
1600 Return to CP to complete paperwork.
1630 Depart CP for the day.

Gregory R Day

10/29/98 S06-96-07-0012

0740 STARTS Greg Day and Reed Lyday arrive at CP GRD

0750 SSM see meeting form weather cool Sunny temp ~ 65°F GRD

0805 Depart CP to mark site 2073

0900 Returned to CP GRD

0945 Homeowner of site 336 called to tell us/ask us about SCM and to grant access. Gave ~~us~~ GRD 10/29/98 us Tenant's name and phone #. GRD

0955 Depart CP to get access agreement signed

1005 Have access agreement

1015 At site 336, driveway contains ACM, unable to do inside fence due to Rottweilers

1100 Returned to CP, called tenant at site 336 left message on answering machine about checking inside fence of property and putting up her dog. Told her we would be around until ~1300

1110 Lunch break

1140 Lunch break completed, START Lyday getting ill with stomach problem

1230 Depart CP for the day, START Lyday is sick, taking him to ND. Airport to fly home

Gregory R Day

S06-96-07-0012 11/9/98 ~~11/10/98~~ JW

1415 START JEFF WRIGHT ARRIVES AT WESTBANK COMMAND POST. AREA IS LOCKED UP AND NO ONE HAS KEYS. START KOEBY JOHNSON AND OSC JOHN MARTIN IS ON SITE. START & OSC WILL GO BACK TO MOTEL CHECK IN AND TRY TO OBTAIN KEYS.

JW

11/10/98

0700 STARTS JEFF WRIGHT AND KOEBY JOHNSON ARRIVE AT COMMAND POST. OSC JOHN MARTIN AND CET DAVID BURNS ARE ON SITE.

0805 IT-OHM TONY ROBERTS + TOM MATHISON ARE ON SITE.

0835 US COE DERIE WHITE ARRIVES ON SITE AND UNLOCK COMMAND POST.

0845 STARTS OFFLOADING SITE FILES FROM TRUCK INTO COMMAND POST.

0000 START KJ/JW out to complete Phase II sketches.

1200 STARTS out to lunch

1300 STARTS return from lunch.

1330 Jeff W. out to Baton Rouge to gather supplies.
KJ. phones residents for restoration approval.

1700 START Jonson off site.

S06-96-07-0012 11/11/98

0645 START JEFF WRIGHT DEPARTS ~~[illegible]~~ 9W MOTEL FOR WESTBANK COMMAND POST.

0700 STARTS J. WRIGHT & KOEBY JOHNSON ARRIVE AT COMMAND POST. OSC JOHN MARTIN IS ON SITE. CET DAVID BURNS IS ALSO ON SITE. OHM-IT TOM MATHISON IS ALSO ON SITE. REMOVAL CREWS ARE SCHEDULED TO BEGIN WORK TODAY.

0710 START KOEBY JOHNSON HAS CONDUCTED DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER CLEAR COOL, HIGH IN 70s.

0830 STARTS JOHNSON & WRIGHT @ KINKOS TO MAKE COPIES OF SITE FILE. COMMAND POST COPIER HAS NOT ARRIVED. OSC MARTIN INFORMED START TO PURCHASE 8mm VIDEO TAPES FOR PRE & POST REMOVAL VIDEO DOCUMENTATION.

0900 STARTS AT SITE #2020 CONDUCTING PRE-REMOVAL VIDEO DOCUMENTATION.

0915 STARTS AT SITE #1171 CONDUCTING PRE-REMOVAL VIDEO DOCUMENTATION.

0920 START PAUL LUGAUER HAS ARRIVED AT COMMAND POST

1000 STARTS WRIGHT, LUGAUER & JOHNSON AT SITE #553 TO CONDUCT VIDEO DOC.

1030 STARTS AT SITE #1853 TO CONDUCT VIDEO DOC.

1037 NO PRE-REMOVAL VIDEO DOC WAS CONDUCTED DUE TO SMALL AMOUNT OF ACM (SMALL LOOSE PIECE - NO DIGGING OR RESTORATION REQUIRED).

1100 VIDEO CAMERA BATTERIES ARE NOT KEEPING A GOOD CHARGE. OSC MARTIN HAS REQUESTED THAT START PURCHASE ~~AT~~ 11/11/98 9W A CAM. RECORDER BATTERY.

Jeff Wright

11/11/98 S06-96-07-0012

1200 STARTS ON LUNCH BREAK

1250 STARTS OFF LUNCH BREAK.

1300 START TO CONDUCT POST REMOVAL VIDEO DOCUMENTATION.

1320 STARTS AT SITE 553 TO COLLECT SAMPLES.

1415 STARTS NOW CONDUCTING VIDEO DOC AT SITES 1921 + 1922

1500 STARTS CONDUCTING VIDEO DOC AT SITE #1879.

1600 STARTS BACK AT CP TO COMPLETE PAPER-WORK.

1700 STARTS JOHNSON + LUCATHER DEPART CP FOR HOTEL.

1715 START WRIGHT CONTINUES TO COORDINATE FILES.

1735 START WRIGHT DROPPING OFF BLANK ACCESS FORM AT SITE #1914 FOR OWNER TO REVIEW.

1750 START WRIGHT BACK AT MOTEL.

SO6-96-07-0012 11/12/98

0655 START JEFF WRIGHT, KOEBY JOHNSON, + PAUL LUGAUER ARE ON SITE. OSC JOHN MARTIN, USCOE TOM MATHISON, CET DAVID BURNS, + REMOVAL CREWS ARE ON SITE.

0710 START KOEBY JOHNSON HAS CONDUCTED DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER CLEAR + COOL TEMP IN MID 60'S.

0730 STARTS PREPARING FOR TODAYS ACTIVITIES.

0805 STARTS JOHNSON + LUGAUER IN FIELD TO CONDUCT PRE + POST VIDEO DOCUMENTATION AS WELL AS CONDUCTING POST REMOVAL SOIL SAMPLING.

0845 J. WRIGHT CALLING RESIDENTS FOR REMOVAL/RESTORATION NOTIFICATION AND COORDINATING SITE FILES.

0900 FIELD ACTIVITIES CONTINUE.

1200 START ON LUNCH BREAK

1300 STARTS OFF LUNCH BREAK.

1315 STARTS JOHNSON + LUGAUER RESUME FIELD ACTIVITIES (VIDEO DOCUMENTATION + SOIL SAMPLING)

1330 J. WRIGHT CONTINUES COMMAND POST ACTIVITIES.

1540 FIELD + CP DUTIES CONTINUE.

1700 STARTS OFF SITE FOR THE DAY.

11/13/98 506-9607-0012

0710 START: JEFF WRIGHT, KOEBY JOHNSON AND PAUL LUGAUER ARE ON SITE. OSC JOHN MARTIN ALSO ON SITE. CET DAVID BURNS IS ON SITE AND ONM-IT TOM MATHISON & TONY ROBERTS ARE ON SITE. USCOE DENNIE WHITE IS ALSO ON SITE.

0712 START KOEBY JOHNSON HAS CONDUCTED DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER CLEAR ≈ 60°F. HIGH TODAY IN MID 70s.

0730 START: JOHNSON & LUGAUER ARE IN FIELD CONDUCTING PRE & POST VIDEO DOCUMENTATION.

0745 J. WRIGHT WORKING IN COMMAND POST.

0900 FIELD ACTIVIES & COMMAND POST DUTIES CONTINUE.

1015 OSC J. MARTIN HAS REQUESTED THAT START COLLECT ONE SET OF AIR SAMPLES NEXT WEEK.

1150 START: BACK AT CP.

1215 START: ON LUNCH BREAK.

1300 START: OFF LUNCH BREAK.

1315 SAMPLE TEAM (JOHNSON & LUGAUER) RESUMES VIDEO DOCUMENTATION, SITE SKETCHING & SOIL SAMPLING.

1530 FIELD ACTIVITIES CONTINUE.

1700 START OFF SITE FOR THE DAY.

506-9607-0012 11/14/98

0650 STARTS JEFF WRIGHT, PAUL LUGAUER AND KOEBY JOHNSON ARE ONSITE. CET DAVID BURNS IS ON SITE AND IT-OMA TOM MATHISON AND PAT MOO ARE ON SITE.

0655 START JOHNSON CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER PARTLY CLOUDY 65°F.

0710 STARTS JOHNSON AND LUGAUER IN FIELD TO CONDUCT VIDEO DOCUMENTATION (PRE & POST REMOVAL) AND COLLECT SOIL SAMPLES.

0830 FIELD WORK & COMMAND POST WORK CONTINUES.

11/16/98 S06-9607-0012

0700 STARTS JEFF WRIGHT, KOEBY JOHNSON & PAUL LUGAUER ARE ON SITE. CET DAVID BURNS IS ON SITE. OHM-IT TOM MATHISON IS ON SITE.

START KOEBY JOHNSON HAS CONDUCTED DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER CLOUDY 69°F.

STARTS JOHNSON & LUGAUER IN FIELD TO CONDUCT VIDEO DOCUMENTATION AND SAMPLE COLLECTION.

0735 J. WRIGHT CALLING RESIDENTS ABOUT RESTORATION ALSO LABELING & COORDINATING FILES.

1000 FIELD ACTIVITIES CONTINUE.

1200 STARTS ON LUNCH BREAK.

1250 STARTS BACK AT CP.

1310 STARTS JOHNSON & LUGAUER WILL LABEL FILES WITH TRACKING NUMBERS (EACH DOCUMENT IN FILE).

1500 FIELD LABELING CONTINUES.

1705 STARTS OFF SITE FOR THE DAY

506-9607-0012 11/17/98

0655 STARTS JEFF WRIGHT, PAUL LUGAMER AND KOEBY JOHNSON ARRIVE AT CP. OHM-IT TONY ROBERTS AND TOM MATHISON ARE ALSO ON SITE, CET DAVID BURNS IS ON SITE.

START CONDUCTS DAILY SITE SAFETY MEETING SEE SITE SAFETY FORM.

TODAY STARTS WILL CONDUCT VIDEO DOCUMENTATION OF PRE REMOVAL ACTIVITIES (STARTS JOHNSON & LUGAMER). STARTS WILL ALSO CONTINUE TO LABEL ALL DOCUMENTS IN INDIVIDUAL SITE FILES.

0750 STARTS LUGAMER & JOHNSON ARE LABELING FILES. J. WRIGHT PRINTING LABELS.

0915 FILE LABELING CONTINUES.

1115 STARTS ON LUNCH BREAK.

1150 STARTS OFF LUNCH BREAK, CONTINUE FILE LABELING.

1315 STARTS JOHNSON & LUGAMER IN FIELD TO CONDUCT VIDEO DOCUMENTATION & COLLECT CONFIRMATION SOIL SAMPLES.

1500 J. WRIGHT CONTINUES FILE COORDINATION AND LABELING

1600 STARTS OFF SITE FOR THE DAY.

11/18/98 506-9607:0012

0702 STARTS JEFF WRIGHT, PAUL LUGAUER & KOEDY JOHNSON ARRIVES AT COMMAND POST. OHM-IT TONY ROBERTS & TOM MATHISON ARE ON SITE. CET DAVID BURNS & USCOE DENEIE WHITE IS ON SITE. START KOEDY JOHNSON CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM.

0800 START MEMBERS WILL WORK ON LABELING ALL DOCUMENTS IN SITE FILES.

0930 FILE LABELING CONTINUES.

1200 STARTS ON LUNCH BREAK.

1250 STARTS BACK AT CP.

1305 FILE LADELING RESUMES.

1505 FILE LADELING CONTINUES.

1700 STARTS OFF SITE FOR THE DAY

S06-9607-0012 11/19/98

0700 STARTS JEFF WRIGHT, KOEBY JOHNSON AND PAUL LUGANER ARRIVES AT CP. OHM-IT TONY ROBERTS & TOM MATHISON ALSO ON SITE. USCOE DENNIS WHITE ON SITE TODAY.
START WRIGHT CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM.

0730 START MEMBERS WILL CONTINUE TO LABEL ALL 11/16/98 SITE FILE DOCUMENTS

1000 FILE LABELING CONTINUE.

1130 STARTS ON LUNCH BREAK.

1215 STARTS OFF LUNCH BREAK, RESUME FILE LABELING.

1400 STARTS JOHNSON + LUGANER INSPECTING SITES.

1600 STARTS JOHNSON + LUGANER OFF SITE FOR THE DAY.

1630 J. WRIGHT OFF SITE FOR THE DAY.

11/20/98 SØL-9607-ØØ12

0655 STARTS JEFF WRIGHT, PAUL LUGAUER AND KOEBY JOHNSON ARE AT COMMAND POST. OHM-IT TOM MATHISON & TONY ROBERTS ARE ON SITE. CET DAVID BURN IS ON SITE. START CONDUCTS DAILY SITE SAFETY MEETING SEE SITE SAFETY FORM. STARTS JOHNSON AND LUGAUER WILL LABEL FILE DOCUMENTS AND CONDUCT VISUAL INSPECTIONS AND COLLECT CONFIRMATION SOIL SAMPLES.

0745 STARTS JOHNSON & LUGAUER LABELING SITE DOCUMENTS. J. WRIGHT PRINTING LABELS AND COORDINATING FILES.

1000 COMMAND POST WORK CONTINUES.

1045 STARTS JOHNSON & LUGAUER IN FIELD TO CONDUCT VISUAL INSPECTIONS AND COLLECT CONFIRMATION SOIL SAMPLES.

1150 STARTS ON LUNCH BREAK

1245 STARTS OFF LUNCH BREAK

1310 STARTS JOHNSON & LUGAUER BACK IN FEILD TO CONDUCT VISUAL INSPECTIONS

1420 J. WRIGHT COORDINATING FILES AND CALLING OWNER ABOUT RESTORATION NOTIFICATIONS.

1530 STARTS RESUME LABELING FILES.

1615 STARTS OFF SITE FOR THE DAY.

506-9607-0012 11/21/98

0658 STARTS JEFF WRIGHT AND PAUL LUGAUER ON SITE. OHM-IT TONY ROBERTS & TOM MATHISON ARE ON SITE. CET DAVID BURNS IS ON SITE.
START CONDUCTS DAILY SITE SAFETY MEETING SEE SITE SAFETY FORM. WEATHER CLOUDY 68°F. START JOHNSON IS NOT ON SITE TODAY. HIS IS SICK.

0750 STARTS ARE LABELING SITE FILES.

1000 STARTS CONTINUE TO LABEL SITE FILES. REMOVAL WORK HAS BEEN CANCELED DUE TO RAIN.

1030 CET DAVID BURNS IS OFF SITE FOR THE DAY.

1115 STARTS NOW CONDUCTING POST-RESTORATION VIDEO DOCUMENTATION. OHM-IT PERSONNEL OFF SITE FOR THE DAY.

1220 STARTS CONTINUE VIDEO DOCUMENTATION.

1400 STARTS BACK AT CP TO LABEL FILES.

1500 STARTS OFF SITE FOR THE DAY.

11/23/98 SOG-9607-0012

0658 START: JEFF WRIGHT, KOEBY JOHNSON AND PAUL LUGANER ARRIVE AT COMMAND POST. CET DAVID BURNS IS ON SITE OHM-IT TONY ROBERTS AND TOM MATHISON ARE ON SITE.

0700 START JOHNSON CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER PARTLY CLOUDY 72°F

0720 STARTS JOHNSON & LUGANER LABELING DOCUMENTS IN SITE FILES. J. WRIGHT PRINTING LABELS AND COORDINATING FILES.

0915 STARTS CONTINUE TO LABEL FILES.

1030 STARTS JOHNSON & LUGANER IN FIELD TO CONDUCT PRE-REMOVAL VIDEO DOCUMENTATION

1150 STARTS ON LUNCH BREAK

1255 STARTS OFF LUNCH BREAK

1315 STARTS RESUME FILE LABELING.

1500 STARTS IN FIELD TO CONDUCT VISUAL INSPECTION AND COLLECT CONFIRMATION SOIL SAMPLES.

1615 START BACK AT COMMAND POST TO COMPLETE PAPERWORK.

1700 STARTS OFF SITE FOR THE DAY.

S06-9607-8812 11/24/98

0700 STARTS JEFF WRIGHT, PAUL LUGAUER AND KOEBY JOHNSON ARE ON SITE. CET DAVID BURNS IS ON SITE. OHA-IT TOM MATHISON AND TONY ROBERTS ARE ON SITE.

0715 START JOHNSON CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER PARTLY CLOUDY HIGH NEAR 75°F.

0730 START: JOHNSON & LUGAUER IN FIELD TO CONDUCT POST REMOVAL VIDEO DOCUMENTATION.

1000 STARTS BACK AT COMMAND POST TO WORK ON LABELING SITE FILES.

1100 STARTS AT SITE # 1816 TO COLLECT SOIL SAMPLE.

1145 STARTS ON LUNCH BREAK

1300 STARTS BACK AT CP TO WORK ON FILE LABELING.

1400 STARTS IN FIELD TO SAMPLE SITE # 1914

1500 STARTS BACK AT CP TO COMPLETE PAPERWORK AND UNPACK SAMPLE VEHICLE

1600 START MEMBERS OFF SITE FOR THE DAY.

11/30/98 506-9607-0012

0930 START JEFF WRIGHT ARRIVE ON SITE. CET DAVID BURNS IS ON SITE. ONE REMOVAL CREW IS IN FIELD WORKING ON SITE # 528. RESTORATION CREW IS ALSO ON SITE.

1000 J. WRIGHT PRINTING LABELS FOR FILE INDEXING.

1130 J. WRIGHT CONTINUES TO PRINT LABELS FOR INDEXING.

1230 START JODY SHIRES ARRIVES AT COMMAND POST. HE WILL HELP LABEL FILES FOR INDEXING AND HELP WITH SAMPLING AND VIDEO DOCUMENTATION.

1245 STARTS WRIGHT & SHIRES ENROUTE TO ENTERPRISE TO PICK UP RENTAL VEHICLE. START WRIGHT WAS GOING TO RENT VEHICLE IN BATON ROUGE BUT NONE WERE AVAILABLE AT CORP. RATE. START SHIRES WILL RENT VEHICLE IN NEW ORLEANS.

1330 STARTS ON LUNCH BREAK.

1440 STARTS OFF LUNCH BREAK AND BACK AT CP. J. SHIRES WILL WORK ON LABELING FILES FOR INDEXING.

1500 J. WRIGHT IN FIELD CONDUCTING POST-RESTORATION VIDEO DOCUMENTATION.

1605 J. WRIGHT BACK AT CP. J. SHIRES CONTINUES TO LABEL FILES.

1700 STARTS OFF SITE TO CHECK INTO HOTEL.

S06-9607-0012 12/1/98

0700 STARTS JEFF WRIGHT AND JODY SHIRES ARRIVE AT ~~SHI~~ MILE 416 COMMAND POST. CET DAVID BURNS IS ON SITE. US CORP OF ENGINEERS DENZIE WHITE IS ON SITE. IT-OHM TONY ROBERTS IS ON SITE.

0710 START WRIGHT CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM

0730 START SHIRES LABELING FILES FOR INDEXING AND J. WRIGHT IS PRINTING LABELS.

0945 STARTS CONTINUES TO LABEL FILES.

1100 STARTS CONTINUE TO LABEL FILES.

1210 STARTS ON LUNCH BREAK.

1305 STARTS BACK AT COMMAND POST.

1320 STARTS WRIGHT AND SHIRES ARRIVE AT SITE #528 TO CONDUCT VISUAL INSPECTIONS AND COLLECT CONFIRMATION SOIL SAMPLES.

1410 STARTS BACK AT CP AFTER COLLECTING. 4 SAMPLES AT SITE #528. NOW COMPLETING PAPERWORK.

1445 STARTS IN FIELD TO CONDUCT INTIAL INSPECTIONS.

1605 STARTS BACK AT CP. RESUME FILE LABELING.

1705 STARTS DEPART SITE FOR THE DAY.

12/2/98 506-9607-0012

0702 STARTS JEFF WRIGHT AND JODY SHIRES ARRIVE AT SITE. USCOE DENZIE WHITE. 12/2/98 JCW ~~AND~~ CET DAVID BURNS IS ON SITE. EPA OSC JOHN MARTIN IS ON SITE AND IT OHM TONY ROBERTS IS ON SITE. START WRIGHT CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM.

0720 START SHIRES LABELING FILES FOR INDEXING.

0930 STARTS CONTINUE LABELING FILES.

1140 STARTS NOW AT SITE #528 TO COLLECT SAMPLES. SEE REMOVAL LOGBOOK.

1230 STARTS ON LUNCH BREAK.

1335 STARTS BACK AT CP.

1410 STARTS BACK AT SITE #528 TO COMPLETE SAMPLING. SEE REMOVAL LOGBOOK.

1445 STARTS BACK AT CP TO COMPLETE SAMPLE PAPER WORK.

1530 STARTS RESUME LABELING FILES.

1730 STARTS OFF SITE FOR THE DAY.

Jeff Wright

S06-9607-0012 12/3/98

0700 STARTS JEFF WRIGHT AND JODY SHIRES ARRIVES AT WESTBANK COMMAND POST. OSC JOHN MARTIN AND CET DAVID BURNS IS ON SITE.

0710 START WRIGHT CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER FOGGY, CLOUDY. STARTS ~~WITH~~ 12/3/98 GW WILL CONTINUE TO LABEL FILES FOR INDEXING. STARTS WILL ALSO CONDUCT VIDEO DOCUMENTATION, VISUAL INSPECTIONS & COLLECT CONFIRMATION SOIL SAMPLES.

0720 STARTS WORKING ON LABELING FILES FOR INDEXING.

1000 STARTS CONTINUE TO LABEL FILES.

1210 STARTS ON LUNCH BREAK.

1305 STARTS BACK AT CP. RESUME FILE LABELING.

1500 FILE LABELING CONTINUES.

1705 STARTS OFF SITE FOR THE DAY.

12/4/98

0700 STARTS. JEFF WRIGHT AND JODY SHIRES ARRIVE AT WESTBANK COMMAND POST. OSC JOHN MARTIN, CET DAVID BURNS, USCOE DENZIE WHITE, OHM-IT TOM MATHISON AND TONY ROBERTS ARE ON SITE.

0705 START WRIGHT CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER CLEAR 67°F.

0730 STARTS WORKING ON LABELING FILES FOR INDEXING.

0900 STARTS CONTINUE TO LABEL FILES. STARTS ARRIVE AT SITE # 336 TO CONDUCT VISUAL INSPECTION, VIDEO DOCUMENTATION AND COLLECT CONFIRMATION SOIL SAMPLES. SEE REMOVAL SUPPORT LOGBOOK.

1120 STARTS BACK AT CP.

1140 OSC JOHN MARTIN OFF SITE TO N.O. AIRPORT TO CATCH FLIGHT TO DALLAS. WILL RETURN NEXT WEEK.

1215 STARTS ON LUNCH BREAK

1315 STARTS BACK AT CP

1330 START SHIRES IN FIELD TO DOUBLE CHECK SITE # FOR POSSIBLE ACM UNDER HOUSE PER OWNERS REQUEST.

1400 START SHIRES BACK AT CP. NO ACM FOUND UNDER STRUCTURE.

1430 START AT SITE # 1550 TO COLLECT SAMPLE AND CONDUCT VIDEO DOCUMENTATION. SEE REMOVAL SUPPORT LOGBOOK.

1555 STARTS BACK AT CP COMPLETING PAPERWORK. WILL ALSO WORK ON LABELING FILES.

1700 STARTS OFF SITE FOR THE DAY.

JW

12/5/98

0700 STARTS JEFF WRIGHT AND JODY SHIRES ARRIVE ON SITE. IT-OHM TOM MATHISON AND TONY ROBERTS ARE ON SITE. CET DAVID BURNS IS ON SITE AND USCGE DENZIL WHITE IS ON SITE.

START WRIGHT CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER FOGGY HIGH IN MID TO HIGH 70S.

0730 STARTS LABELING FILES FOR INDEXING.

1000 STARTS CONTINUE TO LABEL FILES.

1115 STARTS AT SITE 2023 TO COLLECT CONFIRMATION SOIL SAMPLES. SEE REMOVAL SUPPORT LOGBOOK.

1215 STARTS ON LUNCH BREAK.

1250 STARTS BACK AT CP. RESUME FILE LABELING

1320 START SHIRES ENROUTE TO SITE # 2023 TO CONDUCT POST REMOVAL VIDEO DOCUMENTATION.

1420 STARTS OFF SITE FOR THE DAY.

12/7/98 SOG-9607-012

0930 START JEFF WRIGHT AT E&E WAREHOUSE TO PICK UP SAMPLE JARS AND KLEEN GUARD SUITS.

1000 START WRIGHT ENROUTE TO WESTBANK ASBESTOS COMMAND POST.

1130 START WRIGHT AT COMMAND POST. OHM IT PERSONNEL ON SITE. USCOE DENZIE WHITE IS ON SITE. CET DAVID BURNS IS ON SITE

1145 J. WRIGHT CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER PARTLY CLOUDY 77°F. START WILL CONTINUE TO LABEL FILES FOR INDEXING. START WILL ALSO COLLECT CONFIRMATION SOIL SAMPLES AND VIDEO DOCUMENT SITE WHEN NECESSARY.

~~1145~~ 1155 DW 12/7/98 START WRIGHT CHECKING IN TO MOTEL.

1215 START ON LUNCH BREAK

1250 START BACK AT CP.

1335 START WRIGHT NOW AT SITE #2024 TO COLLECT CONFIRMATION SOIL SAMPLES. SEE REMOVAL SUPPORT LOGBOOK.

1635 START BACK AT CP.

1700 START OFFSITE FOR THE DAY. LATE ENTRY - START KOEBY JOHNSON CALLED AND STATED THAT HE WILL NOT COME TO WESTBANK DUE TO ILLNESS.

Jeff Wright

506-9607-012 12/8/98

0705 START JEFF WRIGHT ARRIVES AT COMMAND POST CET DAVID BURNS IS ON SITE. OHM IT TOM MATHISON AND TONY ROBERTS ARE ON SITE BUT IN THE FIELD. USCOE DENZIE WHITE IS ALSO IN THE FEILD.

0715 START WRIGHT CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER MOSTLY SUNNY TO PARTLY CLOUDY, HUMID 78°F.

0730 START WRIGHT IN FIELD TO CHECK ON PROGRESS OF SITES 1963 AND 1895.

1000 START WRIGHT BACK AT CP PACKAGEING SAMPLES FOR SHIPMENT

1150 START WRIGHT ON LUNCH BREAK.

1225 START OFF LUNCH BREAK BACK AT CP, PREPARING SAMPLE EQUIPMENT.

1315 START AT SITE # 1895 TO COLLECT POST EXCAVATION SAMPLES. SEE REMOVAL ASSESSMENT LOGBOOK.

1550 START WRIGHT BACK AT CP TO COMPLETE PAPERWORK

1700 START WRIGHT OFF SITE FOR THE DAY.

12/9/98

0655 START JEFF WRIGHT ARRIVE AT WESTBANK COMMAND POST. CET (ERRS) DAVID BURNS IS ON SITE. USCOE DENNIS WHITE AND OHM IT TONY ROBERTS AND TOM MATHISON ARE ON SITE BUT IN THE FIELD.

0705 START WRIGHT CONDUCTS DAILY SITE SAFETY MEETING SEE SITE SAFETY FORM. WEATHER MOSTLY SUNNY 63°F.

0730 START WRIGHT IN FIELD TO CHECK ON SITES 1963 AND 1879.

1000 START BACK AT COMMAND POST TO WORK ON LABELING FILES, SITREP ETC. SITE 1963 IS NOT COMPLETED. REMOVAL CREW WILL RETURN AFTER COMPLETING SITE 1879.

1200 START ON LUNCH BREAK.

1250 START OFF LUNCH BREAK AND BACK AT SITE 1879 TO COLLECT CONFIRMATION SOIL SAMPLE.

1300 START WRIGHT ENTERS EXCLUSION ZONE TO COLLECT ONE SOIL SAMPLE. START IN LEVEL C.

1320 START OUT OF EZ.

1445 START BACK AT CP. WORKING ON FILE LABELING.

1600 START BACK AT SITE 1879 TO COLLECT FINAL TWO SOIL SAMPLES. SEE REMOVAL SUPPORT LOGBOOK.

1650 START BACK AT CP TO COMPLETE PAPERWORK.

1700 START OFF SITE FOR THE DAY.

JJW

12/10/98

0700 START JEFF WRIGHT ARRIVES ON SITE. OSC JOHN MARTIN AND CET (ERRS) DAVID BURNS IS ALSO ON SITE. USCOE DENZIC WHITE AND OHA IT TOM MATHISON AND TONY ROBERTS ARE IN THE FIELD

0708 START WRIGHT CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER 63°F. PARTLY CLOUDY.

0715 START WRIGHT COORDINATING FILES AND SITE DOCUMENTS OF SITES THAT HAVE BEEN WORKED ON SINCE NOVEMBER 9, 1998.

1000 START CONTINUES TO COORDINATE SITE FILES.

1200 START ON LUNCH BREAK.

1250 START BACK AT CP.

1330 START AT SITE #1708 INSPECTING REMOVAL PROGRESS.

1400 START BACK AT CP WORK ON FILES.

1505 START WRIGHT AT SITE # 1708 TO COLLECT CONFIRMATION SOIL SAMPLES.

1515 START WRIGHT ENTER EXCLUSION ZONE TO COLLECT SOIL SAMPLES.

1600 START OUT OF EZ AFTER COLLECTING SIX SOIL SAMPLES. REMOVAL ACTIONS ARE NOT COMPLETED

1615 START BACK AT CP COMPLETING SAMPLE PAPER-WORK.

1705 START OFF SITE FOR THE DAY.

12/11/98

0705 START JEFF WRIGHT ARRIVES AT WESTBANK COMMAND POST. USCOE DENNIS WHITE IS ON SITE.

0710 START WRIGHT CONDUCTS DAILY SITE SAFETY MEETING. SEE SITE SAFETY FORM. WEATHER CLOUDY 68° 50% CHANCE OF RAIN.

0715 OSC JOHN MARTIN ON SITE.

0730 J. WRIGHT COORDINATING SITE FILE THAT HAS BEEN WORKED ON SINCE NOVEMBER 9, 1998.

1030 J. WRIGHT CONTINUES TO WORK ON FILES.

1130 START WRIGHT + OSC MARTIN INSPECTED (b) (6) [redacted] AND SPOKE WITH OWNER ([redacted]). NO ACM WAS FOUND ON THE PROPERTY. (b) (6) [redacted] STATED THAT HE POURED WASH OUT CONCRETE OVER THE WHOLE AREA.

1145 OSC JOHN MARTIN OFF SITE FOR THE DAY. TO CATCH FLIGHT BACK TO DALLAS.

1200 START WRIGHT ON LUNCH BREAK

1300 START BACK AT COMMAND POST TO RESUME WORK ON FILES AND PACKING SUPPLIES.

1435 CP WORK CONTINUES.

1500 START WRIGHT AT SITE #1708 TO COMPLETE POST REMOVAL SAMPLING. SEE REMOVAL SUPPORT LOG BOOK.

1630 START BACK AT COMMAND POST TO COMPLETE PAPERWORK.

12/12/98 12/12/98

0635 START JEFF WRIGHT ARRIVES AT WESTBANK COMMAND POST.

0650 USCOE DENNIE WHITE IS ON SITE.

0701 START WRIGHT CONDUCTS DAILY SITE SAFETY MEETING SEE SITE SAFETY FORM. MOSTLY CLOUDY HUMID 68°F.

0705 START WRIGHT COMPLETING SAMPLE SKETCH OF SITE 1708 AND PACKAGING SAMPLES FOR SHIPMENT

0730 START Greg Day arrives at CP

0800 Updating database

0900 START Day departs CP to investigate/recheck two sites - #422 and #1565

0915 Checking 422 - new property owners, want to expand driveway dug up fence posts, uncovered ACM about 8 inches down in one hole. Also pointed out splashed concrete on siding of house. Will refer this to COE.

0945 Rechecking 1565, no visible ACM.

1000 At site 1963 to sample

1130 Lunch break

1230 Lunch break completed

Late entry - START Wright departed CP at about 0930.

1300 Depart CP to check new site out #2026

1320 Returned to CP, site 2026 definitely has ACM

1330 Depart CP for the day

Gregory R Day

12/16/98 SO6.9607.012

0800 JEFF WRIGHT DEPARTS RESIDENCE FOR ENTERPRISE RENTAL.

0840 START WRIGHT DEPARTS BATON ROUGE FOR WESTBANK ASBESTOS SITE.

1010 J. WRIGHT ARRIVE AT WEST BANK COMMAND POST. WILL WORK ON FILE COORDINATION, RETURN PHONE CALLS AND BEGINS PACKING UP EQUIPMENT.

1230 START ON LUNCH BREAK

1305 COMMAND POST DUTIES CONTINUE.

1705 START WRIGHT BACK ENROUTE TO BATON ROUGE.

1900 START WRIGHT ARRIVES BACK IN BATON ROUGE.

S06.9607.012 12/17/98

0730 START WRIGHT DEPARTS BATON ROUGE FOR WEST BANK SITE.

0905 START WRIGHT ARRIVES AT COMMAND POST.

0930 START COORDINATING FILES, INPUTING DATA AND PACKING UP EQUIPMENT. NO SITE WORK/SAMPLING WILL BE CONDUCTED TODAY.

1200 START ON LUNCH BREAK.

1240 COMMAND POST WORK CONTINUES.

1650 START DEPARTS CP FOR BATON ROUGE

1830 START WRIGHT ARRIVES BACK IN BATON ROUGE. WILL RETURN RENTAL CAR TOMORROW.

Jeff Wright

1/6/99 506.9607.0012

1000 START WRIGHT DEPARTS BATON ROUGE AFTER PICKING UP EPA VEHICLE, FOR WEST BANK SITE.

1130 J. WRIGHT ARRIVES AT WEST BANK COMMAND POST

1200 J. WRIGHT ANSWER PHONE MESSAGES AND PACKING OFFICE SUPPLIES FOR DEMOBILIZATION.

1600 START BACK ENROUTE TO BATON ROUGE.

1745 START BACK IN BATON ROUGE TO UNLOAD EQUIPMENT.

Jeff Wright



**ecology and environment, inc.**

Recycled Paper/569129