REDACTED VERSION

Delta
FIT 227

47 Drums mostly upright
rusted beyond recognition

3 Anhydrous $AlCl_3$

Some expanded, none leaking

on wooded lot, 200 ft from strip mall
1/4 mi from Day Care

had been pesticide plant

100 ft south

FM 149 + Grant [redacted] (b) (6)

1982 [redacted] (b) (6) [redacted] (b) (6) [redacted] Co.

[redacted] (b) (6)

Ecology + Environment

[redacted] (b) (6)

barbed wire

100 ft

pit

9796579

[redacted] - Houston Lab

50 drums Harris Co a few $AlCl_3$
9602 Front Rd
thru gate follow rd to right

[redacted]

bad shape - leaking, child care center in front of site, been there for years, drums stacked, several have been knocked over

Warner Cable

[redacted]

[redacted]

CERCLIS No.

Front Rd TXD982305195

New Contact for TWC

(b) (6) [redacted]