Please print or type. (Form designed for use on elite (12-pitch) typewriter.) Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: 30500
2. Page 1 of 1
3. Emergency Response Phone: 214-789-1627
4. Manifest Tracking Number: 013487486 JJK

5. Generator's Name and Mailing Address: US EPA REGION 6-CES ENVIRONMENTAL, 1445 ROSS AVE, SUITE 1200, DALLAS, TX 75202, ATTN: GARY MOORE, 214-789-1627

Generator's Site Address (if different than mailing address): US EPA REGION 6-CES ENVIRONMENTAL, 4904 GRIGGS RD, Houston, Texas 77021

Generator's Phone:

6. Transporter 1 Company Name: C/KL SERVICES — U.S. EPA ID Number: TXR000079753

7. Transporter 2 Company Name — U.S. EPA ID Number:

8. Designated Facility Name and Site Address: Blue Ridge Landfill Permit #89429, 2200 FM 521, Fresno, Texas 281.835.6142 — U.S. EPA ID Number: SWR #89429

Facility's Phone:

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
	1. NONHAZ CLASS 1 LIQUIDS FOR SOLIDIFICATIOIN	001	TT	Est 40210	GL	EXBF-207-1
	2.					
	3.					
	4.					

14. Special Handling Instructions and Additional Information: REPUBLIC WASTE APPROVAL #51121419794 — CUSTOMER # 333354
132 VB 607 VB 234786

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Gary Moore for EPA — Signature: [signature] — Month 4 Day 16 Year 2015

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials

Transporter 1 Printed/Typed Name: Kevin Kammerline — Signature: [signature] — Month 4 Day 16 Year 15

Transporter 2 Printed/Typed Name — Signature — Month Day Year

DESIGNATED FACILITY

18. Discrepancy

18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

Manifest Reference Number: Esp 8/5/15

18b. Alternate Facility (or Generator) — U.S. EPA ID Number

Facility's Phone:

18c. Signature of Alternate Facility (or Generator) — Month Day Year

Republic Services 2200 FM 521 (PO Box 879) Fresno, Texas 77545 APR 16 2015 Blue Ridge Landfill Permit# 1805A SWR# 89429

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1. H132 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a

Printed/Typed Name: Michael J. — Signature: [signature] — Month 4 Day 16 Year 15

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

9848341

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: 33000
2. Page 1 of 1
3. Emergency Response Phone: 214-789-1627
4. Manifest Tracking Number: 013487487 JJK

5. Generator's Name and Mailing Address: US EPA REGION 6-CES ENVIRONMENTAL, 1445 ROSS AVE, SUITE 1200, DALLAS, TX 75202, ATTN: GARY MOORE, 214-789-1627

Generator's Site Address (if different than mailing address): US EPA REGION 6-CES ENVIRONMENTAL, 4904 GRIGGS RD, Houston, Texas 77021

Generator's Phone:

6. Transporter 1 Company Name: CKG Services LLC — U.S. EPA ID Number: TXR000079159

7. Transporter 2 Company Name — U.S. EPA ID Number:

8. Designated Facility Name and Site Address: Blue Ridge Landfill Permit #69429, 2200 FM 521, Fresno, Texas 281.835.6142 — U.S. EPA ID Number: SWR #69429

Facility's Phone:

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
	1. NONHAZ CLASS 1 LIQUIDS FOR SOLIDIFICATIOIN	001	TP	4020	GL	F38F-207-1
	2.					
	3.					
	4.					

14. Special Handling Instructions and Additional Information: REPUBLIC WASTE APPROVAL #5112141794 CUSTOMER # 333354 132 VB-607 VB 23313

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: GARY MOORE for EPA — Signature: [signature] — Month 4 Day 7 Year 2015

GENERATOR

INT'L

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

TRANSPORTER

17. Transporter Acknowledgment of Receipt of Materials

Transporter 1 Printed/Typed Name: Shawn Bathoan — Signature: [signature] — Month 4 Day 7 Year 15

Transporter 2 Printed/Typed Name — Signature — Month Day Year

DESIGNATED FACILITY

18. Discrepancy

18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

Manifest Reference Number:

18b. Alternate Facility (or Generator) — U.S. EPA ID Number

Facility's Phone:

18c. Signature of Alternate Facility (or Generator) — Month Day Year

Republic Services 2200 FM 521 (PO Box 279) Fresno, Texas 77545 APR 07 2015 Blue Ridge Landfill Permit# 1505A SWR# 69429

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1. H132 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a

Printed/Typed Name: Michael [illegible] — Signature: [signature] — Month 4 Day 7 Year 15

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

Please print or type. (Form designed for use on elite (12-pitch) typewriter.) Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: 30500
2. Page 1 of 1
3. Emergency Response Phone: 214-789-1627
4. Manifest Tracking Number: 013487488 JJK

5. Generator's Name and Mailing Address: US EPA REGION 6-CES ENVIRONMENTAL
1445 ROSS AVE, SUITE 1200 ATTN: GARY MOORE
DALLAS, TX 75202 214-789-1627

Generator's Site Address (if different than mailing address): US EPA REGION 6-CES ENVIRONMENTAL
4904 GRIGGS RD
Houston, Texas 77021

Generator's Phone:

6. Transporter 1 Company Name: CKG Services LLC — U.S. EPA ID Number: TXR000079159

7. Transporter 2 Company Name — U.S. EPA ID Number:

8. Designated Facility Name and Site Address: Blue Ridge Landfill Permit #89429
2200 FM 521
Fresno, Texas 281.835.6142
U.S. EPA ID Number: SWR #89429

Facility's Phone:

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
	1. NONHAZ CLASS 1 LIQUIDS FOR SOLIDIFICATIOIN	001	TT	EST 4020	GL	FX8F-207-1
	2.					
	3.					
	4.					

14. Special Handling Instructions and Additional Information: RE USED WASTE APPROVAL #51121419794 CUSTOMER # 333354
132 ~~VB-007~~ VB 28203

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: Gary Moore for EPA — Signature: [signature] — Month 3 Day 7 Year 15

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials

Transporter 1 Printed/Typed Name: Irvin Rodriguez — Signature: [signature] — Month 3 Day 7 Year 15

Transporter 2 Printed/Typed Name — Signature — Month Day Year

18. Discrepancy

18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection

Manifest Reference Number:

18b. Alternate Facility (or Generator) — U.S. EPA ID Number

Facility's Phone:

18c. Signature of Alternate Facility (or Generator) — Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)

1. H132 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a

Printed/Typed Name: Michael R. — Signature: [signature] — Month 4 Day 7 Year 15

Republic Services
2200 FM 521 (PO Box 879)
Fresno, Texas 77545
APR 07 2015
Blue Ridge Landfill
Permit# 1505A
SWR# 89429

GENERATOR — INT'L — TRANSPORTER — DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR

6.0

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator ID Number: 30500
2. Page 1 of 1
3. Emergency Response Phone: 214-789-1627
4. Manifest Tracking Number: 013487490 JJK

5. Generator's Name and Mailing Address: US EPA REGION 6-CES ENVIRONMENTAL
1445 ROSS AVE, SUITE 1200 ATTN: GARY MOORE
DALLAS, TX 75202 214-789-1627

Generator's Site Address (if different than mailing address): US EPA REGION 6-CES ENVIRONMENTAL
4904 GRIGGS RD
Houston, Texas 77021

Generator's Phone:

6. Transporter 1 Company Name: CKG Services LLC
U.S. EPA ID Number: TXR000078159

7. Transporter 2 Company Name
U.S. EPA ID Number

8. Designated Facility Name and Site Address: Landfill Permit #89429
2200 FM 521
Fresno, Texas 281.835.6142
U.S. EPA ID Number: SWR #89429

Facility's Phone:

9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers No.	10. Containers Type	11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
	1. NONHAZ CLASS 1 LIQUIDS FOR SOLIDIFICATIOIN	001	TI	Est 4000	GL	F38F-207-1
	2.					
	3.					
	4.					

14. Special Handling Instructions and Additional Information: REPUBLIC WASTE APPROVAL #51121419794 CUSTOMER # 333354
132 VB 997 23322

15. **GENERATOR'S/OFFEROR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.
I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Generator's/Offeror's Printed/Typed Name: MARK HAYES
Signature
Month 3 Day 17 Year 15

16. International Shipments ☐ Import to U.S. ☐ Export from U.S. Port of entry/exit:
Transporter signature (for exports only): Date leaving U.S.:

17. Transporter Acknowledgment of Receipt of Materials
Transporter 1 Printed/Typed Name: Shawn O'Rourkes
Signature
Month 3 Day 17 Year 15

Transporter 2 Printed/Typed Name
Signature
Month Day Year

18. Discrepancy
18a. Discrepancy Indication Space ☐ Quantity ☐ Type ☐ Residue ☐ Partial Rejection ☐ Full Rejection
Manifest Reference Number:

18b. Alternate Facility (or Generator)
U.S. EPA ID Number

Facility's Phone:

18c. Signature of Alternate Facility (or Generator)
Month Day Year

19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)
1. 2. 3. 4.

20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a
Printed/Typed Name: Michael D.
Signature
Month 3 Day 17 Year 15

Republic Services
FM 521 (PO Box 879)
2200 FM 521
Fresno, Texas 77545
MAR 17 2015
Blue Ridge Landfill
Permit# 1505A
SWR# 89429

GENERATOR

INT'L

TRANSPORTER

DESIGNATED FACILITY

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

DESIGNATED FACILITY TO GENERATOR