Site Name:	Operational Period:	U.S. EPA Region 6
Task Order 62 CES Environmental	Date: 2-13-2015	**DAILY WORK ORDER**
Branch: Federal	Division/ Group: Response	mergency and Rapid Response Service

WORK AUTHORIZED:

Continue to pump water on site as necessary, depending on rainfall.

Continue development of profiles and disposal of sludge, liquids, and solids.

Continue removal of water, oil, sludge, and waste, from the ASTs, Frac Tanks, Totes, and Drums.

Site Cerclis:#	TXD 008950461	On-Scene Coordinator:	ERRS Response Manager
Contract Number:	EP – S6 - 07 -02	Gary Moore, USEPA	LeRoy Cassidey, CB&I Federal
Task Order:	062	Date: 2.13.2015 Time:1700	Date: 2.13.2015 Time: 1700

PERSONNEL ON-SITE:	QTY	Used	Unused
Response Manager	1	1	
Foreman	1	1	
	0	0	
Truck Driver/Equip Op	1	1	
Laborer	2	2	
PERSONNEL OFF-SITE			
Subcontract Manager	1	1	
Transport and Disposal Coord	1	1	
Field Cost Accountant	1	1	
Health and Safety Manager	1	1	

EQUIPMENT ON-SITE:	QTY	USED	Unused
Pick –up Truck	2	2	
Generator	1	1	
Trash Pumps	0	0	
PID	1	1	
Frac Tank w Liner	1	1	
4,000 PSI Pressure Washer	1	1	
Open Top Roll Off	8	8	
Vacuum Truck Air Mover	1	1	
Carbon Vapor Unit	1	1	
Skid Steer	1	1	
Vacuum Boxes	25	25	
9,000 lb Overhead Lift	1	1	
Storage Trailer	1	1	
Myers (Bean) Pump	1	1	
Air Compressor	1	1	

WORK ACCOMPLISHED / AMENDMENTS *(problem areas, general comments, summary)(Input for day's 1, 900-5Pon5):*

The RM coordinated site activities with the Foreman, processed invoices, and operational-H/Safety paperwork. He continued discussions on waste categorization waste disposal. Updated CES Truck Log and Container Log.

T&D Coordinator continue waste profiles, approvals, and continue discussions on waste categorization waste.

The crew completed removal of water and sludge from N OT 8. Crew removed water from the WWTS sump. Crew removed bolts from T8.

OSC	Date:	Time:	RM	Date:	Time:
Gary Moore	2/16/15	0945		2.16.2015	~~1100~~ 0818

Next OPERATIONAL PERIOD *(administrative, tactical / resource status changes, special instructions, H&S)(Input for next DWO):*

Remove bolts from manways on WWT tanks and start sludge removal.

FT 1001 transport to and disposal at Lonestar Ecology LLC on Monday.

9858700