9006-05

ecology and environment, inc.

International Specialists in the Environment

Job Number (DAllAS - TS 1306)

Anacast Foundry site,
Kennedale, Texas

TDD# : T06-9006-05
PAN# : TTXΦ25ΦSAA
CERCLIS : TXDΦ585Φ4762
OSC : Charles Fisher
TAT : MO ERFANI

994290

E & E Job Number TS1306 - DALLAS

Telephone Code Number

Site Name Anacast Foundry

State/City Texas / Kennedale

TDD T06-9006-05

PAN TTX025ØSAA

SSID TXDØ585Ø4762

Start/Finish Date 7-13-90 / 7-13-90

Book 1 of 1

E & E Emergency Response Center: (716) 684-8940

TDD#: T06-9006-05
TXD058504762

Anacast Foundry

7/13/90

0830 TAT members Chris Quina, Marty Rutledge and Mohsen ERFANI left the office for the site with EPA-TAT vehicle.
Direction to the site: Hwy 20 West to Mansfield Hwy business → go left (South) toward Kennedale, Texas
Site: 701 Mansfield Hwy business

Things to do:
1) Visual observation
2) use of EM31 (Ground conductivity meter)
3) use of a metal detector

BackGround: Anacast is out of business for over a year now, Anacast is a subsidery of Anadite. (Forging of Al & Mg castings)
contact: George AbiSAAB
817/282-9171 Ex. 221
Texas Water Commission:
214/298-6171

M. Erfani

4 TDD#: T06-9006-05
TXD #58504762

Anacast Foundry

7/13/90

Situation: EPA Region 6 Received a letter indicating that The Anacast Foundry in Kennedale, Texas has a large number of buried hazardous drums. The letter indicates that The main burial is behind the employees parking lot & near a house on old Dick Price Road.

TAT contacted Texas Water Commission in regard to above matter → TWC is not aware of any buried drums.

OSC: Mr. Charles Fisher (Recomendations): 1) conduct Site Assessment 2) visual observation 3) use EM-31

M. Eufai

Anacast Foundry

7/13/90

0915 TAT members arrived at the site.
Temperature: 73°F, SUNNY (A beautiful day!) TAT is conducting site safety/plan/Review and meeting at this time. (Topics discussed Refer to safety plan)
Responsibilities:
Mohsen ERFANI – Project Manager
Chris Quina – Safety and E31 operator
Marty Rutledge – support

0930 George Abi SAAB with Anadite took TAT members into the site for observation. TAT conducted a visual observation of the site and found no drums or any hazardous material. No stain or any noticeable odor was observed. It appears that all drums or machinery Removed from the site.

M. Erfani

6 TDD#: T06-9006-05
ITXD#58504762

Anacast Foundry

7/13/90 Photographer: ERFANI

Camera: 35AFF/645502

1010 (#1) West
(#2) West
(#3) West
(#4) South
(#5) South
(#6) South
(#7) South
(#8) West
(#9) South
(#10) South
(#11) North
(#12) North
(#13) North
(#14) South
(#15) North
(#16) North

TAT Members are Investigating the site and using EM-31, Metal detector or just visual observation of the site. pictures show TAT's work activities at the site.

(#17)
(#18) Pano North area
(#19) of work with EM-31

(#20) Pano North
#21 area of Worth with EM-31

M-Efani

TDD#: T06-9006-05
TXD0585Ø4762

Anacast Foundry

7/13/90

0950 TAT Member Chris Quina Preparing EM-31 Instrument for site investigation at this time; all Instrument calibration / functions are checked by TAT Member Quina.

1000 TAT Member Marty Rutledge is Conducting site Inspection with a metal detector at this time (MAC-51B).

1010 Mr. George AbisAAB is not aware of any waste hauled away in 1987 by black-Mooring Company. Mr. George AbisAAB gives TAT Member Mohsen ERFANI a letter from Texas Water Commission (dated 1/2/90) in regard to TWC Inspection of the facility on 12/12/89.

1025 TAT Member ErfanI is drawing a site sketch of the site. M-Erfani

8 TDD#: T06-9006-05
TXD Φ585Φ4762
Anacast Foundry

7/13/90



M. Erfani

TDD#: T06-9006-05
TXD Φ585Φ4762

Anacast Foundry

7/13/90



M. Eifani

10 TDD#: T06-9006-05
TXD#585Ø4762

Anacast Foundry

7/13/1990

1037 TAT member Quina is working with Data logger in conjuction to EM-31. TAT member is inputing data and gathering Information at this time.
No unusual reading observed at this time. No indication of buried drums or any unusual features. TAT member Quina is continuing observation with EM-31 and data logger (these activities are concentrated at North east, North west, center portion of the site near Price Road.

1040 TAT member ERFANI & Mr. George Abisaab are at south portion of the site → No drums or Machinery were observed.
M. Erfani

TDD#: T06-9006-05
TXD#585044762

Anacast Foundry

7/13/1990

1045 TAT Member Marty Rutledge completed site inspection with the Metal detector at this time; no unusual reading was observed.

1050 TAT Members are working with EM-31 to complete Site Inspection at this time. EM-31 is a Geophysical Survey Instrument utilizing a conductivity meter and a magnetic cable locator which measures the conductivity of subsurface soils. The Instrument has a depth range of approximately 15 feet. Also, MAC-51B Magnetic was used which is designed to detect buried metals and tracing underground

M. Eifani

12 TDD#: T06-9006-05
TXD Φ585Φ4762
Anacast Foundry
7/13/1990

1110 cables and pipes.
The Instrument has an approximate depth range of six feet. XXXX
The following is contents of TWC (Inspection) letter dated 01-02-90: "On December 12, 1989, the Writer contacted (writer is Paul Cooper of TWC) George Abi-Saab, Safety Director, and conducted a compliance Evaluation Inspection at the referenced facility. The Company is located at 7901 West Mansfield Highway in Kennedale, Texas. The Company has ceased operation and has removed all wastes and machinery from the facility. The Company does not intend to

M. Erfani

TDD#: T06-9006-05
TXD 0585 04762

Anacast Foundry

7/13/90

resume operation at the facility and intends to sell it (The property). Based on previous inspection report as well as this Inspection, There is no contamination left on-site. It is requested the Company's registration be inactivated. There were no significant violations of the Texas Hazardous and solid waste Regulations alleged during this inspection."

1130 TAT members left the site for lunch break / office at this time.

M. Enfani

14 TDD #: T06-9006-05
TXD055504762

7/13/90 Anacast Foundry

telephone Directory:

George Abi-Saab
with Anadite ~~a~~ME
~~subsidery~~ME anacast
used to be a
subsidery of
Anadite
817-282-9171 ex: 221

Texas Water Commission
(Paul Cooper)
214-298-6171

Environmental protection Agency
(Charles Fisher - OSC)
214-655-2270

Ecology & Environment, Inc.
(EPA - contractor)
MO Erfani
214-742-6601

M. Erfani

TDD#: T06-9006-05
TXD0585 04762
7-13

Instrument used:

EM-31 : borrowed from Region 7 (K.C.).

MAC-51B : Metal detector (#696788)

Camera: (#645502)

M. Erfani