TOPIC: MDNR - call

DATE: 2/18/14

FILE UNDER:

PAGE:

0714

40462398

3.0

Superfund

0100

→ MDNR response -

→ Surface

$9^{20}/9^{30}$ Pattonville FD

on-site are monitoring

hand held / Area RAE's - nothing detected

$\approx 10^{00}$ under control -

1 day extinguisher

1 trunk of soil

→ Gas extraction 78

"popped" top minimal odors

Construction complete -

$\approx$ 10 ft x 15 ft

Leachate pre-treatment Tank #1 lost

ring to be completed this week -

Liquid tightness tension in next few weeks -

MFE letters

- Surface event
- Gas monitoring "pop-off"

→ ? Loop back with state gmp - ?

Incident fall apart - Republic keeping up w/ several meeting

Delay in notification by Republic

(1) Try to require "pager" like response system -

(2) Camera's on landfill @ multiple locations -

→ (3) AG may be reaching out on schedule for installing barrier -

Order negotiations?

CO data looks good. ←

Maps -

Phase 2 work plan

MDHSS → MCE inquiry (?)

→ ? Comments -

TOPIC:

DATE:

FILE UNDER:

PAGE:

Call w/ MoAg

KB opening remarks → RP's

CT ① Input from state TCR

continue & build on

RH ② - Air monitoring issue

CT ③ Non-RIM bundling ?? → ?

RIM

Non-RIM

DH ④ Negative Easement - St. Louis Airport Authority

GC PT readings -

Start on East

* indicate gently constructive beginning → keep accelerator down -

* economy forward?