9-5-02 Herculaneum Lead Smelter TO-27

0615 STM R. Schuler leaves office

0720 Arrive on Site, Today's weather will be Knice, high's in the upper 80's. Activities today will include: ① Oversight of Backfilling / Exc. by ER ② Road Sampling ③ Data Entry ④ Shoot ATC's Confirmation Samples. ⑤ Load Hi-Vols ⑥ - Recall interior Recon. Residents who we have not been in contact with

0800 - Revo Calibrates Niton - Then Road Samples

0830 Schuler begins shooting Confirmation Samples

0845 Schuler and OSC Silver out to oversee Activities - Revo begins Road Sampling

0900 Put up fence at high school, 561 Reservoir backfilling with rock, 491 Ling - needs Seed and Straw. 423 Thurnell complete 361 Mott complete

1000 All other activities on property are the same as yesterday. - Schuler and Silver out to look at properties in Pevely That have ~~potential~~ RCS contamination, Also view properties in Crystal City. looking for ABNORMALTIES.

1100 Revo continues ~~Recontamination~~ RCS Road Sampling

12-12:30 Lunch

A717 40499079 2.0
Superfund
0400

9-5-02 Herculaneum Lead Smelter TO-22

1300 Reno finishes Road Sampling - Then takes lunch.

1330 Schuler updates DATABASE - both POST EXC. loading and Soil Recontamination.

1400 OSC Silver has conference call, STM Schuler loads Hi-Vols STM Reno fills in for Schuler and updates EXCEL Spreadsheet for interim lead cont. results.

1500 Schuler finishes Hi-Vols

1510 Silver finishes Conference CALL.

1630 LEAVE Site

1745 ARRIVE at office - End of Day

Roger Schuler
9-5-02