20 10-11-02 Herculaneum Lead Sue Hall G9011.L01.0027.00

0615 STM R. Schuler leaves office

0720 Arrive on site. Today's Activities will include: (1) Load Hi-Vols (2) Oversight of Exc. (3) Prepare Samples and COC's for shipment to Laboratory. (4) Work on meeting Agenda for focus group meeting on Oct 23rd. (5) Sample soil @ 812 Brown.

0730 - Today's weather will be OVERCAST - High's in the middle to Low 70's - No Rain is expected and there is no wind.

0800 - Schuler Returns tel. calls.

0900 Reno - out to unload /Reload Hi-Vols at Doe Run There is fire Engines ~~& Police Cat~~ RCS - no smoke - (STM Schuler will call DR to see what occured.

1000 OSC Siller is off site again will Return Tuesday.

1015 - Oversee Exc. Activities -

1100-1130 - Lunch

1145 Exc. Activity @ 353 Mott and 419 Hill and 139 Nassau - backfilling.

A717 40499104 2.0

Superfund

0100

10/11/02 Herculaneum Lead Smelter TO-22 10/1

According to ER there is a homeowning 06

parade today which will be occuring 07

at 13:00 - 14:00 will wrap through

Herculaneum, ER will not

1230 Reno Runs Hi-Vol Calculations, STM Schuler

~~13~~ is to 353 Mott to check Excavation

- There is still handwork that needs completing

when STM Schuler arrives on Site, the

homeowner has his minivan in the contaminated

soil LOAD OUT pile. 0800

1300 - Package up cooler for shipment to LAB.

1400 Fill out timesheet for the week

and close up activities for

the day. 090

1430 LEAVE Site

1545 ARRIVE at office, End of week

100

1100