27 11-4-02 Herculaneum Lead Smelter TO-27

0630 STM R. Schuler leaves office

0730 Arrive on Site. Activities today includes: (1) Print out data. - we now have a new printer (finally) (2) Oversight of Excavation (3) Soil Recontamination Sampling (4) Load Hi-Vols

0800 - Setup New Printer

0830 Schuler calls ER - They will only be cleaning up some Equipment, No Excuse occur, ~~Perhaps~~ DRCS They might be doing some concrete work.

0900 - Reno & Schuler take a look at yards to do Recon Sampling. Yards are still extremely wet.

11-1130 - Lunch

1200 Reno Enters/organizes Data, Schuler puts data into Binders.

A717 40499119 2.0

Superfund

0400

CMFames