11-25-02 Herculaneum Lead Smelter 69011.L.01.0027.01

0615 STM R. Schuler leaves ~~site~~ RCS office

0730 Arrive on Site. Today's Activities includes: (1) Oversight of Exc. (2) Unload & Reload Hi-Vols (3) Data Entry (4) Purchase Site Supplies. (5) Leak Tests for Niton

0800 - STM Schuler to get oil changed and pick up supplies at Walmart
- Rono enters lab data that arrived via email

1000 Schuler back to trailer - Rono checks on excavations

1100 Perform leak tests on Niton XRF units.

12-12:30 Lunch

1245 STM Schuler mails - leak tests, Exc Activities include: 710 Brown, 227 Joachim 417 Burris - excavation

1300 - Rono unloads Hi-Vols - reload

1400 - STM Parish picks up minivan and drops off Suburban

1500 STM Schuler reads over

A717 40499134 2.0

Superfund

0100

:00270 11-25-02 Herculaneum Lead Smelter TC-27

Deposition Sampling plan.

1545 - LEAVE SITE (END of Day)

1700 - ARRIVE at office - End of Day