12/23/02 H2S TO-27

0620 STM R. Schuler leaves office.

0730 Arrive on Site. Activities today include:

① Oversight of EXCAVATION

0800 - Schuler works on paperwork

1030 - Schuler with G. Walker of Doe Run to check on properties - EXC in Crystal Heights at 156 Acline to delineate cont. There is some discrepancy.



After Reviewing The Nitan Readings

A717 40499153 2.0

Superfund

0100

12/23/02 HLS TO27

The whole QUAD will be taken OUT. In The back there is gravel That will be taken.

1130-1230 Lunch

1300 Schulz oversees Site Activities

1300 1461 Crystal Heights Road - to sample - post Exc. Exc. The Front of The House - Back to trailer to shoot samples.

1530 Leave Site - Ends of Day

1645 Arrive at office