12-16-91

2nd Shift Hazmat Incident

9:30
~~9:30~~ I got a call that the plumber's had responded to a possible hole in Tank #4 Deoxidizer

9:40 After finding what appeared to be 100 gallon's of material in the secondary containment I called Tim Savage to report the spill

9:50 After talking with Tim and determining the possible danger's it was decided to call a Hazmat incident / Shop evacuated

10:00 Boeing fire Dept arrived on the scene

1100 after talking with Gary Shirk it was decided the plan of action would be to drain the #4 Tank into our portable Tank so as to prevent the remainder of the material & inside the tank from eating away the tank. Then He requested that we pump out as much material as possible from the secondary containment in the event more material leaked from the tank into the pit. - posibility of material between the liner and Tank wall

11:30 1st entry Team pumped out Tank #4 - came out at 12:00 pm - Deconed

12:04 2nd entry Team pump's out pit - came out at 12:25 pump out Completed

12:45 Incident Closed, Security on Duty to prevent entry by shop per Gary Shirk

Gary Shirle requested that security guard the area until Facilities makes their evaluations.

The entry team reported a one inch gash in #4 Tank about half way up the wall

There will be a post Incident meeting at 7:00 pm in the facilities Confrence Room

Pat O'Neill