10-31-90

Jim -

I need additional information on this incident that occurred on 10-31-90. Please provide the following information:

- Time of Spill:

- You indicate that 50% of the coolant fluid ~~was~~ discharged to the storm sewer / River. Why was the West Point Treatment Plant notified instead of the WA State Dept of Ecology? Was the catch basin that this liquid flowed into thoroughly cleaned out?

- It is my understanding that the spilled coolant originated from a tub skid of metal chips and not a drum of chemical. Please verify.

All future spills to Metro must be reported to the West Point Treatment Plant immediately & all spills to the storm sewer must be reported to the site environmental engineer immediately. We can be reached through Plant Services Dispatch when we are not at work.

If you have any other information regarding this incident please write it down. I need this information by tomorrow so I can make the appropriate reports to regulatory agencies. Thanks.

Ty Gaub
Div II Environ. engineer

B-DUW2-2457992