

KCSlip4 69217

SEA437308

January 64

1-1-64	–
1-2-64 Hilton	Pumped sludge washed down tanks, Ran lab. Made one drying bed ready for sludge. Cleaned pump wet well
1-3-64 Hilton	Pumped sludge, washed down tanks, Ran lab. cleaned bio-filter spray arms. cleaned pump wet well.
1-4-64 Tony	Pumped sludge at 9:05 AM + 2 PM
1-5-64	
1-6-64 Hilton	Pumped sludge washed down tanks Ran lab. went to pump station cleaned pump wet well. pumped 7000 gal. digested sludge to drying bed. went to Cascade, pump station and Skyway.
1-6-64 Hilton	Pumped sludge washed down plant. went to Cascade to work on spray fields in A.M. and P.M.

KCSlip4 69218

SEA437309

1-8-64 Hilson	Pumped sludge, washed down plant Ran lab., pumped out scum pit, cleaned pump wet well. unknown substance came into plant, will not settle in primary tank, has to be scimed off. looks like fiber of some kind.
1-9-64 Hilson	Pumped sludge washed down tanks Ran lab, cleaned pump wet well, went to Cascade plant,
1-10-64 Hilson	Pumped sludge washed down plant Ran lab, cleaned bio-filter spray arms, cleaned pump wet well,
1-11-64	Pumped Sludge at 9AM & 2PM
1-12-64	
1-13-64 Hilson	Pumped sludge washed down plant 2 Glen here and took out No 2 wet well pump for repair, Went to Cascade, pump station & Skyway, Ran lab, cleaned pump wet well.

KCSlip4 69219

SEA437310

1-14-64 Wilson	Pumped Sludge, washed down plant, pumped out scum pit, Wendy here to put No 2 wet well pump back after repairing shaft and lower bearing. Ran lab. cleaned pumps wet well.
1-15-64 Wilson	Pumped Sludge washed down plant, Ran lab. went to Renton plant, Cleaned pump wet well.
1-16-64 Wilson	Pumped sludge, washed down plant, Ran lab. cleaned bio-filter spray arms, put in 3 bulbs in yard lights. cleaned pump wet well. took check valve out of sump pump and cleaned
1-17-64	Washed down plant, pumped Sludge, Ran lab. went to Cascade, pump station and Skyway.
1-18-64	Pumped Sludge at 9 A.M. & 2 P.M.
1-19-64	

KCSlip4 69220

SEA437311

1-20-64 Pumped sludge washed down plant, went to Cascade, pump station + Skyway, Helped charge Chlorine tank at Renton plant. Ran lab.

1-21-64 Pumped sludge washed down Kilson tanks Ran lab, pumped out scum pit, cleaned pump wet well, went to Renton plant and helped charge floats in wet well,

1-22-64 Pumped sludge washed down Kilson tanks, Ran lab. went to safety meeting, went to Cascade to work in spray filter, cleaned pump wet well,

1-23-64 Pumped sludge washed down tanks, Ran lab., charged pump wet well, cleaned bio-filter spray arms,

1-24-64 Pumped sludge washed down tanks went to Renton plant to put on B.O.D. test cleaned pump wet well Ran lab.

KCSlip4 69221

SEA437312

1-25-64 Pumped Sludge at 930 AM and 2 PM

1-26-64

1-27-64 Pumped sludge, washed down tanks, went to Cascade, pump stations + Skyway, Ran lab, cleaned pump out well, went to new pump station to work on No 2 pumps,
Wilson

1-28-64 Pumped sludge, washed down tanks, Ran lab, pumped out scum pit, cleaned pump out well, Al + Tony brought sludge grinder over from Renton plant but will not work on 440 Volts,
Wilson

1-29-64 Pumped sludge washed down tanks went to Cascade worked in spring fields all AM, over to Renton plant in PM to run B.O.D. test, cleaned pump out well.
Wilson

1-30-64 Pumped Sludge at 8 AM + 2 PM
Went to P.N.P.C.A meeting at Bellevue
Tony

KCSlip4 69222

SEA437313

1-31-64 Pumped sludge washed-down lander Ran lab up clean pump wet well.

2-1-64 - Pumped Sludge at Tony 9AM and 2PM

February

2-3-64 Wilson	Pumped Sludge washed down tanks went to Cascade and pump stations thru to Skyway. Ran lab. cleaned pump out well.
2-4-64 Tony	Pumped Sludge at 8 A.M. 11 A.M. & 2:30 P.M.
2-5-64 Tony	Pumped Sludge - at 8 A.M. 2 PM
2-6-64	Pumped Sludge 3 times
2-7-64	Pumped Sludge - 3 times
2-8-64 Tony	Pumped Sludge twice
2-9-64	Pumped Sludge - twice Pumped out scum pit
2-10-64	Pumped Sludge - 3 times
2-11-64	Pumped Sludge 3 times
2-12-64. Al & Walt	Pumped sludge 3 times. Cleaned Pumps in wet well

KCSlip4 69224

SEA437315

2-13-64 Back after being sick from
Kilson the 4th Pumped sludge
washed down tanks, Ran
lab, cleaned pump out
well, cleaned bio-filter
spray drain.

2-14-64 Pumped sludge washed down
Kilson tanks, Ran lab, pumped
digested sludge to drying
bed, 3500 gal., cleaned pump
out well

2-15-64

2-16-64

2-17-64 Pumped sludge, washed down
Kilson tanks, Ran lab, cleaned
pump out well, took
check valve off sump
pump and cleaned and
replaced, went to Renton
plant to work.

2-18-64 Pumped sludge, washed down
Kilson plant Ran lab. went to
Renton plant while Al + Tony
made the rounds cleaned
pump out well.

KCSlip4 69225

SEA437316

14-64 Wilson	Pumped sludge washed down plant Ran lab, cleaned pump out well, went to Cascade to work in spray field
2-20-64 Wilson	Pumped sludge, washed down plant, pumped out scum pit, cleaned pumps out well, Ran lab. got mama from Renton plant and mowed the lawn.
2-21-64 Wilson	Pumped sludge washed down tanks, went to Cascade, pump station and skyway with Woodi went to Cascade pump station in the P.M. both pumps plugged cleaned same, stick in one rags in the other
2-22-64	
2-23-64	

KCSlip4 69226

SEA437317

2-24-64 Pumped sludge, washed down tanks, Ran lab, cleaned pump out well, work in yard,

2-25-64 Pumped sludge, washed down Wilson tanks, Ran lab. Cleaned filter screens, pumped out scum pit cleaned pump out well, worked in yard,

2-26-64 Pumped sludge, washed down Wilson tanks, went to Cascade pump station and Highway Ran lab. Cleaned out pump out well.

2-27-64 Pumped Sludge washed down Wilson tanks, Ran lab. cleaned pump out well, worked on flow meter,

2-28-64 Pumped sludge, washed down Wilson tanks Ran lab, pumped out scum pit cleaned pump out well, worked on flow meter.

2-29-64

KCSlip4 69227

SEA437318

9 MARCH 64

-64

2-64 Pumped sludge washed
ilson down tanks, went to
Cascade, pumping Stations
and Skyway back at 12:00
Ran lab, cleaned pump
wet well, repaired air hose,

3-64 Pumped sludge, washed
lson down tanks, went to
Cascade, pump station and
Skyway back at 11.45 A.M.
cleaned pump wet well, back
to Cascade spray field and
pump station back at 3:00 PM

4-64 Pumped Sludge washed down
lson tanks went to Cascade, pump
Stations and Skyway back
at 12:40, cleaned pump wet
well, went with Willis to
Cascade to check sludge
back at 2:15 PM, Ran lab.

5-64 Pumped Sludge washed down
Wilson tank went to Cascade, pump
station and Skyway back at
11:00 AM. Ran lab cleaned
pump wet well, worked in
yard.

KCSlip4 69228

SEA437319

3-6-64 Hilson Pumped sludge washed down tank, went to Cascade pump stations and Skyway back at 12:00 cleaned bio filter arms, pumped out scum pit cleaned pump wet well, put 4 new teeth in the comminuter.

3-7-64

3-8-64

3-9-64 Hilson Pumped sludge, washed down tanks, went to Cascade pump stations and Skyway back at 11:00 cleaned pump wet well, got mower and cut the lawn.

3-10-64 Hilson Pumped sludge washed down tanks, went to Cascade pump station, Skyway back at 12:00, went to Skyway to break up sludge blanket back at 2:45 P.M.

11-64 Pumped sludge washed down
Wilson tanks, went to Cascade
pump station and pulled
both pumps to dump back
at 11:30 A.M., 12:30 P.M. went
to Cascade, pump stations
and lagoons.

-12-64 Pumped sludge washed down
Wilson tanks, pumped out scum
pit, went to Cascade to
work on spray fields, back
at 11:30 A.M., changed pump
out well, cleaned out check
valve, went to pump
station and lagoons.

3-13-64 Pumped sludge, washed down
Wilson tanks, cleaned bio-filter
arm, went to Cascade, pump
station and lagoons back
at 11:00 A.M. Ran lab, cleaned
pump out well, work on
monthly report.

3-14-64

3-15-64

KCSlip4 69230

SEA437321

3-16-64 Pumped sludge, washed
Kilson down tanks, went to
Cascade, and pump station
back at 11:00 AM, ran lab,
then to Skyway and pump
station, back at 1:30 P.M.
pumped out scum pit and
cleaned pump out well.

3-17-64 Pumped sludge, washed down
Kilson tanks, went to Cascade
pump station, and Skyway
back at 12:00 noon. Ran
lab, made 2 diaphragms
and put some in air
relay units.

3-18-64 Pumped sludge, washed
Kilson down tanks, went to
Cascade, pump stations and
Skyway, back at 12:00 noon
back to Cascade to help
pump out sludge

3-19-64 Pumped sludge, washed
Kilson down tanks, went to
Cascade to pump sludge
Back at 11:00 AM, cleaned pump
out well, cleaned check
valve, went to Skyway
and pump station and
Cascade.

KCSlip4 69231

SEA437322

-20-64 Wilson	Pumped sludge, washed down tanks, went to Cascade, Skyway and pump station, back at 11:00 A.M. cleaned pump wet well, pumped out scum pit, went to Cascade pump stations
3-23-64 Wilson	Pumped sludge, washed down tanks, pumped out scum pit, went to Cascade and pump stations, back a 11:00 A.M went to Skyway and pump station in the P.M.
3-24-64 Wilson	Pumped sludge, washed down plant, cleaned out one drying bed and started to fill with digested sludge went to Cascade, pump station and Skyway back at 11:00 A.M, put new gasket in check valve for wet well pump, went to Spray field to clean sprinklers,
3-25-64 Wilson	Pumped sludge, washed down plant, went to Cascade pumping Stations and Skyway back at 11:00 A.M. pulled no 2 wet well pump, Gatia air locked,

Cleaned pump out well, pumped digested sludge to drying bed.

3-26-64 Pumped sludge washed down
Wilson tanks, went to Cascade, New Pump Station and Skyway back at 11:30 A.M., cleaned pump out well. Ran lab.

3-27-64 Pumped sludge washed down
Wilson tanks, went to Cascade and pump station back at 11:00 A.M. pumped out scum pit, went to Cascade to repair spray line and to Skyw

3-28-64

3-29-64

3-30-64 Pumped sludge, washed down
Wilson plant went to Cascade, pump station and Skyway back at 11:30 AM cleaned pump out well, went to Didymo plant to get 20 sack lim

KCSlip4 69233

SEA437324

-31-64 Pumped sludge, washed down
Nelson plant, pumped out scum
pit, went to Cascade, pump
station and Skyway both
at 11:30 AM, worked on flow
meter relays went to
Cascade to work on spray
line.

KCSlip4 69234

SEA437325

April

4-1-64 Pumped sludge washed down
Wilson tanks, went to Cascade to
take rags out of pumps at
north pump station, then
to plant, other pump station
and skyway, back at 11:30 AM
worked on flow meter, then
to Cascade to work on spray
lines.

4-2-64 Pumped sludge, washed down
tanks, went to Cascade and
pump station and skyway
back at 11:30, got mower from
Renton plant and cut the
lawn, cleaned pump wet
well and bio filter arms,

4-3-64 Pumped sludge, washed down
Wilson tanks, went to Cascade and
pump stations and skyway
back at 11:00 AM, cleaned pump
wet well, went to Cascade
to work in spray fields

4-4-64

4-5-64

KCSlip4 69235

SEA437326

4-6-44 Wilson — Pumped sludge, washed down tanks, went to Cascade plant and pumping stations back at 11:00 A.M. Repaired turn signal on truck, went to Skyway and Tacoma pump station cleaned pump out well.

4-7-44 Wilson — Pumped sludge, washed down tanks, went to Cascade + pump station + Skyway back at 11:00 A.M. Cleaned pump out well, worked on flow meter.

4-8-44 Wilson — Pumped sludge, washed down tanks, went to Cascade + pumping stations + Skyway back at 11:50 A.M. pumped out wash pit, cleaned out pump out well, went to Cascade to work on spray filter

4-9-44 Pumped sludge washed down tanks, went to Cascade + pump stations + Skyway back at 11:45 A.M. Cleaned pump out well, went to Drafting plant for lime.

KCSlip4 69236

SEA437327

4-10-64 Pumped Sludge washed
Hilson down plant, went to
Cascade plant and pumping
stations back at 1100 A.M.
cleaned pump wet well
went to pump station and
Skyway plant,

4-11-64

4-12-64

4-13-64 Pumped Sludge washed down
Hilson tanks, went to Cascade &
pumping Stations & Skyway
back at 11:AM, Cleaned pump
wet well, washed down bio-
filter spray arms, pumped
out scum pit,

4-14-64 Pumped sludge washed down
Hilson tanks, went to Cascade &
Pump station & Skyway,
back at 11:30 A.M. cleaned
pump wet well, cleaned
out drying bed and pumped
it full of digested sludge,

KCSlip4 69237

SEA437328

4-15-64 Wilson	Pumped sludge washed down tanks, went to Cascade & pumping stations, and Skyway back at 11:40 A.M. went to Cascade to work on pumps in wet well
4-16-64 Wilson	Pumped sludge washed down tanks, went to Cascade to drag pumps in wet well back at 11:40 A.M. cleaned pumps wet well, went to Cascade & pump station
4-17-64 Wilson	Pumped sludge washed down tanks, went to Cascade & Pumping stations and Skyway, back at 11:30 A.M. ~~pulled No 1 wet well pump and dragged out the lawn~~, pumped out scum pit.
4-18-64	
4-19-64	

KCSlip4 69238

SEA437329

4-20-64 Pumped sludge washed
Hilson down tanks, went to
pump station, then Cascade
plant and pump stations then
to Skyway plant, back at
11:00 A.M, cleaned pump wet
well, ran lab., went to
Cascade pump station
to derag pump's.

4-21-64 Pumped sludge, washed down
Hilson tanks, pumped out scum
pit, went to Cascade, + pump
station + Skyway. back
at 11:00 A.M. cleaned pump wet
well. Ran lab, cleaned weirs
on primary + secondary
tanks.

4-22-64 Pumped sludge, washed down
Hilson tanks went to pump
station and Cascade back
at 11:30 A.M, cleaned pump
wet well, went to Skyway
plant.

4-23-64 Pumped sludge, washed down
Hilson tanks, went to Cascade and
pump station + Skyway, back
at 11:00 A.M. cleaned pump
wet well, worked at
Renton plant in P.M.

KCSlip4 69239

SEA437330

-24-64 Pumped sludge, washed
Wilson down tanks, went to
Cascade plant, pumping
stations and Skyway, back
at 11:30 A.M., cleaned pump
wit well. Ran lab, went
with Willis in the P.M.

4-25-64

4-26-64

4-27-64 Pumped sludge, washed down
Wilson tanks, pumped out scum
pit, went to Cascade and
pumping station, back
at 11:00 A.M. cleaned pump
wit well, went to Skyway
went to Bryn Mawr to
drag a pump.

4-28-64 Pumped sludge, went
Wilson with Willis to pump
station then to Skyway
back at 1:00 P.M., went
to pump station and
Cascade back at 3:00 P.M.
(cut in new pipe line at pump station)

KCSlip4 69240

SEA437331

4-29-64 Hilson Pumped sludge, washed down tanks, cleaned pump wet well greased all equip, went to pump station & Skyway back to Renton plant then to Cascade and pumping stations back at 12:15 P.M. went to pump station and Cascade with Willis

4-30-64 Hilson Pumped sludge washed down tanks, went with Willis to pump station then to Skyway back at 10:00 A.M. got mower and cut the lawn, went to Cascade plant,

64

5-1-64 Hilson	Pumped Sludge washed down tanks went with Willis to pump station and Skyway, then to Cascade back at 11:45 A.M. Cleaned pump wet well, pumped out scum pit, got one bed ready for sludge.
5-2-64 Tony	Pumped Sludge at 9 AM + 2 PM
5-3-64	
5-4-64 Hilson	Pumped Sludge, washed down tanks, Ron lab. Cleaned pump wet well, went to Cascade to drag pump and work in spray fields.
5-5-64 Hilson	Pumped Sludge washed down tanks, went to Cascade, pump station and Skyway back at noon Cleaned pump wet well, went to Cascade to work in spray field

45-6-64 / Kilson	Pumped sludge washed down tanks Ran lab, cleaned pumps and mill, went to safety meeting at 1115 A.M., went to Cascade to work on spray field
5-7-64 Kilson	Pumped sludge washed down tanks, pumped out scum pit, went to pump station and Skyway to work back at 12:00 noon, cleaned pump and mill, went to Cascade to work on valve
5-8-64 Kilson	Pumped sludge washed down tanks, went to Cascade & pumping station & Skyway back at 1:30 A.M. cleaned pump and mill, pumped out scum pit, worked on secondary bio-filter for ponding,
5-9-64	
5-10-64	

KCSlip4 69243

SEA437334

5-11-64 Pumped sludge washed down tanks, pumped out scum pit, went with Willis & Al to pump station, back at 10:45, cleaned pump wet well, went to Cascade & pumping stations & Skyway back at 5:00 P.M.
Nelson

5-12-64 Pumped sludge, washed down tanks, went with Willis to weld pipe line, then to Cascade and pump station back at 11:00 A.M. cleaned pump wet well, went to Skyway and pump station to cut in No 2 pressure line.
Nelson

5-13-64 Pumped sludge washed down tanks, went to Cascade & pump stations, back at 10:00 A.M. put the mower and cut the lawn, cleaned pump wet well
Nelson

5-14-64 Pumped sludge, washed down tanks, cleaned pump wet well, went to Cascade pump station and Skyway. back at 4:00 AM cleaned bio filter arms.
Nelson

KCSlip4 69244

SEA437335

4/1 5-15-64 Pumped sludge washed down tanks pumped out sludge pit, went to Cascade pumping station & sprayed back at 11:00 AM. Cleaned pump out well, went with Willis on pipe line run

5-16-64

4/1

5-17-64

5-18-64 Pumped sludge washed down tank, cleaned out wet well. Went to Cascade and sprayed fields back at 12 noon. Went with Willis in P.M.

5-19-64 Pumped sludge washed down tank, went to Skyway Cascade & sprayfield back at 11:00 A.M. Cleaned pump wet well, went to Skyway to pump out tanks

KCSlip4 69245

SEA437336

5-20-64 Pumped sludge, washed down
Wilson tanks, Cleaned pump and well
went to Cascade + pumping station
Back at 12:00 noon, dredged
No. 2 circulation pump went
to Skyway with Willis

5-21-64 Pumped sludge washed down
Wilson tanks, Boeing Engineers here
at 8:00 A.M. to see about hookup
of sewage line, went to pump
station back at 11:30 A.M.
Cleaned pump and well
went to Cascade + pump
station + Skyway.

5-22-64 Pumped sludge washed down
Wilson tanks, went to Skyway + pump
station + Cascade, back at
1:30 A.M. cleaned pump and well
pumped oil scum pit, went
to Skyway and pump station
1 hr. overtime.

5-23-64

5-24-64

KCSlip4 69246

SEA437337

4 5-25-44 Pumped sludge, washed
7 Wilson down tanks, went to pump
station and Skyway, then
to Cascade, back at 12 noon
went to Skyway + pump
station back at 3 P.M.

5-26-44 Pumped sludge, washed
Wilson down tanks, went to
Skyway and pump station
4 worked at pump station
7 with Wendy all day

5-27-44 Pumped sludge washed down
Wilson tank, pumped out scum
pit, work with Wendy
on pump at big pump
station, finished pump
out work here,

5-28-44 Pumped sludge washed
Wilson down tanks, worked
at pump station with Wendy

5-29-44 Pumped sludge washed
Wilson down tanks, went to
pump station + Skyway +
Cascade, back at 12:00
then to pump station
+ Skyway + Cascade

KCSlip4 69247

SEA437338

19 June 64

6-1-64 Wilson — Pumped sludge washed down tanks, No. 1 + 2 wet well pumps air locked (took them apart to let out air) went to Pump station + Cascade with Willis back at 10:45 AM, cleaned pump wet well made out monthly report.

6-2-64 Wilson — Worked at Skyway to pump out tanks, from 6-2-64 to 6-5-64

Worked at Bryn Mawr pumping tanks from 6-8-64 to 6-12-64

6-17-64

KCSlip4 69248

SEA437339