AI 937-9446

Wa 6906
no date
5f

take surface soil samples
(first 6") of old area
to demonstrate clean
closure

toe drain should be monitored

biannual monitoring
of toe drain

insp. Report
Whidbey Is
NAS

USEPA RCRA
3058159