(b) (6) [redacted] Science teacher

[redacted] 2 ballasts smoking a week apart
District risk assessor says its OK
told that PCBs are in the ballasts & they are being replaced
Kids were working in the area, bulbs had just been replaced
Not 100% sure on PCB status of both ballasts
- 1 is leaking brown goop, 1 is swollen looks ready to burst
↳ have now been replaced, post smoking incident
Smoking for 45 min before opening doors/windows, it's a carpeted room
They are testing the room - not sure how
Pregnant lady would like to get breast milk tested - how?
Really leaky windows

not sure if goo has been cleaned
Monroe School District

Geraldine Gardner
(b) (6) [redacted]

Craig Jones - ID Power

4/30/14 voicemails
Vered - check in on Phase I review
206-948-2821

Wendy ECL
5/5/14 VM
Luke WSU Energy Program - no PCB expertise but maybe collaborate
360-956-2043