(b) (6) [redacted] - Parent @ Sky Valley 5/3 6:06pm
How were air #s developed
(b) (6) [redacted]

5/16
Jay Collins NW Region ODEQ Haz waste & inspector
Sigard, OR will be generating PCB waste, want to know how to store
503-229-5008

5/24 voicemail
✓ Kendall - email from Mr. Mannix 312 353 1147
✓ mike - Notary - confirming 206-371-8755
John Wallace 206-616-5837
✓ mike PC Hotline 8202

Kendall → call w/ Devlin today or tomorrow
- if there are PCBs in soil it's unauth. disposal
- So want to see air & wipe sampling over time w/ seasons

360-804-2579

Call w/ Mr. Mannix - Kendall said we do want the plan by 25th
- if you can't address all the components of Michelle's email - hold off until you can get them - but submit the plan
- Kendall ⇒ we do need soil sampling and quarterly air and wipe sampling
- Mannix ⇒ annex has soil/dirt abutting building, but library/Pod building has none - only sidewalk/asphalt
- Kendall → even concrete dust would be a concern, but would be easier to address. <10ug/100cm² on conc.; <1mm on soil