4260127 Wolf Den 5/4/2010

40 CFR 280.41a Failure to monitor tanks at least every 30 days.

Provide copy of June and July 2010 release detection results to EPA

Due 7/20/2010

40 CFR 280.44 Failure to provide any release detection for underground piping.

Have certified technician test Automatic Line Leak Detectors. ~~Yes~~ (Pres) and either have product lines tested or perform 0.1 gallon / hour leak test with PLLD.

Provide copy of results to EPA

Due 6/4/2010

* Maintain and Keep copys of all release detection results for previous 12 months on file.

Further enforcement action if deemed necessary will come from EPA Region 10.

Philip A. Nenninger