STATE OF ILLINOIS

P.O. BOX 19276 SPRINGFIELD, ILLINOIS 62794-9276

State Form

EPA Form 8700-22 (Rev. 3-99)

FORM APPROVED OMB No. 2050-0039

PLEASE TYPE (Form designed to fit on one (12 pitch) typewriter)

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID Number

2. Page 1 of

3. Generator's Name and Mailing Address

Rutgers University Facilities Services
300 Dr. Martin Luther King Blvd
Newark, NJ 07102

4. *24 HOUR EMERGENCY AND SPILL ASSISTANCE NUMBER: 201-845-8255

5. Transporter 1 Company Name — US EPA ID Number

Clean Harbors Env Services Inc — N J D 0 8 3 7 2 0 1 3

7. Transporter 2 Company Name — US EPA ID Number

9. Designated Facility Name and Site Address — US EPA ID Number

Clean Harbors Services Inc
11800 South Stony Island Ave
Chicago, IL 60617

I L D 0 0 0 6 0 8 4 7 1

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
a. RQ, WASTE TOXIC SOLIDS, ORGANIC, N.O.S. (D008), 6.1, UN2811, II	001	DM	00160	P	D008
b. Waste Hydrofluoric acid, 8, UN1790, PGI	001	DF	00005	P	U134
c.					
d.					

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above in Item #14

15. Special Handling Instructions and Additional Information

NJDEP# 07259 DECAL# 0806 14 WO# C3481866

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: STEPHEN ETZOLD — Signature — Date: Month 10 Day 23 Year 02

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Matthew J. Schlesser — Signature — Date: Month 10 Day 23 Year 02

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name — Signature — Date: Month Day Year

GENERATOR

TRANSPORTER

FACILITY

Clean Harbors Environmental Services, Inc. 11800 South Stony Island Ave. Chicago, IL 60617

This form is authorized to require compliance in Illinois. Revised Statute, 1989, Chapter 111 1/2, Section 1004 and 1021, that this information be submitted to the Agency. Failure to provide this information may result in a civil penalty against the owner or operator not to exceed $25,000 per day of violation and criminal penalties for knowingly making false statements or representations, or knowingly transporting hazardous waste to a facility not in compliance with the Act, ranging from $50,000 per day of violation and imprisonment up to 5 years. This form has been approved by the Forms Management Center.

COPY 6. GENERATOR'S COPY

ACKNOWLEDGEMENT OF NOTIFICATION

OF HAZARDOUS WASTE ACTIVITY

12/17/90

This is to acknowledge that you have filed a Notification of Hazardous Waste Activity for the installation located at the address shown in the box below to comply with Section 3010 of the Resource Conservation and Recovery Act *(RCRA)*. Your EPA Identification Number for that installation appears in the box below. The EPA Identification Number must be included on all shipping manifests for transporting hazardous wastes; on all Annual Reports that generators of hazardous waste, and owners and operators of hazardous waste treatment, storage and disposal facilities must file with EPA; on all applications for a Federal Hazardous Waste Permit; and other hazardous waste management reports and documents required under Subtitle C of RCRA.

EPA I.D. NUMBER ->	NJD103803417
FACILITY NAME ->	RUTGERS THE STATE UNIVERSITY NJ
MAILING ADDRESS ->	BLDG 4127 KILMER RD DEPT REHS PISCATAWAY, NJ 08854
INSTALLATION ADDRESS ->	360 DR MARTIN LUTHER KING BLVD NEWARK, NJ 07102

EPA Form 8700-12AB (4-80)

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION II
26 FEDERAL PLAZA
NEW YORK, NEW YORK 10278

ATTN: PERMITS ADMINISTRATION BRANCH, ROOM 505

TO: DICKISON SUSAN COORD
RUTGERS THE STATE UNIVERSITY NJ
BLDG 4127 KILMER RD DEPT REHS
PISCATAWAY, NJ 08854

DRAFT

NJD 103 803 417

COMPLIANCE EVALUATION INSPECTION (CEI)

RUTGERS, THE STATE UNIVERSITY

NEWARK, NEW JERSEY

WORK ASSIGNMENT R02035

unpaid

follow-up during academic year

poss. chemistry lab was not inspected | closed for summer

See Dickson 908 932-2550

DRAFT

TABLE OF CONTENTS

Section		Page
1.0	INTRODUCTION	1
2.0	SITE BACKGROUND	1
2.1	Facility Description and Operations	1
2.2	Hazardous Waste Generation	2
3.0	ON-SITE OBSERVATIONS	2
3.1	Identification of Hazardous Waste	2
3.2	Examination of Paperwork	2
4.0	CONCLUSIONS	2

1.0 INTRODUCTION

In accordance with RCRA policy, hazardous waste transporters, generators, or treatment/storage/disposal (TSD) facilities are subject to Compliance Evaluation Inspections (CEIs), which address facility environmental concerns. The inspections are conducted to evaluate compliance with all applicable standards promulgated under 40 CFR Parts 262 through 268.

Under TES V Work Assignment R02035, CDM Federal Programs Corporation (CDM Federal) was contracted to conduct a CEI at the Rutgers State University facility in Newark, New Jersey. Michelle Stowers of Science Applications International Corporation (SAIC), a subcontractor to CDM Federal, visited Rutgers State University on August 13, 1993 to conduct the CEI. The information contained within this report was obtained from facility personnel and onsite records during the CEI, except where referenced otherwise.

The CEI was conducted using (as appropriate) the New Jersey Generator Inspection Report, General Site Inspection Form, Waste Minimization Checklist, Transporters Standards Checklist, Hazardous Waste Tank System Inspection Checklist, and the RCRA Land Disposal Restrictions Checklist. These documents were used as the basis for the inspection. All pertinent information is recorded in the inspection narrative. When necessary, relevant checklists were completed to provide additional detail when specific concerns were encountered during the inspection.

2.0 SITE BACKGROUND

2.1 FACILITY DESCRIPTION AND OPERATIONS

The Rutgers State University facility (Rutgers), a hazardous waste generator, is located at 360 Dr. Martin Luther King Boulevard in Newark, New Jersey. The EPA ID number of Rutgers is NJD 103803417.

The building at 360 Dr. Martin Luther King Boulevard appeared to contain educational classrooms and administrative offices. Because the educational facility was in summer session, and only limited background information was provided for this inspection, the inspector had difficulty locating anyone familiar with possible hazardous waste generation activities. The EPA-listed facility contact, Susan Dickison, was identified by onsite Rutgers personnel as a Health Safety Specialist, but she was not located at this facility location. Ms. Dickison was located in the central New Brunswick office. The

DRAFT

nearest Health Safety Specialist that onsite personnel could identify was Ellen Vastola, in Piscataway, New Jersey.

The inspector spoke with Dean Warshaver, whose office is in the 360 Dr. Martin Luther King building, regarding possible hazardous waste generation activities at this location. He was not aware of any hazardous waste activities, but when prodded, he admitted that there were chemistry laboratories at this location that might generate spent chemicals. Dean Warshaver would provide no additional information; he referred the inspector to Ellen Vastola. Ms. Vastola was not available on the day of the inspection. No additional information was available. An inspection could not be conducted.

2.2 HAZARDOUS WASTE GENERATION

The inspector could not locate anyone familiar with hazardous waste generation on the day of the inspection.

3.0 ON-SITE OBSERVATIONS

3.1 IDENTIFICATION OF HAZARDOUS WASTE

The inspector could not locate anyone familiar with hazardous waste generation on the day of the inspection.

3.2 EXAMINATION OF PAPERWORK

No paperwork was examined. The inspector could not locate anyone familiar with hazardous waste generation on the day of the inspection.

4.0 CONCLUSIONS

No one familiar with hazardous waste generation was available on the day of the inspection. In an effort to determine the status of the facility, it is recommended that EPA contact the Rutgers State University by telephone or by mail. Future inspections while school is in session may yield more favorable results.

THE STATE UNIVERSITY OF NEW JERSEY
RUTGERS

Department of Radiation and Environmental Health and Safety
Building 4127 • Kilmer Campus • Piscataway • New Jersey 08854 • 201/932-2550

REGION II
N.Y.
SEP 11 AM 10: 19
BRANCH

September 8, 1989

NJD 103 803 417

USEPA - Region II
Permits Administration Branch
26 Federal Plaza, Room 505
New York, NY 10278

Gentlemen:

Attention: Mr. David Abrinas

Enclosed are four (4) applications for additional EPA ID numbers for the following Rutgers University campuses: Cook Campus, Douglass Campus, and College Avenue Campus located in New Brunswick, NJ; also, Rutgers Newark Campus, located in Newark, NJ.

Rutgers University does not believe that they are required to get EPA ID numbers for each site; however, if Rutgers University does generate more than a "small quantity generator", EPA ID numbers will have been obtained to dispose of the material.

If there are any further questions, please contact me at 201-932-2550.

Sincerely yours,

Susan Dickison
Coordinator, Hazardous Waste

cc: Flair Hope-Mills
EPA Region II
Assistant Regional Council

Encs.
HG/epap

Please print or type with ELITE type (12 characters per inch) in the unshaded areas only

Form Approved. OMB No. 2050-0028. Expires 10-30-91
GSA No. 0246-EPA-OT

United States Environmental Protection Agency
Washington, DC 20460

EPA Notification of Hazardous Waste Activity

Please refer to the *Instructions for Filing Notification* before completing this form. The information requested here is required by law *(Section 3010 of the Resource Conservation and Recovery Act).*

For Official Use Only

Comments: FX

Installation's EPA ID Number	Approved	Date Received (yr. mo. day)
NJD 003803417		890911

I. Name of Installation

RUTGERS, THE STATE UNIVERSITY, NJ

II. Installation Mailing Address

Street or P.O. Box: BLDG 4127 KILMER Rd DEPT REHS

City or Town: PISCATAWAY | State: NJ | ZIP Code: 08854

III. Location of Installation

Street or Route Number: 360 DR. MARTIN LUTHER KING BLVD.

City or Town: NEWARK | State: NJ | ZIP Code: 07102

IV. Installation Contact

Name and Title *(last, first, and job title)*: DICKISON SUSAN COOR

Phone Number *(area code and number)*: 201 932 2550

V. Ownership

A. Name of Installation's Legal Owner: RUTGERS UNIVERSITY

B. Type of Ownership *(enter code)*: S

VI. Type of Regulated Waste Activity *(Mark 'X' in the appropriate boxes. Refer to instructions.)*

A. Hazardous Waste Activity

- [X] 1a. Generator
- [ ] 1b. Less than 1,000 kg/mo.
- [ ] 2. Transporter
- [ ] 3. Treater/Storer/Disposer
- [ ] 4. Underground Injection
- [ ] 5. Market or Burn Hazardous Waste Fuel *(enter 'X' and mark appropriate boxes below)*
  - [ ] a. Generator Marketing to Burner
  - [ ] b. Other Marketer
  - [ ] c. Burner

B. Used Oil Fuel Activities

- [ ] 6. Off-Specification Used Oil Fuel
  - [ ] a. Generator Marketing to Burner
  - [ ] b. Other Marketer
  - [ ] c. Burner
- [ ] 7. Specification Used Oil Fuel Marketer *(or On site Burner)* Who First Claims the Oil Meets the Specification

VII. Waste Fuel Burning: Type of Combustion Device *(enter 'X' in all appropriate boxes to indicate type of combustion device(s) in which hazardous waste fuel or off-specification used oil fuel is burned. See instructions for definitions of combustion devices.)*

[ ] A. Utility Boiler [ ] B. Industrial Boiler [ ] C. Industrial Furnace

VIII. Mode of Transportation *(transporters only – enter 'X' in the appropriate box(es)*

[ ] A. Air [ ] B. Rail [ ] C. Highway [ ] D. Water [ ] E. Other *(specify)*

IX. First or Subsequent Notification

Mark 'X' in the appropriate box to indicate whether this is your installation's first notification of hazardous waste activity or a subsequent notification. If this is not your first notification, enter your installation's EPA ID Number in the space provided below.

[ ] A. First Notification [X] B. Subsequent Notification *(complete item C)*

C. Installation's EPA ID Number: NJD000582387

EPA Form 8700-12 (Rev. 10-88) Previous edition is obsolete.

Continue on reverse

NOTE Photocopy this page before completing if you have more than 26 wastes to list

Form Approved OMB No 158 SEC

EPA I.D NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W [redacted] 1	W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	D001	15,000	P	S01	
2	D002	7,000	P	S01	
3	D003	200	P	S01	
4	D004	10	P	S01	
5	D005	15	P	S01	
6	D006	2,000	P	S01	
7	D007	15	P	S01	
8	D008	200	P	S01	
9	D009	200	P	S01	
10	D010	15	P	S01	
11	D011	50	P	S01	
12	D012	100	P	S01	
13	D013	50	P	S01	
14	D014	10	P	S01	
15	D015	10	P	S01	
16	D016	10	P	S01	
17	D017	5	P	S01	
18	F001	450	P	S01	
19	F002	1800	P	S01	
20	F003	1800	P	S01	
21	F004	200	P	S01	
22	F005	8,100	P	S01	
23	F006	450	P	S01	
24	F007	100	P	S01	
25	F008	100	P	S01	
26	F009	100	P	S01	

EPA Form 3510-3 (6-80)

CONTINUE ON F

(enter "A" "B" "C" etc behind the "3" to identify photocopied pages)

NOTE Photocopy this page before completing if you have more than 26 wastes to list. Form Approved OMB No. 158 S

EPA I.D. NUMBER (enter from page 1)		FOR OFFICIAL USE ONLY		
W [redacted]	1	W DUP	2	DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1)
1	F010	50	P	S01	
2	F011	50	P	S01	
3	F012	50	P	S01	
4	F014	50	P	S01	
5	F015	50	P	S01	
6	F019	50	P	S01	
7	F020	50	P	S01	
8	F021	25	P	S01	
9	F022	25	P	S01	
10	F023	25	P	S01	
11	F024	50	P	S01	
12	F026	25	P	S01	
13	F027	50	P	S01	
14	F028	50	P	S01	
15	X721	5,400	P	S01	
16	X722	3,000	P	S01	
17	X723	3,000	P	S01	
18	X724	3,000	P	S01	
19	X725	1,000	P	S01	
20	X726	1,000	P	S01	
21	X727	2350	P	S01	
22	X728	1800	P	S01	
23	X940	8,000	P	S01	
24	K001	50	P	S01	
25	K002	50	P	S01	
26	K003	50	P	S01	

EPA Form 3510-3 (6-80)

CONTINUE ON

(enter "A", "B", "C", etc. behind the "3" to identify photocopies)

NOTE Photocopy this page before completing [illegible]

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY	
W [redacted] 1	W DUP	2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D)
1	K005	50	P	S01	
2	K006	50	P	S01	
3	K007	50	P	S01	
4	K008	50	P	S01	
5	K009	50	P	S01	
6	K010	50	P	S01	
7	K011	50	P	S01	
8	K013	50	P	S01	
9	K014	50	P	S01	
10	K015	50	P	S01	
11	K016	50	P	S01	
12	K017	50	P	S01	
13	K018	50	P	S01	
14	K019	50	P	S01	
15	K020	50	P	S01	
16	K021	50	P	S01	
17	K022	50	P	S01	
18	K023	50	P	S01	
19	K024	50	P	S01	
20	K093	50	P	S01	
21	K094	50	P	S01	
22	K025	50	P	S01	
23	K026	50	P	S01	
24	K027	50	P	S01	
25	K028	50	P	S01	
26	K029	50	P	S01	

EPA Form 3510-3 (6-80)

CONTINUE C

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

EPA I.D. NUMBER (enter from page 1)

W [redacted] 1

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (If a code is not entered in D.1)
1	K095	50	P	S01	
2	K096	50	P	S01	
3	K030	50	P	S01	
4	K83	50	P	S01	
5	K103	50	P	S01	
6	K104	50	P	S01	
7	K085	50	P	S01	
8	K105	50	P	S01	
9	K111	50	P	S01	
10	K112	50	P	S01	
11	K113	50	P	S01	
12	K114	50	P	S01	
13	K115	50	P	S01	
14	K116	50	P	S01	
15	K031	50	P	S01	
16	K032	50	P	S01	
17	K033	50	P	S01	
18	K034	50	P	S01	
19	K097	50	P	S01	
20	K035	50	P	S01	
21	K036	50	P	S01	
22	K037	50	P	S01	
23	K038	50	P	S01	
24	K039	50	P	S01	
25	K040	50	P	S01	
26	K041	50	P	S01	

EPA Form 3510-3 (6-80)

CONTINUE O

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

NOTE Photocopy this page before completing if you have more than 26 wastes to list.

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W [redacted] 1	W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D1)
1	K098	50	P	S01				
2	K042	50	P	S01				
3	K043	50	P	S01				
4	K099	50	P	S01				
5	K044	50	P	S01				
6	K045	50	P	S01				
7	K046	50	P	S01				
8	K047	50	P	S01				
9	K048	50	P	S01				
10	K049	50	P	S01				
11	K050	50	P	S01				
12	K051	50	P	S01				
13	K052	50	P	S01				
14	K053	50	P	S01				
15	K054	50	P	S01				
16	K055	50	P	S01				
17	K056	50	P	S01				
18	K057	50	P	S01				
19	K058	50	P	S01				
20	K059	50	P	S01				
21	K061	50	P	S01				
22	K062	50	P	S01				
23	K066	50	P	S01				
24	K067	50	P	S01				
25	K068	50	P	S01				
26	K069	50	P	S01				

NOTE: Photocopy this page before completing if you have more than 26 wastes to list. Form Approved OMB No. 158

EPA I.D. NUMBER (enter from page 1)		FOR OFFICIAL USE ONLY	
W [redacted]	1	W DUP	2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1)
1	K100	50	P	S01	
2	K071	50	P	S01	
3	K073	50	P	S01	
4	K074	50	P	S01	
5	K106	50	P	S01	
6	K086	50	P	S01	
7	K084	50	P	S01	
8	K101	50	P	S01	
9	K102	50	P	S01	
10	K087	50	P	S01	
11	K060	50	P	S01	
12	P066	1	P	S01	
13	P001	1	P	S01	
14	P002	1	P	S01	
15	P003	5	P	S01	
16	P070	1	P	S01	
17	P004	5	P	S01	
18	P005	5	P	S01	
19	P006	5	P	S01	
20	P007	1	P	S01	
21	P008	1	P	S01	
22	P009	1	P	S01	
23	P119	1	P	S01	
24	P010	5	P	S01	
25	P012	1	P	S01	
26	P011	1	P	S01	

EPA Form 3510-3 (6-80)

CONTINUE ON REVERSE

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages.)

NOTE: Photocopy this page before completing ...

EPA I.D. NUMBER (enter from page 1)		FOR OFFICIAL USE ONLY		
W [redacted]	1	W DUP	2	DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D)
1	P011	1	P	S01	
2	P012	1	P	S01	
3	P038	1	P	S01	
4	P054	1	P	S01	
5	P013	5	P	S01	
6	P024	5	P	S01	
7	P077	1	P	S01	
8	P028	5	P	S01	
9	P042	5	P	S01	
10	P014	5	P	S01	
11	P028	5	P	S01	
12	P015	5	P	S01	
13	P016	5	P	S01	
14	P017	5	P	S01	
15	P018	1	P	S01	
16	P021	10	P	S01	
17	P123	1	P	S01	
18	P103	1	P	S01	
19	P022	5	P	S01	
20	P095	5	P	S01	
21	P033	1	P	S01	
22	P023	1	P	S01	
23	P024	1	P	S01	
24	P026	1	P	S01	
25	P027	1	P	S01	
26	P029	5	P	S01	

EPA Form 3510-3 (6-80)

CONTINUE O

(enter "A", "B", "C" etc. behind the "3" to identify photocopied pages)

NOTE Photocopy this page before completing if you have more than 26 wastes to list.

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W [redacted]	W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1)
1	P030	5	P	S01	
2	P031	1	P	S01	
3	P033	1	P	S01	
4	P036	1	P	S01	
5	P037	1	P	S01	
6	P038	1	P	S01	
7	P039	1	P	S01	
8	P041	1	P	S01	
9	P040	1	P	S01	
10	P043	1	P	S01	
11	P044	1	P	S01	
12	P045	1	P	S01	
13	P071	5	P	S01	
14	P082	1	P	S01	
15	P046	1	P	S01	
16	P047	1	P	S01	
17	P034	5	P	S01	
18	P048	5	P	S01	
19	P020	1	P	S01	
20	P085	1	P	S01	
21	P039	1	P	S01	
22	P049	1	P	S01	
23	P109	1	P	S01	
24	P050	1	P	S01	
25	P058	1	P	S01	
26	P051	5	P	S01	

EPA Form 3510-3 (6-80)

CONTINUE

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

NOTE Photocopy this page before completing if you have more than 26 wastes to list.

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W [redacted]	W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (If a code is not entered in D1)
1	P042	1	P	S01	
2	P046	1	P	S01	
3	P084	1	P	S01	
4	P101	1	P	S01	
5	P054	5	P	S01	
6	P097	1	P	S01	
7	P056	5	P	S01	
8	P057	5	P	S01	
9	P058	5	P	S01	
10	P065	1	P	S01	
11	P059	1	P	S01	
12	P051	1	P	S01	
13	P037	1	P	S01	
14	P060	1	P	S01	
15	P004	1	P	S01	
16	P060	1	P	S01	
17	P062	1	P	S01	
18	P111	1	P	S01	
19	P068	1	P	S01	
20	P063	1	P	S01	
21	P063	5	P	S01	
22	P096	1	P	S01	
23	P064	1	P	S01	
24	P007	1	P	S01	
25	P092	1	P	S01	
26	P065	1	P	S01	

EPA Form 3510-3 (6-80) CONTINUE ON REVERSE

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages.)

NOTE: Photocopy this page before completing [illegible]

EPA I.D. NUMBER (enter from page 1)		FOR OFFICIAL USE ONLY		
W [redacted]	1	W DUP	2	DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D)
1	P016	1	P	S01	
2	P112	1	P	S01	
3	P118	5	P	S01	
4	P059	1	P	S01	
5	P066	1	P	S01	
6	P067	1	P	S01	
7	P068	1	P	S01	
8	P064	5	P	S01	
9	P069	1	P	S01	
10	P071	1	P	S01	
11	P072	1	P	S01	
12	P073	5	P	S01	
13	P074	5	P	S01	
14	P074	5	P	S01	
15	P073	5	P	S01	
16	P075	5	P	S01	
17	P076	5	P	S01	
18	P078	5	P	S01	
19	P081	5	P	S01	
20	P082	1	P	S01	
21	P084	1	P	S01	
22	P050	1	P	S01	
23	P085	1	P	S01	
24	P087	5	P	S01	
25	P087	5	P	S01	
26	P088	5	P	S01	

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-S800

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W [redacted] 7 1	W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	P089	1	P	S01	
2	P034	10	P	S01	
3	P048	5	P	S01	
4	P047	5	P	S01	
5	P020	5	P	S01	
6	P099	5	P	S01	
7	P036	5	P	S01	
8	P092	5	P	S01	
9	P093	1	P	S01	
10	P094	1	P	S01	
11	P095	1	P	S01	
12	P096	1	P	S01	
13	P041	5	P	S01	
14	P044	1	P	S01	
15	P043	5	P	S01	
16	P094	1	P	S01	
17	P089	1	P	S01	
18	P040	1	P	S01	
19	P097	1	P	S01	
20	P111	1	P	S01	
21	P098	5	P	S01	
22	P099	5	P	S01	
23	P070	1	P	S01	
24	P101	1	P	S01	
25	P027	1	P	S01	
26	P069	1	P	S01	

EPA Form 3510-3 (6-80)

CONTINUE ON R

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

Form Approved OMB No

EPA I.D. NUMBER (enter from page 1): W A [redacted] 7 1

FOR OFFICIAL USE ONLY: W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIP (If a code is not entered	
1	P081	1	P	S01					
2	P017	5	P	S01					
3	P102	1	P	S01					
4	P003	1	P	S01					
5	P005	1	P	S01					
6	P067	1	P	S01					
7	P102	1	P	S01					
8	P008	1	P	S01					
9	P075	5	P	S01					
10	P111	5	P	S01					
11	P103	1	P	S01					
12	P104	5	P	S01					
13	P105	5	P	S01					
14	P106	5	P	S01					
15	P107	1	P	S01					
16	P108	1	P	S01					
17	P018	1	P	S01					
18	P108	1	P	S01					
19	P115	5	P	S01					
20	P109	1	P	S01					
21	P110	1	P	S01					
22	P111	1	P	S01					
23	P112	5	P	S01					
24	P062	5	P	S01					
25	P113	5	P	S01					
26	P113	5	P	S01					

EPA Form 3510-3 (6-80)

CONTINUE

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

EPA I.D. NUMBER (enter from page 1): W [redacted] 1

FOR OFFICIAL USE ONLY: W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (If a code is not entered in
1	P114	1	P	S01	
2	P115	1	P	S01	
3	P045	1	P	S01	
4	P049	1	P	S01	
5	P014	1	P	S01	
6	P116	1	P	S01	
7	P026	1	P	S01	
8	P072	1	P	S01	
9	P093	1	P	S01	
10	P123	1	P	S01	
11	P118	1	P	S01	
12	P119	5	P	S01	
13	P120	5	P	S01	
14	P120	5	P	S01	
15	P001	1	P	S01	
16	P121	5	P	S01	
17	P122	1	P	S01	
18	U001	20	P	S01	
19	U034	20	P	S01	
20	U187	10	P	S01	
21	U005	10	P	S01	
22	U112	50	P	S01	
23	U144	50	P	S01	
24	U214	50	P	S01	
25	U248	5	P	S01	
26	U328	20	P	S01	

EPA Form 3510-3 (6-80)

CONTINUE

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages.)

Form Approved OMB No

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W [redacted] 7 1	W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered)
1	U353	20	P	S01	
2	U002	50	P	S01	
3	U003	50	P	S01	
4	U004	20	P	S01	
5	U005	20	P	S01	
6	U006	20	P	S01	
7	U007	50	P	S01	
8	U008	40	P	S01	
9	U150	40	P	S01	
10	U011	10	P	S01	
11	U012	40	P	S01	
12	U014	10	P	S01	
13	U015	10	P	S01	
14	U010	10	P	S01	
15	U157	10	P	S01	
16	U016	10	P	S01	
17	U016	10	P	S01	
18	U017	20	P	S01	
19	U018	10	P	S01	
20	U018	10	P	S01	
21	U094	10	P	S01	
22	U012	20	P	S01	
23	U014	20	P	S01	
24	U049	40	P	S01	
25	U093	20	P	S01	
26	U158	20	P	S01	

EPA Form 3510-3 (6-80)

CONTINUE

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

Form Approved OMB No

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W A [redacted] 7	W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIP (if a code is not entered)
1	U222	20	P	S01	
2	U181	10	P	S01	
3	U019	75	P	S01	
4	U038	20	P	S01	
5	U030	20	P	S01	
6	U037	50	P	S01	
7	U190	20	P	S01	
8	U028	10	P	S01	
9	U069	10	P	S01	
10	U088	10	P	S01	
11	U102	10	P	S01	
12	U107	10	P	S01	
13	U070	10	P	S01	
14	U071	10	P	S01	
15	U072	10	P	S01	
16	U017	10	P	S01	
17	U223	5	P	S01	
18	U239	10	P	S01	
19	U201	5	P	S01	
20	U127	10	P	S01	
21	U056	10	P	S01	
22	U188	10	P	S01	
23	U220	10	P	S01	
24	U165	10	P	S01	
25	U166	10	P	S01	
26	U203	5	P	S01	

EPA Form 3510-3 (6-80)

CONTINUE

(enter "A", "B", "C", etc. behind the "3" to identify photocopies of ...)

Form Approved OMB No. 1

EPA I.D. NUMBER (enter from page 1): W [redacted] 7 | 1

FOR OFFICIAL USE ONLY: W DUP | 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPT (If a code is not entered in
1	U114	5	P	S01				
2	U090	5	P	S01				
3	U055	20	P	S01				
4	U169	20	P	S01				
5	U183	10	P	S01				
6	U185	10	P	S01				
7	U020	5	P	S01				
8	U020	5	P	S01				
9	U207	10	P	S01				
10	U023	10	P	S01				
11	U234	10	P	S01				
12	U021	20	P	S01				
13	U202	10	P	S01				
14	U120	10	P	S01				
15	U022	20	P	S01				
16	U022	20	P	S01				
17	U197	10	P	S01				
18	U023	10	P	S01				
19	U050	10	P	S01				
20	U085	5	P	S01				
21	U021	5	P	S01				
22	U073	5	P	S01				
23	U091	5	P	S01				
24	U095	5	P	S01				
25	U024	10	P	S01				
26	U027	20	P	S01				

Form Approved OMB No

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W [redacted] 1	W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIP (if a code is not entered)
1	U244	10	P	S01	
2	U028	10	P	S01	
3	U246	20	P	S01	
4	U225	10	P	S01	
5	U030	20	P	S01	
6	U128	10	P	S01	
7	U172	10	P	S01	
8	U035	10	P	S01	
9	U031	75	P	S01	
10	U159	40	P	S01	
11	U160	20	P	S01	
12	U053	20	P	S01	
13	U074	10	P	S01	
14	U031	40	P	S01	
15	U136	10	P	S01	
16	U032	20	P	S01	
17	U238	10	P	S01	
18	U178	10	P	S01	
19	U176	10	P	S01	
20	U177	10	P	S01	
21	U219	5	P	S01	
22	U097	5	P	S01	
23	U215	40	P	S01	
24	U156	10	P	S01	
25	U033	10	P	S01	
26	U211	50	P	S01	

EPA Form 3510-3 (6-80)

CONTINUE

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

Form Approved OMB No 1

EPA I.D. NUMBER (enter from page 1)

W [redacted]

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPT (If a code is not entered in
1	U033	10	P	S01				
2	U034	5	P	S01				
3	U035	5	P	S01				
4	U036	10	P	S01				
5	U026	5	P	S01				
6	U037	20	P	S01				
7	U039	5	P	S01				
8	U041	5	P	S01				
9	U042	1	P	S01				
10	U044	50	P	S01				
11	U046	40	P	S01				
12	U047	1	P	S01				
13	U048	5	P	S01				
14	U049	5	P	S01				
15	U032	40	P	S01				
16	U050	5	P	S01				
17	U051	10	P	S01				
18	U052	40	P	S01				
19	U052	20	P	S01				
20	U053	5	P	S01				
21	U055	5	P	S01				
22	U246	10	P	S01				
23	U197	20	P	S01				
24	U056	75	P	S01				
25	U057	75	P	S01				
26	U136	5	P	S01				

EPA Form 3510-3 (6-80)

CONTINUE O

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

EPA I.D. NUMBER (enter from page 1) W [redacted] 1

FOR OFFICIAL USE ONLY W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				2. PROCESS DESCRIPTION (if a code is not entered above)
1	U058	5	P	S01				
2	U240	5	P	S01				
3	U059	5	P	S01				
4	U142	1	P	S01				
5	U062	5	P	S01				
6	U133	5	P	S01				
7	U221	10	P	S01				
8	U063	5	P	S01				
9	U063	5	P	S01				
10	U064	10	P	S01				
11	U064	10	P	S01				
12	U066	20	P	S01				
13	U069	20	P	S01				
14	U062	10	P	S01				
15	U070	40	P	S01				
16	U071	40	P	S01				
17	U072	40	P	S01				
18	U073	40	P	S01				
19	U074	20	P	S01				
20	U075	20	P	S01				
21	U192	10	P	S01				
22	U060	20	P	S01				
23	U061	20	P	S01				
24	U078	20	P	S01				
25	U079	20	P	S01				
26	U022	10	P	S01				

EPA Form 3510-3 (6-80)

CONTINUE

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No 158 S8

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W [redacted] 1	W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	U060	50	P	S01				
2	U061	200	P	S01				
3	U081	20	P	S01				
4	U082	10	P	S01				
5	U240	10	P	S01				
6	U083	10	P	S01				
7	U084	10	P	S01				
8	U085	10	P	S01				
9	U108	10	P	S01				
10	U086	10	P	S01				
11	U087	10	P	S01				
12	U088	10	P	S01				
13	U089	5	P	S01				
14	U148	5	P	S01				
15	U090	5	P	S01				
16	U091	10	P	S01				
17	U092	10	P	S01				
18	U093	10	P	S01				
19	U094	5	P	S01				
20	U095	5	P	S01				
21	U096	1	P	S01				
22	U097	5	P	S01				
23	U098	5	P	S01				
24	U099	5	P	S01				
25	U101	5	P	S01				
26	U102	5	P	S01				

EPA I.D. NUMBER (enter from page 1)

W [redacted] 1

FOR OFFICIAL USE ONLY

W DUP ? DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered above)
1	U103	5	P	S01				
2	U105	5	P	S01				
3	U106	5	P	S01				
4	U107	1	P	S01				
5	U108	20	P	S01				
6	U109	1	P	S01				
7	U110	5	P	S01				
8	U111	1	P	S01				
9	U174	1	P	S01				
10	U067	10	P	S01				
11	U076	10	P	S01				
12	U077	10	P	S01				
13	U114	1	P	S01				
14	U131	1	P	S01				
15	U024	5	P	S01				
16	U003	5	P	S01				
17	U117	5	P	S01				
18	U025	1	P	S01				
19	U184	5	P	S01				
20	U208	5	P	S01				
21	U209	5	P	S01				
22	U218	5	P	S01				
23	U227	10	P	S01				
24	U043	10	P	S01				
25	U042	5	P	S01				
26	U078	20	P	S01				

EPA Form 3510-3 (6-80)

CONTINU

(enter "A", "B", "C", etc. behind the "3" to identify ...)

EPA I.D. NUMBER (enter from page 1) W [redacted]

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				2. PROCESS DESCRIP (if a code is not entered ab
1	U079	1	P	S01				
2	U210	5	P	S01				
3	U173	5	P	S01				
4	U004	5	P	S01				
5	U006	5	P	S01				
6	U112	100	P	S01				
7	U113	40	P	S01				
8	U238	20	P	S01				
9	U038	10	P	S01				
10	U114	5	P	S01				
11	U067	10	P	S01				
12	U077	10	P	S01				
13	U115	5	P	S01				
14	U116	5	P	S01				
15	U117	20	P	S01				
16	U076	5	P	S01				
17	U118	5	P	S01				
18	U119	10	P	S01				
19	U139	5	P	S01				
20	U120	5	P	S01				
21	U122	200	P	S01				
22	U123	40	P	S01				
23	U124	20	P	S01				
24	U125	5	P	S01				
25	U147	5	P	S01				
26	U213	20	P	S01				

EPA Form 3510-3 (6-80) CONTINU

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

EPA I.D. NUMBER (enter from page 1)

W [redacted] 1

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered above)
1	U125	40	P	S01	
2	U124	40	P	S01	
3	U206	5	P	S01	
4	U126	5	P	S01	
5	U163	20	P	S01	
6	U127	5	P	S01	
7	U128	5	P	S01	
8	U129	10	P	S01	
9	U130	10	P	S01	
10	U131	10	P	S01	
11	U132	5	P	S01	
12	U243	5	P	S01	
13	U133	5	P	S01	
14	U086	5	P	S01	
15	U098	5	P	S01	
16	U099	5	P	S01	
17	U109	5	P	S01	
18	U134	50	P	S01	
19	U134	5	P	S01	
20	U135	10	P	S01	
21	U096	5	P	S01	
22	U136	5	P	S01	
23	U116	5	P	S01	
24	U137	5	P	S01	
25	U139	5	P	S01	
26	U140	50	P	S01	

EPA Form 3510-3 (6-80)

CONTINUE

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

EPA I.D. NUMBER (enter from page 1)

W A [redacted] 1

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				2. PROCESS DESCRIP (if a code is not entered a
1	U141	5	P	S01				
2	U142	5	P	S01				
3	U143	5	P	S01				
4	U144	10	P	S01				
5	U145	10	P	S01				
6	U146	10	P	S01				
7	U129	5	P	S01				
8	U147	20	P	S01				
9	U148	10	P	S01				
10	U149	5	P	S01				
11	U150	5	P	S01				
12	U151	50	P	S01				
13	U152	5	P	S01				
14	U092	10	P	S01				
15	U029	20	P	S01				
16	U045	20	P	S01				
17	U046	10	P	S01				
18	U068	10	P	S01				
19	U080	10	P	S01				
20	U075	10	P	S01				
21	U138	10	P	S01				
22	U119	5	P	S01				
23	U211	10	P	S01				
24	U121	5	P	S01				
25	U123	5	P	S01				
26	U036	5	P	S01				

EPA Form 3510-3 (6-80)

CONTINU

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

EPA I.D. NUMBER (enter from page 1)

W [redacted] 1

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPT (if a code is not entered in
1	U154	50	P	S01				
2	U247	5	P	S01				
3	U155	5	P	S01				
4	U154	50	P	S01				
5	U029	5	P	S01				
6	U186	5	P	S01				
7	U045	10	P	S01				
8	U156	5	P	S01				
9	U226	10	P	S01				
10	U157	5	P	S01				
11	U158	5	P	S01				
12	U132	5	P	S01				
13	U068	40	P	S01				
14	U080	40	P	S01				
15	U122	10	P	S01				
16	U159	50	P	S01				
17	U160	1	P	S01				
18	U138	5	P	S01				
19	U161	40	P	S01				
20	U162	20	P	S01				
21	U163	20	P	S01				
22	U164	5	P	S01				
23	U010	5	P	S01				
24	U059	5	P	S01				
25	U165	10	P	S01				
26	U047	10	P	S01				

EPA Form 3510-3 (6-80)

CONTINU

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W [redacted]	W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIP (if a code is not entered	
1	U166	5	P	S01		
2	U236	5	P	S01		
3	U166	5	P	S01		
4	U167	5	P	S01		
5	U168	5	P	S01		
6	U167	5	P	S01		
7	U168	5	P	S01		
8	U026	5	P	S01		
9	U169	20	P	S01		
10	U170	10	P	S01		
11	U171	10	P	S01		
12	U172	5	P	S01		
13	U173	5	P	S01		
14	U174	5	P	S01		
15	U111	5	P	S01		
16	U176	5	P	S01		
17	U177	5	P	S01		
18	U178	5	P	S01		
19	U179	5	P	S01		
20	U180	5	P	S01		
21	U181	5	P	S01		
22	U193	5	P	S01		
23	U058	5	P	S01		
24	U115	5	P	S01		
25	U041	5	P	S01		
26	U182	5	P	S01		

EPA Form 3510-3 (6-80)

CONTINU

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

EPA I.D. NUMBER (enter from page 1)

W [redacted] 1

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPT (if a code is not entered in
1	U183	5	P	S01				
2	U184	5	P	S01				
3	U185	5	P	S01				
4	U186	5	P	S01				
5	U187	10	P	S01				
6	U188	100	P	S01				
7	U048	25	P	S01				
8	U039	25	P	S01				
9	U081	5	P	S01				
10	U082	5	P	S01				
11	U101	5	P	S01				
12	U170	5	P	S01				
13	U242	5	P	S01				
14	U137	5	P	S01				
15	U145	50	P	S01				
16	U087	5	P	S01				
17	U189	5	P	S01				
18	U190	5	P	S01				
19	U191	5	P	S01				
20	U192	10	P	S01				
21	U194	10	P	S01				
22	U110	5	P	S01				
23	U066	5	P	S01				
24	U149	10	P	S01				
25	U171	10	P	S01				
26	U027	5	P	S01				

EPA I.D. NUMBER (enter from page 1)

W [redacted] 7 1

FOR OFFICIAL USE ONLY

W DUP ? DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				2. PROCESS DESCRIPTION (if a code is not entered above)
1	U193	5	P	S01				
2	U235	10	P	S01				
3	U126	10	P	S01				
4	U140	10	P	S01				
5	U002	40	P	S01				
6	U007	40	P	S01				
7	U084	10	P	S01				
8	U243	10	P	S01				
9	U009	10	P	S01				
10	U152	10	P	S01				
11	U008	40	P	S01				
12	U113	40	P	S01				
13	U118	40	P	S01				
14	U162	40	P	S01				
15	U194	25	P	S01				
16	U083	40	P	S01				
17	U196	100	P	S01				
18	U155	10	P	S01				
19	U179	10	P	S01				
20	U191	10	P	S01				
21	U164	10	P	S01				
22	U180	5	P	S01				
23	U200	5	P	S01				
24	U201	40	P	S01				
25	U202	5	P	S01				
26	U203	5	P	S01				

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W [redacted] 1	W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered)
1	U204	40	P	S01				
2	U205	5	P	S01				
3	U015	5	P	S01				
4	U089	5	P	S01				
5	U206	5	P	S01				
6	U135	5	P	S01				
7	U103	200	P	S01				
8	U189	5	P	S01				
9	U205	5	P	S01				
10	U207	5	P	S01				
11	U208	5	P	S01				
12	U209	5	P	S01				
13	U210	5	P	S01				
14	U213	50	P	S01				
15	U214	5	P	S01				
16	U215	5	P	S01				
17	U216	5	P	S01				
18	U217	5	P	S01				
19	U218	10	P	S01				
20	U153	10	P	S01				
21	U219	10	P	S01				
22	U244	10	P	S01				
23	U220	3700	P	S01				
24	U221	10	P	S01				
25	U223	25	P	S01				
26	U222	5	P	S01				

EPA I.D. NUMBER (enter from page 1): W M [redacted] 7 1

FOR OFFICIAL USE ONLY: W DUP ? DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIP. (if a code is not entered)
1	U328	10	P	S01	
2	U353	10	P	S01	
3	U011	5	P	S01	
4	U226	80	P	S01	
5	U227	80	P	S01	
6	U228	80	P	S01	
7	U121	10	P	S01	
8	U234	5	P	S01	
9	U182	5	P	S01	
10	U235	5	P	S01	
11	U236	5	P	S01	
12	U237	5	P	S01	
13	U043	10	P	S01	
14	U239	80	P	S01	
15	U200	5	P	S01	
16	U248	5	P	S01	
17	U249	5	P	S01	
18	C102	5	P	S01	
19	C103	10	P	S01	
20	C463	10	P	S01	
21	C104	5	P	S01	
22	C105	10	P	S01	
23	C106	10	P	S01	
24	C107	5	P	S01	
25	C108	10	P	S01	
26	C109	25	P	S01	

EPA I.D. NUMBER (enter from page 1) W [redacted] 1

FOR OFFICIAL USE ONLY W DUP ? DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPT (if a code is not entered in
1	C110	25	P	S01	
2	C115	100	P	S01	
3	C112	50	P	S01	
4	C113	10	P	S01	
5	C114	5	P	S01	
6	C115	5	P	S01	
7	C116	5	P	S01	
8	C117	5	P	S01	
9	C118	5	P	S01	
10	C119	5	P	S01	
11	C120	25	P	S01	
12	C121	10	P	S01	
13	C122	5	P	S01	
14	C123	5	P	S01	
15	C124	5	P	S01	
16	C125	5	P	S01	
17	C126	5	P	S01	
18	C127	5	P	S01	
19	C128	5	P	S01	
20	C129	10	P	S01	
21	C130	5	P	S01	
22	C131	5	P	S01	
23	C132	5	P	S01	
24	C133	75	P	S01	
25	C464	5	P	S01	
26	C500	5	P	S01	

(enter "A", "B", "C", etc. behind the "1" to identify

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W [redacted] 1	W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered)
1	C501	5	P	S01	
2	C134	5	P	S01	
3	C135	5	P	S01	
4	C136	20	P	S01	
5	C138	10	P	S01	
6	C139	10	P	S01	
7	C140	20	P	S01	
8	C141	5	P	S01	
9	C142	20	P	S01	
10	C143	5	P	S01	
11	C144	5	P	S01	
12	C145	5	P	S01	
13	C146	5	P	S01	
14	C147	5	P	S01	
15	C148	5	P	S01	
16	C149	10	P	S01	
17	C150	10	P	S01	
18	C151	10	P	S01	
19	C152	5	P	S01	
20	C153	5	P	S01	
21	C154	5	P	S01	
22	C465	5	P	S01	
23	C156	5	P	S01	
24	C157	2,000	P	S01	
25	C158	5	P	S01	
26	C159	5	P	S01	

EPA I.D. NUMBER (enter from page 1)		FOR OFFICIAL USE ONLY	
W [redacted]	1	W DUP	2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in
1	C160	5	P	S01				
2	C466	5	P	S01				
3	C161	5	P	S01				
4	C162	40	P	S01				
5	C163	80	P	S01				
6	C464	300	P	S01				
7	C467	40	P	S01				
8	C165	25	P	S01				
9	C166	80	P	S01				
10	C167	40	P	S01				
11	C168	5	P	S01				
12	C169	5	P	S01				
13	C170	40	P	S01				
14	C171	5	P	S01				
15	C172	5	P	S01				
16	C173	5	P	S01				
17	C174	5	P	S01				
18	C176	50	P	S01				
19	C177	25	P	S01				
20	C178	5	P	S01				
21	C179	5	P	S01				
22	C180	5	P	S01				
23	C181	5	P	S01				
24	C182	5	P	S01				
25	C497	5	P	S01				
26	C183	5	P	S01				

EPA Form 3510-3 (6-80)

CONTINU

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

EPA I.D. NUMBER (enter from page 1) W [redacted] 1

FOR OFFICIAL USE ONLY W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRI (if a code is not entered
1	C184	10	P	S01				
2	C185	5	P	S01				
3	C186	5	P	S01				
4	C187	1	P	S01				
5	C468	10	P	S01				
6	C188	10	P	S01				
7	C189	5	P	S01				
8	C190	15	P	S01				
9	C191	5	P	S01				
10	C192	5	P	S01				
11	C193	5	P	S01				
12	C194	5	P	S01				
13	C195	5	P	S01				
14	C196	5	P	S01				
15	C197	5	P	S01				
16	C198	50	P	S01				
17	C199	50	P	S01				
18	C200	200	P	S01				
19	C201	5	P	S01				
20	C202	5	P	S01				
21	C203	5	P	S01				
22	C204	5	P	S01				
23	C205	5	P	S01				
24	C206	5	P	S01				
25	C207	5	P	S01				
26	C208	5	P	S01				

EPA I.D. NUMBER (enter from page 1)

W [redacted] 1

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D(1))
1	C209	5	P	S01				
2	C210	5	P	S01				
3	C211	5	P	S01				
4	C212	5	P	S01				
5	C492	5	P	S01				
6	C493	5	P	S01				
7	C494	5	P	S01				
8	C213	40	P	S01				
9	C470	5	P	S01				
10	C216	40	P	S01				
11	C215	40	P	S01				
12	C217	25	P	S01				
13	C218	40	P	S01				
14	C220	40	P	S01				
15	C221	40	P	S01				
16	C222	25	P	S01				
17	C223	5	P	S01				
18	C224	5	P	S01				
19	C225	5	P	S01				
20	C226	5	P	S01				
21	C227	5	P	S01				
22	C228	5	P	S01				
23	C229	5	P	S01				
24	C230	25	P	S01				
25	C471	5	P	S01				
26	C232	5	P	S01				

EPA I.D. NUMBER (enter from page 1)

W [redacted]

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered above)
1	C234	5	P	S01				
2	C235	5	P	S01				
3	C236	5	P	S01				
4	C237	5	P	S01				
5	C238	5	P	S01				
6	C239	5	P	S01				
7	C240	5	P	S01				
8	C241	5	P	S01				
9	C242	5	P	S01				
10	C243	5	P	S01				
11	C244	5	P	S01				
12	C245	5	P	S01				
13	C246	5	P	S01				
14	C247	5	P	S01				
15	C248	5	P	S01				
16	C249	5	P	S01				
17	C250	5	P	S01				
18	C251	5	P	S01				
19	C252	5	P	S01				
20	C253	5	P	S01				
21	C254	5	P	S01				
22	C255	5	P	S01				
23	C256	5	P	S01				
24	C257	5	P	S01				
25	C258	5	P	S01				
26	C259	5	P	S01				

EPA I.D. NUMBER (enter from page 1)

W [redacted] 1

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPT. (if a code is not entered in
1	C260	5	P	S01				
2	C261	5	P	S01				
3	C262	5	P	S01				
4	C263	20	P	S01				
5	C265	5	P	S01				
6	C266	5	P	S01				
7	C267	5	P	S01				
8	C268	5	P	S01				
9	C269	10	P	S01				
10	C270	10	P	S01				
11	C272	5	P	S01				
12	C274	5	P	S01				
13	C275	5	P	S01				
14	C276	20	P	S01				
15	C277	5	P	S01				
16	C472	10	P	S01				
17	C278	5	P	S01				
18	C473	40	P	S01				
19	C279	5	P	S01				
20	C280	5	P	S01				
21	C281	5	P	S01				
22	C282	5	P	S01				
23	C283	200	P	S01				
24	C284	5	P	S01				
25	C285	40	P	S01				
26	C286	10	P	S01				

EPA Form 3510-3 (6-80)

CONTINUE

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

EPA I.D. NUMBER (enter from page 1)

W [redacted] 1

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPT. (if a code is not entered in
1	C287	5	P	S01				
2	C288	5	P	S01				
3	C289	5	P	S01				
4	C290	5	P	S01				
5	C291	5	P	S01				
6	C474	5	P	S01				
7	C475	5	P	S01				
8	C292	5	P	S01				
9	C293	5	P	S01				
10	C294	5	P	S01				
11	C295	5	P	S01				
12	C296	5	P	S01				
13	C297	5	P	S01				
14	C298	5	P	S01				
15	C299	5	P	S01				
16	C300	5	P	S01				
17	C301	5	P	S01				
18	C302	5	P	S01				
19	C477	50	P	S01				
20	C303	5	P	S01				
21	C304	5	P	S01				
22	C305	5	P	S01				
23	C306	40	P	S01				
24	C307	10	P	S01				
25	C308	10	P	S01				
26	C309	10	P	S01				

EPA Form 3510-3 (6-80)

CONTINU

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

EPA I.D. NUMBER (from page 1)

W [redacted] 1

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPT. (if a code is not entered in
1	C310	5	P	S01				
2	C478	5	P	S01				
3	C311	5	P	S01				
4	C312	5	P	S01				
5	C313	50	P	S01				
6	C479	5	P	S01				
7	C480	5	P	S01				
8	C314	5	P	S01				
9	C315	5	P	S01				
10	C316	5	P	S01				
11	C317	5	P	S01				
12	C481	5	P	S01				
13	C318	5	P	S01				
14	C319	50	P	S01				
15	C320	5	P	S01				
16	C321	1	P	S01				
17	C322	5	P	S01				
18	C323	5	P	S01				
19	C324	1	P	S01				
20	C325	5	P	S01				
21	C326	5	P	S01				
22	C327	5	P	S01				
23	C328	1	P	S01				
24	C329	10	P	S01				
25	C330	5	P	S01				
26	C334	15	P	S01				

EPA Form 3510-3 (6-80)

CONTINU

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

EPA I.D. NUMBER (enter from page 1)

W [redacted] 1

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPT (if a code is not entered in
1	C335	5	P	S01				
2	C336	1	P	S01				
3	C337	5	P	S01				
4	C338	5	P	S01				
5	C339	10	P	S01				
6	C340	25	P	S01				
7	C341	5	P	S01				
8	C342	5	P	S01				
9	C343	5	P	S01				
10	C346	5	P	S01				
11	C347	5	P	S01				
12	C348	5	P	S01				
13	C349	5	P	S01				
14	C350	5	P	S01				
15	C351	5	P	S01				
16	C352	5	P	S01				
17	C353	5	P	S01				
18	C356	5	P	S01				
19	C357	5	P	S01				
20	C358	5	P	S01				
21	C360	5	P	S01				
22	C361	5	P	S01				
23	C362	5	P	S01				
24	C363	5	P	S01				
25	C482	5	P	S01				
26	C365	5	P	S01				

EPA Form 3510-3 (6-80)

CONTINU

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

EPA I.D. NUMBER (enter from page 1)

W [redacted] 1

FOR OFFICIAL USE ONLY

W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D.1)
1	C366	10	P	S01				
2	C367	5	P	S01				
3	C369	10	P	S01				
4	C370	1	P	S01				
5	C483	5	P	S01				
6	C371	5	P	S01				
7	C372	5	P	S01				
8	C484	5	P	S01				
9	C485	5	P	S01				
10	C373	5	P	S01				
11	C374	5	P	S01				
12	C375	5	P	S01				
13	C376	10	P	S01				
14	C377	100	P	S01				
15	C380	5	P	S01				
16	C381	5	P	S01				
17	C382	5	P	S01				
18	C383	5	P	S01				
19	C384	5	P	S01				
20	C498	5	P	S01				
21	C385	10	P	S01				
22	C386	5	P	S01				
23	C387	4,500	P	S01				
24	C388	5	P	S01				
25	C389	5	P	S01				
26	C390	5	P	S01				

EPA Form 3510-3 (6-80)

CONTINUE

(enter "A", "B", "C", etc. behind the "1" to identify ...)

[redacted] | DUP | 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCR. (if a code is not entered)
1	C392	5	P	S01	
2	C486	10	P	S01	
3	C394	5	P	S01	
4	C395	5	P	S01	
5	C396	100	P	S01	
6	C397	5	P	S01	
7	C398	5	P	S01	
8	C399	5	P	S01	
9	C400	40	P	S01	
10	C401	15	P	S01	
11	C402	5	P	S01	
12	C403	5	P	S01	
13	C404	40	P	S01	
14	C405	1	P	S01	
15	C406	5	P	S01	
16	C407	5	P	S01	
17	C408	5	P	S01	
18	C409	5	P	S01	
19	C410	25	P	S01	
20	C413	25	P	S01	
21	C414	25	P	S01	
22	C415	25	P	S01	
23	C416	10	P	S01	
24	C418	5	P	S01	
25	C419	10	P	S01	
26	C489	5	P	S01	

EPA Form 3510-3 (6-80) CONT

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

[redacted] | DUP | DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESC. (if a code is not entered in D.1)
1	C420	5	P	S01				
2	C421	10	P	S01				
3	C422	10	P	S01				
4	C423	5	P	S01				
5	C424	5	P	S01				
6	C425	5	P	S01				
7	C426	5	P	S01				
8	C427	5	P	S01				
9	C428	5	P	S01				
10	C429	5	P	S01				
11	C430	5	P	S01				
12	C431	10	P	S01				
13	C432	5	P	S01				
14	C433	3700	P	S01				
15	C502	5	P	S01				
16	C503	5	P	S01				
17	C504	5	P	S01				
18	C505	5	P	S01				
19	C435	5	P	S01				
20	C436	25	P	S01				
21	C437	5	P	S01				
22	C438	5	P	S01				
23	C439	10	P	S01				
24	C440	80	P	S01				
25	C441	80	P	S01				
26	C442	80	P	S01				

EPA Form 3510-3 (6-80)

CON

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

[redacted] | DUP | DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

No.	A. EPA HAZARD WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)				D. PROCESSES 2. PROCESS DESC. (if a code is not entered)
1	C443	5	P	S01				
2	C490	10	P	S01				
3	C444	5	P	S01				
4	C445	5	P	S01				
5	C446	5	P	S01				
6	C447	5	P	S01				
7	C448	5	P	S01				
8	C449	5	P	S01				
9	C450	5	P	S01				
10	C451	5	P	S01				
11	C452	5	P	S01				
12	C453	5	P	S01				
13	C491	5	P	S01				
14	C455	5	P	S01				
15	C456	5	P	S01				
16	C457	10	P	S01				
17	C458	5	P	S01				
18	C459	10	P	S01				
19	C461	5	P	S01				
20	C462	5	P	S01				
21	C487	1	P	S01				
22	C488	1	P	S01				
23	C411	1	P	S01				
24	C412	5	P	S01				
25	C111	25	P	S01				
26	C175	25	P	S01				

EPA Form 3510-3 (6-80)

CON

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

NOTE: Photocopy this page before completing if you have more than 26 wastes to list.

Form Approved OMB No. 158-

EPA I.D. NUMBER (enter from page 1)	FOR OFFICIAL USE ONLY
W V [redacted]	W DUP 2 DUP

IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

LINE NO.	A. EPA HAZARD WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES 1. PROCESS CODES (enter)	D. PROCESSES 2. PROCESS DESCRIPTION (if a code is not entered in D1)
1	K004	50	P	S01	
2	P077	5	P	S01	
3	U009	100	P	S01	
4	U153	50	P	S01	
5	U225	50	P	S01	
6	U044	50	P	S01	
7	C469	10	P	S01	
8	C219	10	P	S01	
9	C476	25	P	S01	
10	C331	50	P	S01	
11	C332	25	P	S01	
12	C333	10	P	S01	
13	C359	10	P	S01	
14	C417	50	P	S01	
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					

EPA Form 2510-3 (6-80)

CONTINUE ON

(enter "A", "B", "C", etc. behind the "3" to identify photocopied pages)

FOIA Report of Non-Sensitive Compliance Monitoring and Enforcement Data

Report run on: January 30, 2014 - 4:15 PM

Version 5.0

User Selection Criteria

Location:	New Jersey, all activities	**Activity Location:**	None Chosen
Handler ID:	NJD103803417	**Group of IDs:**	None Chosen
Handler Name:			
Handler Universe:	All Facilities Regardless of Universe		
Determined Date Range:	From: 10/01/1980 To: 01/30/2014		
Location County Code:	None Chosen	**Evaluation Type:**	
Location City:		**Focus Area:**	
Location Zip Code:		**Violation Type:**	
State District:	None Chosen	**Display Code Descrip.:**	Yes
Sort Order:	Region, State, Handler Name	**Display Universes:**	Yes

Results

Data meeting the criteria you selected follows.

Total Pages:5 Total Handlers:1

Report Description

This report presents available information from the Resource Conservation and Recovery Act Information System (RCRAInfo) about compliance evaluations, violations, and enforcement actions meeting the criteria supplied by the user. Evaluations showing no violations does not always indicate that no violations were determined. Violation without enforcement actions does not always mean no enforcement action will be issued. In order to avoid releasing enforcement sensitive information to the public the following information is not shown on the report: pending civil / judicial referrals, criminal actions and referrals, and State to EPA referrals; all other enforcement actions are released.

Report Information

Name:	cme_foia.rdf
Developed by:	EPA Headquarters, Office of Enforcement and Compliance Assurance
Deployed:	June 2006
Last Updated:	May 2012
Contact:	rcrainfo.help@epa.gov
Tables Used:	cmecomp3, ccitation3, hreport_univ5, lu_citation, lu_state, hid_groups
Libraries:	none

FOIA Report of Non-Sensitive Compliance Monitoring and Enforcement Data

Report run on: January 30, 2014 - 4:15 PM

RUTGERS UNIVERSITY - NEWARK CAMPUS County Name / Code: ESSEX / NJ013 **NJD103803417**

Location: 360 MARTIN LUTHER KING; NEWARK, NJ 07102 **REGION 02**

Mailing: 27 RD 1; BLDG 4086; PISCATAWAY, NJ 08854-8036

Activity Location: NJ State District: NORTHERN Accessibility: Non-Notifier: Extract Flag: Y Active Site: Y

Generator: LQG Transporter: N Operating TSDF: ------ IC In Place: N EI Indicator (HE / GW): N / N
Short-Term Gen: N Transfer Facility: N Offsite Receiver: N HSM: N Subpart K: ----
Full Enforcement: ------ Converter: ------ State Unaddressed SNC: N EPA Unaddressed SNC: N
CA Wrkld: N State TSDF: ------ State Addressed SNC: N EPA Addressed SNC: N
Active State Gen: N State SNC w/Comp Sched: N EPA SNC w/Comp Sched: N

Violation: Activity Location: NJ Type: 262.A Determined Date: 06/28/1994 Determined by Agency: State Responsible Agency: State
Scheduled Compliance Date: 07/13/1994 Actual Compliance Date: 07/19/1994 RTC Qualifier: OBSERVED Sequence Number: 1

NRR Evaluation 07/19/1994 Activity Location: NJ By: State Identifier: 000 Person: NJSS Branch: M Found Violation: YES
Citizen Complaint: NO Multimedia Inspection: NO Sampling: NO Not Subtitle C: NO Day Zero: Focus Area:

CEI Evaluation 06/28/1994 Activity Location: NJ By: State Identifier: 000 Person: NJSS Branch: M Found Violation: YES
Citizen Complaint: NO Multimedia Inspection: NO Sampling: NO Not Subtitle C: NO Day Zero: Focus Area:

Enforcement: Activity Location: NJ Type: 120 Action Date: 06/28/1994 Identifier: 000
Docket: Agency: State Responsible Person: NJSS Branch: M
CA Component: N Disposition Status: Appeal Initiated: Appeal Resolved:

Violation: Activity Location: NJ Type: 262.B Determined Date: 06/28/1994 Determined by Agency: State Responsible Agency: State
Scheduled Compliance Date: 07/13/1994 Actual Compliance Date: 07/19/1994 RTC Qualifier: OBSERVED Sequence Number: 2

NRR Evaluation 07/19/1994 Activity Location: NJ By: State Identifier: 000 Person: NJSS Branch: M Found Violation: YES
Citizen Complaint: NO Multimedia Inspection: NO Sampling: NO Not Subtitle C: NO Day Zero: Focus Area:

CEI Evaluation 06/28/1994 Activity Location: NJ By: State Identifier: 000 Person: NJSS Branch: M Found Violation: YES
Citizen Complaint: NO Multimedia Inspection: NO Sampling: NO Not Subtitle C: NO Day Zero: Focus Area:

Enforcement: Activity Location: NJ Type: 120 Action Date: 06/28/1994 Identifier: 000
Docket: Agency: State Responsible Person: NJSS Branch: M
CA Component: N Disposition Status: Appeal Initiated: Appeal Resolved:

Evaluations With No Violations:

CEI Evaluation 04/24/2013 Activity Location: NJ By: State Identifier: 001 Person: NOSDS Branch: Found Violation: NO
Citizen Complaint: NO Multimedia Inspection: YES Sampling: NO Not Subtitle C: NO Day Zero: 04/24/2013 Focus Area:

CEI Evaluation 03/10/2010 Activity Location: NJ By: State Identifier: 001 Person: TOPHT Branch: N Found Violation: NO
Citizen Complaint: NO Multimedia Inspection: NO Sampling: NO Not Subtitle C: NO Day Zero: 03/10/2010 Focus Area:

CEI Evaluation 07/30/2008 Activity Location: NJ By: State Identifier: 001 Person: COMES Branch: N Found Violation: NO
Citizen Complaint: NO Multimedia Inspection: YES Sampling: NO Not Subtitle C: NO Day Zero: 07/30/2008 Focus Area:

* Note: Penalty amount may not reflect all violations cited.

Total Number of Handlers: 1
Total Number of Activity Locations: 1

*** End of Report ***

* Note: Penalty amount may not reflect all violations cited.

Description of codes used on the report:

Universes	Description of Universes
Generator	Indicates that the facility is a Large Quantity Generator (LQG), Small Quantity Generator (SQG), Conditionally Exempt Small Quantity Generator (CEG), or not a generator (N).
Transporter	Indicates that the facility Transports waste subject to RCRA regulations. ('Y' indicates that the facility is in this universe).
Operating TSDF	Indicates that the facility is a Treatment, Storage or Disposal facility subject to any type of enforcement. It then specifies the type of facility (L - Land Disposal; I - Incinerator; B - BIF; S - Storage; T - Treatment)
IC in Place	Indicates that the facility has Institutional Controls in place. ('Y' indicates that the facility is in this universe).
EI Indicator (HE / GW)	Indicates that the facility has controls in place for Environmental Indicators. HE - Human Exposures ('+' indicates the exposure exists and is under control; '-' indicates the exposure exists and is not under control; 'N' indicates the exposure does not exist) GW - Groundwater Release ('+' indicates the exposure exists and is under control; '-' indicates the exposure exists and is not under control; 'N' indicates the exposure does not exist)
Short-Term Gen	Indicates that the facility is a short term or one time event generator and not generating from ongoing processes.
Transfer Facility	Indicates that the facility transfers hazardous waste.
Offsite Receiver	Indicates that the facility, whether public or private, currently accepts hazardous waste from another site (site identified by a different EPA ID).
HSM	Indicates that the facility manages hazardous secondary material(s) (e.g. spent material, by-product or sludge) that when discarded, would be identified as hazardous waste.
Subpart K	Indicates that the facility has opted into the subpart K laboratory rule. It then specifies the type of facility (C - College or University; H - Teaching Hospital; N - Non-profit Research Institute; W - withdrawal from the rule)
Full Enforcement	Indicates that the facility is a Treatment, Storage or Disposal facility which is part of the Full Enforcement universe. It then specifies the type of facility (L - Land Disposal; I - Incinerator; B - BIF; S - Storage; T - Treatment)
CA Workload	Indicates that the facility is part of the Corrective Action Workload universe. ('Y' indicates that the facility is in this universe).
Active State Gen	Indicates that the facility is an Active State Generator. ('Y' indicates that the facility is in this universe).
Converter	Indicates that the facility is a Converter Treatment, Storage or Disposal facility. It then specifies the type of facility (L - Land Disposal; I - Incinerator; B - BIF; S - Storage; T - Treatment)
State TSDF	Indicates that the facility is a State Treatment, Storage or Disposal facility. It then specifies the type of facility (L - Land Disposal; I - Incinerator; B - BIF; S - Storage; T - Treatment)
State Unaddressed SNC	Indicates that the facility is a State Unaddressed Significant Non-Complier. ('Y' indicates that the facility is in this universe).
State Addressed SNC	Indicates that the facility is a State Addressed Significant Non-Complier. ('Y' indicates that the facility is in this universe).
State SNC w/ Compl. Sched	Indicates that the facility is a State Significant Non-Complier with a Compliance Schedule. ('Y' indicates that the facility is in this universe).
EPA Unaddressed SNC	Indicates that the facility is an EPA Unaddressed Significant Non-Complier. ('Y' indicates that the facility is in this universe).
EPA Addressed SNC	Indicates that the facility is an EPA Addressed Significant Non-Complier. ('Y' indicates that the facility is in this universe).
EPA SNC w/ Compl. Sched	Indicates that the facility is a EPA Significant Non-Complier with a Compliance Schedule. ('Y' indicates that the facility is in this universe).

* Note: Penalty amount may not reflect all violations cited.

Description of codes used on the report:

ACCESSIBILITY - indicates the reason why the handler is not accessible for normal RCRA tracking and processing (previously called Bankrupt Indicator):

Code	Description
B	indicates that the handler has filed for bankruptcy and bankruptcy litigation is in process.
C	indicates that all RCRA responsibilities for permitting/closure, corrective action, and compliance monitoring and enforcement at the facility have been formally transferred to the CERCLA program or state equivalent.
F	indicates that all responsible parties (owners/operators) for the handler have fled the country or are otherwise not available for prosecution.
L	indicates that the handler's case is tied up in litigation to the extent that further progress in achieving RCRA compliance through normal enforcement is not possible.

NON-NOTIFIER - indicates that the handler has been identified through a source other than Notification and is suspected of conducting RCRA-regulated activities without proper authority:

Code	Description
E	indicates that the handler was initially a non-notifier, subsequently determined to be exempt from requirements to notify.
O	indicates that the handler is a former non-notifier.
X	indicates that the handler is a non-notifier.

Violation Type	Description
262.A	GENERATORS - GENERAL
262.B	GENERATORS - MANIFEST

Evaluation Type	Type Description
CEI	COMPLIANCE EVALUATION INSPECTION ON-SITE
NRR	NON-FINANCIAL RECORD REVIEW

Enforcement Type	Enforcement Description
120	WRITTEN INFORMAL

* Note: Penalty amount may not reflect all violations cited.