PROCESS FLOW DIAGRAM

Sanitized Attachment for Part II, Section A, 1. d.



1, 2, 3, 4, 5: Points of Release