Chemical Analysis of Radioactive Material From Areas 1 and 2

Table 13

Concentration in ppm

	Offsite Bkg Sample	Area 1 Surface (#101)	Area 1 Surface (#102)	Area 1 Borehole (#103)	Area 2 Surface (#104)	Area 2 Surface (#105)
Barium	250	300	1811	2386	1158	1197
Lead	16	15	108	121	11	50
Zinc	132	146	94	76	28	167
Sulfate	20	15	108	121	11	50

*Background