Survey Information															
Date (b)(7)(i)	Beginning Time (b)(7)(ii)	End Time (b)(7)(ii)	Name of OGI Operator (b)(7)(iii)	Training and Experience of OGI Operator (b)(7)(iii)	Ambient Temperature, Sky Conditions and Maximum Wind Speed (b)(7)(iv)	Monitoring Instrument (b)(7)(v)	Deviations (or Statement of No Deviations) (b)(7)(vi)	Number and Type of Components for Which Emissions Were Detected (b)(7)(vii)	Number and Type of Components Not Repaired as Required (b)(7)(viii)	Number and Type of DTM & UTM Components Monitored (b)(7)(ix)	Date of Successful Leak Repairs (b)(7)(x)	Number and Type of Components Placed on DOR (b)(7)(xi)	Explanation for DOR (b)(7)(xi)	Type of Instrument Used to Resurvey a Repaired Component (not during the initial finding) (b)(7)(xii)	Comments
1/19	8:35 AM	8:45 AM	Larry Dameron	> 1 years experience	55 F, Clear/Sunny, 1.5 mph	ThermaCAM Gas FindIR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
5/19	8:00 AM	8:10 AM	Larry Dameron	> 1 years experience	41 F, Clear/Sunny, 0 mph	ThermaCAM Gas Find IR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
3/18	11:35 AM	11:45 AM	David Keene	4 years experience	55 F, Clear/Sunny, 7.1 mph	FLIR ThermaCAM GasFind IR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
1/19	7:50 AM	8:05 AM	Larry Dameron	> 1 years experience	55 F, Clear/Sunny, 2 mph	ThermaCAM Gas FindIR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
/18	10:45 AM	10:55 AM	David Keene	4 years experience	77 F, Clear/Sunny, 0 mph	FLIR ThermaCAM GasFind IR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
8/18	11:05 AM	11:15 AM	David Keene	4 years experience	82 F, Cloudy/Overcast, 0.5 mph	FLIR ThermaCAM GasFind IR	Yes - See Comments	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	No site photo.
/11/18	11:55 AM	12:05 PM	David Keene	4 years experience	40 F, Clear/Sunny, 7.8 mph	FLIR ThermaCAM GasFind IR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
21/19	9:15 AM	9:25 AM	Larry Dameron	> 1 years experience	61 F, Clear/Sunny, 0 mph	ThermaCAM Gas FindIR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
16/19	9:15 AM	9:25 AM	Larry Dameron	> 1 years experience	53 F, Clear/Sunny, 0 mph	ThermaCAM Gas FindIR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
25/18	1:15 PM	1:25 PM	David Keene	4 years experience	70 F, Light; Cloudy/Overcast; Rain, 0 mph	THermaCAM	Yes - See Comments	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	No site photo. Correction to 10/31/2 report.
/6/18	11:50 AM	12:00 PM	David Keene	4 years experience	60 F, Light; Cloudy/Overcast; Rain, 0 mph	FLIR ThermaCAM GasFind IR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
8/19	12:15 PM	12:20 PM	Larry Dameron	> 1 years experience	59 F, Cloudy/Overcast, 0 mph	ThermaCAM Gas FindIR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
30/19	10:15 AM	10:25 AM	Larry Dameron	> 1 years experience	71 F, Cloudy/Overcast, 0.1 mph	ThermaCAM Gas FindIR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
12/19	7:55 AM	8:10 AM	Larry Dameron	> 1 years experience	60 F, Cloudy/Overcast, 0.5 mph	ThermaCAM Gas FindIR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
12/19	9:00 AM	9:15 AM	Larry Dameron	> 1 years experience	63 F, Cloudy/Overcast, 1 mph	ThermaCAM Gas Find IR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
/25/18	2:35 PM	2:45 PM	David Keene	4 years experience	69 F, Light; Cloudy/Overcast; Rain, 0.1 mph	GF320	Yes - See Comments	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	No site photo.
2/19/18	3:25 PM	3:35 PM	David Keene	4 years experience	51 F, Clear/Sunny, 5 mph	FLIR ThermaCAM GasFind IR	Yes - See Comments	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	No site photo.
/19/18	1:40 PM	1:50 PM	David Keene	4 years experience	85 F, Cloudy/Overcast, 0 mph	FLIR ThermaCAM GasFind IR	Yes - See Comments	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	No site photo.
/11/19	9:00 AM	9:09 AM	Larry Dameron	> 1 years experience	55 F, Clear/Sunny, 0 mph	ThermaCAM Gas FindIR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
/13/19	9:23 AM	9:45 AM	Larry Dameron	> 1 years experience	48 F, , 0.1 mph	ThermaCamGas FindIR	No Deviations	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	
/26/18	1:50 PM	2:00 PM	David Keene	4 years experience	68 F, Light; Cloudy/Overcast; Rain, 0 mph	GF320	Yes - See Comments	No Leaks Detected	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	No site photo.