Exceptions Under §60.5375a(a)(3) - Technically Infeasible to Route to the Gas Flow Line or Collection System, Re-inject into a Well, Use as an Onsite Fuel Source, or Use for Another Useful Purpose Served By a Purchased

for the Period erated Under eption * (b)(2)(i) and (c)(1)(iv))	Ending Date for the Period the Well Operated Under the Exception * (§60.5420a(b)(2)(i) and §60.5420a(c)(1)(iv))	Why the Well Meets the Claimed Exception * (§60.5420a(b)(2)(i) and §60.5420a(c)(1)(iv))	Name of Nearest Gathering Line * (§60.5420a(b)(2)(i) and §60.5420a(c)(1)(iii)(A)-(B))	Location of Nearest Gathering Line * (§60.5420a(b)(2)(i) and §60.5420a(c)(1)(iii)(A)-(B))	Technical Considerations Preventing Routing to this Line * (§60.5420a(b)(2)(i) and §60.5420a(c)(1)(iii)(A)-(B))	Capture, Reinjection, and Reuse Technologies Considered * (§60.5420a(b)(2)(i) and §60.5420a(c)(1)(iii)(A)-(B))
.6	e.g.: 10/18/2016	e.g.: As further described in this report, technical issues prevented the use of the gas for useful purposes.	e.g.: ABC Line	e.g.: 100 miles away at 34.12345 latitude, -101.12345 longitude	e.g.: right of use	e.g.: on-site generators
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	NA
	NA	NA	NA	NA	NA	
	NA	NA	NA	NA		
	NA	NA				
	NA					