# Collection of Fugitive Emissions Components at a Compressor Station

§60.5420a(b)(7)

| Facility Name | Legal Entity | Survey Information | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | Date (b)(7)(i) | Beginning and End Time (b)(7)(ii) | Name, Training and Experience of OGI Operator (b)(7)(iii) | Ambient Temperature, Sky Conditions and Maximum Wind Speed (b)(7)(iv) | Monitoring Instrument (b)(7)(v) | Deviations (or Statement of No Deviations) (b)(7)(vi) | Number and Type of Components for Which Emissions Were Detected (b)(7)(vii) | Number and Type of Components Not Repaired as Required (b)(7)(viii) | Number and Type of DTM & UTM Components Monitored (b)(7)(ix) | Date of Successful Leak Repairs (b)(7)(x) | Number and Type of Components Placed on DOR and Explanation (b)(7)(xi) | Type of Instrument Used to Resurvey a Repaired Component (not during the initial finding) (b)(7)(xii) |
| Dulaney Station | EQM Gathering Opco | 8/16/2018 | 7:51 AM-8:18 AM | Steve LaRue- ITC Certified | 73 deg F Partly Cloudy Calm | FLIR GF320 OGI Camera | No | One (1) Compression Fitting on fuel skid kimray<br>One (1) Compression Fitting on fuel skid kimray | None | None | 8/16/2018 | None | NA |
| Dulaney Station | EQM Gathering Opco | 11/8/2018 | 7:40 AM-8:05 AM | Steve LaRue- ITC Certified | 32 deg F Foggy Calm | FLIR GF320 OGI Camera | No | One (1) Joe Valve on fuel to heater 2<br>One (1) motor valve hammer union on fuel skid | None | None | 11/16/2018 | None | FLIR GF320 OGI Camera |
| Dulaney Station | EQM Gathering Opco | 2/22/2019 | 7:41 AM-8:36 AM | Steve LaRue- ITC Certified | 32 deg F Cloudy Calm | FLIR GF320 OGI Camera | No | One (1) Production Tank 3 thief hatch seal<br>One (1) Production Tank 7 thief hatch seal<br>One (1) PSV threads on compressor<br>One (1) Knockout Point Threads on compressor<br>One (1) Valve on combustor | None | None | 3/8/2019 | None | FLIR GF320 OGI Camera |
| Dulaney Station | EQM Gathering Opco | 5/16/2019 | 10:05 AM-10:22 AM | Steve LaRue- ITC Certified | 65 deg F Partly Cloudy Calm | FLIR GF320 OGI Camera | No | One (1) motor valve hammer union on fuel skid | None | None | 5/20/2019 | None | FLIR GF320 OGI Camera |
| Janus Compressor Station | EQM Gathering Opco | 9/24/2018 | 8:30 AM-10:05 AM | Jermy Davis/ Sam McDaniel- Certified | 62deg F Overcast 5 mph | FLIR GFx320 OGI Camera | No | One (1) Unit 3 throw 2 head end<br>One (1) Unit 3 throw 4 head end<br>One (1) Unit 3 throw 6 head end | None | None | 10/9/2018 | None | FLIR GFx320 OGI Camera |
| Janus Compressor Station | EQM Gathering Opco | 12/27/2018 | 12:30 PM-2:00 PM | Sam McDaniel- Certified | 52 deg F Overcast 6 mph | FLIR GFx320 OGI Camera | No | One (1) Unit 1 throw 2 head end<br>One (1) Unit 3 throw 6 head end | None | None | 1/8/2019 | None | FLIR GFx320 OGI Camera |
| Janus Compressor Station | EQM Gathering Opco | 3/18/2019 | 2:20 PM-3:45 PM | Sam McDaniel- Certified (1 year) | 39 deg F Cloudy 5 mph | FLIR GFx320 OGI Camera | No | None (no leaks detected) | None | None | NA | NA | NA |