**ıs of Performance for Crude Oil and Natural Gas Facilities for which Construction, Modification or Reconstruction Commenced After September 18, 2015 - §60.5420a(b) Annual Report**

**ımpressor affected facility, an owner or operator must include the information specified in paragraphs (b)(4)(i) and (ii) of this section in all annual reports:**

ıch field indicates that the corresponding field is required.

| Compressor ID * (§60.5420a(b)(1)(ii)) | Are emissions from the rod packing unit being routed to a process through a closed vent system under negative pressure? * (§60.5420a(b)(4)(i)) | If emissions are not routed to a process through a closed vent system under negative pressure, what are the cumulative number of hours or months of operation since initial startup or the previous rod packing replacement (whichever is later)? * (§60.5420a(b)(4)(i)) | Units of Time Measurement * (§60.5420a(b)(4)(i)) | Deviations where the reciprocating compressor was not operated in compliance with requirements* (§60.5420(b)(4)(ii) and §60.5420a(c)(3)(iii)) |
|---|---|---|---|---|
| .g.: Comp-12b | e.g.: no | e.g.: 2 | e.g.: months | e.g.: Rod packing replacement exceeded 36 months. Replacement occurred after 37 months. |
| each Pad Compressor | no | 12,481 | hours | None |
| ost Pad Compressor | no | 3,762 | hours | None |
| oastal Pad Compressor | no | 18,347 | hours | None |
| tatler Pad Compressor | no | 14,067 | hours | None |
| oastal Pad Compressor | no | 9,223 | hours | None |
| isher Pad Compressor 1 | no | 11,651 | hours | None |
| isher Pad Compressor 2 | no | 3,470 | hours | None |