Facility	Location	Date of Survey	Beginning Time	End Time	Operator(s) Name Performing Survey	Operator(s) Training	Ambient Temperature (F)	Sky Conditions	Max Wind Speed	Monitoring Instrument Used	Any Deviations from Monitoring Plan	Number and Type of Components Leaking	Date of Successful Repair for Each Component	Remonitoring Instrument Use
Balli	39.302138, -80.843915	5/29/2018	12:00	2:15	N. Summerfield	FLIR Certified	78	Cloudy	5	FLIR GF320	None	Line flange	6/4/2018	FLIR GF320
												Radiator line	5/31/2018	
												Hammer union	6/15/2018	
												Stainless T line	5/31/2018	
												Rupture Disk	5/31/2018	
												Stainless elbow line	6/4/2018	
												Tank hammer union (4)	6/18/2018	
												Regulator (2)	5/29/2018	
												Kimray Regulator	5/29/2018	
												Tank enardos (5)	5/29/2018	
		8/27/2018	12:00	1:25	N. Summerfield	FLIR Certified	83	Clear	5	FLIR GF320	None	Tank hammer union	5/29/2018	
												Solenoid	8/30/2018	
												Stainless fitting	8/27/2018	
Buck Run	39.31584, -80.94732	8/16/2017	10:30	12:00	N. Summerfield	FLIR Certified	73	Clear	0	FLIR GF320	None	VRU site glass	8/24/2017	FLIR GF320
		10/25/2017	Day 1 12:15 pm Day 2 11:10 am	Day 1 2:15 pm Day 2 12:10 pm	N.Summerfield	FLIR Certified	45	Cloudy	5	FLIR GF320	None	valve	11/21/2017	FLIR GF320
												pancake	11/21/2017	
												back pressure regualtor	12/7/2018	
												regulator	11/27/2017	
												stainless connection (3)	10/25/2017	
												threads (2)	10/25/2017	
		3/29/2018	9:15	Not Recorded	A. Rafuse	FLIR Certified	58	Rain	0	AVO	Camera away for repairs	NO LEAKS FOUND (AVO)	3/29/2018	N/A
		5/2/2018	10:55	11:55	N.Summerfield	FLIR Certified	70	Clear	5	FLIR GF320	None	regulator	5/23/2018	FLIR GF320
												Site glass regulator	5/23/2018	
		7/23/2018	10:50	11:40	N.Summerfield	FLIR Certified	75	Clear	5	FLIR GF320	None	dump	7/30/2018	FLIR GF320
												high/low	7/30/2018	
												threads (2)	8/13/2018	
												valve	8/7/2018	
												stainless fitting	8/7/2018	
												stainless fitting (2)	7/23/2018	
Charlene	39.299717, -80.963838	8/16/2017	11:15	1:30	N. Summerfield	FLIR Certified	81	Clear	0	FLIR GF320	None	Combustor regulator	8/16/2017	FLIR GF320
		11/28/2017	12:25	2:25	N.Summerfield	FLIR Certified	60	Clear	5	FLIR GF320	None	pancake	11/30/2017	FLIR GF320
												regualtor	11/30/2017	
												stainless connection (10)	11/28/2017	
												threads	11/28/2017	
		3/29/2018	8:55	9:10	A. Rafuse	FLIR Certified	57	Rain	0	AVO	Camera away for repairs	NO LEAKS FOUND (AVO)	3/29/2017	N/A
		5/2/2018	9:15	10:45	N.Summerfield	FLIR Certified	66	Clear	5	FLIR GF320	None	enardo	5/2/2018	FLIR GF320
												stainless fitting	5/2/2018	
		7/23/2018	9:40	10:40	N.Summerfield	FLIR Certified	73	Clear	2	FLIR GF320	None	enardo	7/24/2018	FLIR GF320
												emergency hatch (3)	7/24/2018	
												regulator	8/13/2018	
												dump	7/30/2018	