Location	Date of Survey	Beginning Time	End Time	Operator(s) Name Performing Survey	Operator(s) Training	Ambient Temperature (F)	Sky Conditions	Max Wind Speed	Monitoring Instrument Used	Any Deviations from Monitoring Plan	Number and Type of Components Leaking	Date of Successful Repair for Each Component	Remonitoring Instrument Used	Number and Type of Components Added to Delay of Repair List-Give Explanation of Why	Num Diffic Moni
39.234098, -80.840039	10/17/2017	8:00	9:45	N.Summerfield	FLIR Certified	36	Clear	0	FLIR GF320	None	ESD Pin	11/21/2017	FLIR GF320	None	
											stainless connection	11/30/2017			
											stainless connection (2)	10/17/2017			
											Level controller	10/17/2017			
	2/22/2018	10:15	10:40	N.Summerfield	FLIR Certified	41	Rain	5	AVO	Camera away for repairs	NO LEAKS FOUND	2/22/2018	N/A	N/A	
	5/9/2018	9:35	11:30	N.Summerfield	FLIR Certified	70	Clear	2	FLIR GF320	None	pop off	5/25/2018	FLIR GF320	None	
											threads	5/9/2018			
											stainless fitting	5/9/2018			
											Enardo Valve	5/9/2018			
											emergency (3)	5/9/2018			
											thief hatch (2)	5/9/2018			
	8/9/2018	8:25	9:30	N.Summerfield	FLIR Certified	73	Clear	1	FLIR GF320	None	emergency hatch (2)	8/9/2018	FLIR GF320	None	
											threads	8/9/2018			
39.367716, -80.743718	8/10/2017	11:40	1:10	N. Summerfield	FLIR Certified	71	Clear	0	FLIR GF320	None	VRU site glass	8/16/2017	FLIR GF320	None	
					FLIR Certified						Tank hatch gaskets	8/16/2017			
					FLIR Certified						Ball Valve	8/10/2017			
					FLIR Certified						Stainless connection	8/10/2017			
	11/16/2017	9:15	10:00	N.Summerfield	FLIR Certified	48	Clear	10	FLIR GF320	None	stainless connection	11/16/2017	FLIR GF320	None	
	3/16/2018	11:55	12:40	N.Summerfield	FLIR Certified	29	Clear	5	FLIR GF320	None	quick exhaust	3/28/2018	FLIR GF320	None	
											Connection	3/27/2018			
											stainless connection	3/16/2018			
	4/5/2018	11:40	1:00	N.Summerfield	FLIR Certified	28	Clear	5	FLIR GF320	None	tubing hangar	4/5/2018	FLIR GF320	None	
	7/9/2018	11:40	12:30	N.Summerfield	FLIR Certified				FLIR GF320	None	NO LEAKS FOUND	7/9/2018			
39.365245, -80.993244	8/8/2017	9:30	11:50	N. Summerfield	FLIR Certified	65	Clear	5	FLIR GF320	None	Pressure regulator	8/14/2017	FLIR GF320	None	
											Enardo Valve	8/21/2017			
											Stainless connection	8/8/2017			
											Quick Exhaust	8/8/2017			
											Quick Exhaust	8/8/2017			
											Quick Exhaust	8/8/2017			
											Quick Exhaust	8/8/2017			
											Stainless connection	8/8/2017			
											Regulator	8/8/2017			
	11/10/2017	11:30	1:00	N.Summerfield	FLIR Certified	33	Clear	5	FLIR GF320	None	Ball Valve	11/21/2017	FLIR GF320	None	
											pop off	11/21/2017			
	3/28/2018	10:00	10:30	N.Summerfield	FLIR Certified	49	Rain	5	AVO	Camera away for repairs	NO LEAKS FOUND	N/A	None	N/A	
	4/27/2018	8:10	10:00	N.Summerfield	FLIR Certified	47	Clear	5	FLIR GF320	None	regulator	5/8/2018	FLIR GF320	None	
	7/17/2018	11:50	2:00	N.Summerfield	FLIR Certified	81	Clear	5	FLIR GF320	None	dump	8/6/2018	cancelled	None	
											quick exhaust	8/13/2018	FLIR GF320		
											valve	7/31/2018			
											stainless fitting (2)	7/17/2018			
											emergency hatch	7/17/2018			
39.253405, -80.56035	10/3/2017	8:00	9:30	N.Summerfield	FLIR Certified	45	Clear	0	FLIR GF320	None	enardos (2)	10/23/2017	FLIR GF320	None	
											pancake	10/23/2017			
											pop off	10/23/2017			
											pop off	10/24/2017			
											stainless connection (3)	10/3/2017			
	2/15/2018	9:15	9:30	N.Summerfield	FLIR Certified	56	Rain	5	AVO	Camera away for repairs	NO LEAKS FOUND	N/A	None	N/A	
	5/24/2018	9:25	10:00	N.Summerfield	FLIR Certified				FLIR GF320	None	emergency hatch	5/24/2018	FLIR GF320	None	