Facility	Location	Date of Survey	Beginning Time	End Time	Operator(s) Name Performing Survey	Operator(s) Training	Ambient Temperature (F)	Sky Conditions	Max Wind Speed	Monitoring Instrument Used	Any Deviations from Monitoring Plan	Number and Type of Components Leaking	Date of Successful Repair for Each Component	Remonitoring Instrument Used	Number and Typ Components Add Delay of Repair Give Explanatio Why
Long Run	39.30031, -80.864087	12/7/2017	9:00	11:30	N. Summerfield	FLIR Certified	27	Clear	5	FLIR GF320	None	enardos and hatches	1/9/2018	FLIR GF320	1
												stainless fitting	12/7/2017		
		3/14/2018	12:40	2:00	N. Summerfield	FLIR Certified	29	Clear	5	FLIR GF320	None	regulator	3/14/2018	FLIR GF320	None
												stainless fitting	3/14/2018		
		5/16/2018	8:45	10:10	N. Summerfield	FLIR Certified	67	Rain	5	FLIR GF320	None	ESD Pancake	6/21/2018	FLIR GF320	1
												quick exhaust	5/21/2018		
												level controller	5/16/2018		
												quick exhuast	5/16/2018		
												plug threads	5/16/2018		
		8/21/2018	8:05	8:50	N. Summerfield	FLIR Certified	70	Clear	2	FLIR GF320	None	Solenoid	8/27/2018	FLIR GF320	None
Mackay	39.23833, -80.897085	10/24/2017	10:30	11:45	N.Summerfield	FLIR Certified	55	Cloudy	10	FLIR GF320	None	solenoid	11/21/2017	FLIR GF320	None
												stainless connection	10/24/2017		
		3/6/2018	11:25	12:30	N.Summerfield	FLIR Certified	44	Rain	5	AVO	Camera away for repairs	NO LEAKS FOUND	N/A	N/A	N/A
		5/7/2018	12:10	1:15	N.Summerfield	FLIR Certified	69	Clear	5	FLIR GF320	None	stainless fitting (3)	5/10/2018	FLIR GF320	None
		8/9/2018	9:55	11:20	N.Summerfield	FLIR Certified	74	Clear	7	FLIR GF320	None	quick exhaust	8/9/2018	FLIR GF320	None
McGill	39.274611, -80.848821	10/19/2017	9:45	12:00	N.Summerfield	FLIR Certified	48	Clear	5	FLIR GF320	None	regualtor	10/9/2017	FLIR GF320	None
												hammer union	10/9/2017		
												pancake	10/9/2017		
												level controller	10/9/2017		
		3/6/2018	2:20	3:00	N.Summerfield	FLIR Certified	48	Clear	5	AVO	Camera away for repairs	NO LEAKS FOUND	N/A	N/A	N/A
		5/11/2018	7:55	9:30	N.Summerfield	FLIR Certified	60	Clear	5	FLIR GF320	None	undergournd leaks	5/24/2018	FLIR GF320	None
												Ball Valve	5/11/2018		
												stainless fitting (6)	5/11/2018		
		8/9/2018	1:30	2:30	N.Summerfield	FLIR Certified	81	Clear	2	FLIR GF320	None	valve	8/13/2018	FLIR GF320	None
												emergency hatch	8/9/2017		
												stainless fitting	8/9/2018		
												quick exhaust (2)	8/9/2018		
Melody	39.358366, -80.75935	8/10/2017	12:45	2:00	N. Summerfield	FLIR Certified	73	Cloudy	0	FLIR GF320	None	NO LEAKS FOUND	NA	NA	None
		12/11/2017	10:30	11:25	N. Summerfield	FLIR Certified	35	Clear	10	FLIR GF320	None	hammer union	12/11/2017	FLIR GF320	None
		2/15/2018	1:30	2:00	N. Summerfield	FLIR Certified	63	Cloudy	5	AVO	Camera away for repairs	NO LEAKS FOUND	2/15/2018	N/A	None
		4/5/2018	8:30	10:05	N. Summerfield	FLIR Certified	28	Clear	5	FLIR GF320	None	stainless fitting	4/5/2018	FLIR GF320	None
		7/12/2018	8:25	9:40	N. Summerfield	FLIR Certified	60	Clear	5	FLIR GF320	None	dump stuck (3)	7/12/2018	FLIR GF320	None
												gauge	7/12/2018		
												regulator	7/12/2018		
												quick exhaust (2)	7/12/2018		
Misery	39.360614, -80.749024	8/10/2017	12:15	2:00	N. Summerfield	FLIR Certified	73	Cloudy	0	FLIR GF320	None	Quick Exhaust	8/16/2017	FLIR GF320	None
												Pancake regulator	8/10/2017		
												Ball Valve	8/10/2017		
												Stainless connection	8/10/2017		
		11/16/2017	10:15	12:00	N.Summerfield	FLIR Certified	48	Clear	15	FLIR GF320	None	stainless connection	11/16/2017	FLIR GF320	None
												quick exhaust (2)	11/16/2017		
		3/16/2018	10:55	11:49	N.Summerfield	FLIR Certified	29	Clear	5	FLIR GF320	None	filter	3/16/2018	FLIR GF320	None
		4/5/2018	10:10	11:30	N.Summerfield	FLIR Certified	28	Clear	5	FLIR GF320	None	stainless connection	4/5/2018	FLIR GF320	None
												pancake	4/5/2018		
												stainlless cylineder	4/5/2017		
		7/9/2018	12:40	2:00	N.Summerfield	FLIR Certified	79	Clear	2	FLIR GF320	None	pop off	7/12/2018	FLIR GF320	None
												quick exhaust	7/9/2018		
												stainless fitting	7/9/2018		