cility	Location	Date of Survey	Beginning Time	End Time	Operator(s) Name Performing Survey	Operator(s) Training	Ambient Temperature (F)	Sky Conditions	Max Wind Speed	Monitoring Instrument Used	Any Deviations from Monitoring Plan	Number and Type of Components Leaking	Date of Successful Repair for Each Component	Remonitoring Instrument Used	Number and Type of Components Added to Delay of Repair List- Give Explanation of Why
oland	39.299039, -80.978379	9/25/2017	12:29	Not Recorded	N. Summerfield	FLIR Certified	N/A	N/A	N/A	N/A	N/A	pad shut in	N/A	N/A	N/A
		11/29/2017	8:00	12:00	N. Summerfield	FLIR Certified	37	Clear	5	FLIR GF320	None	Pancake regulator (2)	12/21/2017	FLIR GF320	None
												back pressure regualtor (3)	1/5/2018 Cancelled		Cancelled
												Pop off	1/16/2018		None
												hammer union	1/10/2018		
												stainless fitting (5)	11/29/2017		
												cylinder	11/29/2017		
												level controller	11/29/2017		
												supply line (2)	Nov-17		
												hammer union	11/29/2017		
		2/15/2018	1:30	2:00	N. Summerfield	FLIR Certified	58	Rain	0	AVO	Camera away for repairs	NO LEAKS FOUND	2/15/2018	N/A	N/A
		4/4/2018	10:45	1:00	N. Summerfield	FLIR Certified	38	Clear	10	FLIR GF320	None	regulator	23-Apr	FLIR GF320	None
												pancake	4/23/2018		
												valve	4/23/2018		
												pancake	4/4/2018		
												hammer union	4/4/2018		
												stainless fitting	4/4/2018		
		7/24/2018	9:30	12:30	N. Summerfield	FLIR Certified	76	Clear	2	FLIR GF320	None	pancake	8/6/2018	FLIR GF320	None
												quick exhaust	7/24/2018		
												pop off	7/24/2018		
												stainless fitting	7/24/2018		
												hammer union	7/24/2018		
erpoint	39.452022, -80.858967	11/8/2017	8:30	12:50	N.Summerfield	FLIR Certified	40	Clear	10	FLIR GF320	None	stainless connection	11/20/2017	FLIR GF320	None
												well head base	11/28/2017		
												valve	11/9/2017		
												pancake (2)	11/9/2017		
												valve	11/20/2017		
												pancake	11/20/2017		
												valve (3)	11/8/2017		
												stainless fitting (2)	11/8/2017		
												regulator	11/8/2017		
												hammer union (2)	11/8/2017		
		3/27/2018	12:25	1:20	N.Summerfield	FLIR Certified	44	Rain	5	AVO	Camera away for repairs	valve	4/4/2018	N/A	N/A
		4/25/2018	9:20	10:45	N.Summerfield	FLIR Certified	55	Cloudy	5	FLIR GF320	None	well head base (2)	closed	closed out	None
												pancake	5/1/2017	FLIR GF320	None
		7/11/2018	10:20	11:30	N.Summerfield	FLIR Certified	76	Clear	5	FLIR GF320	None	Solenoid	8/7/2018	FLIR GF320	None
												stainless fitting	7/11/2018		
												dump stuck (2)	7/11/2018		
evival	39.323976, -80.690379	9/22/2017	9:45	Not Recorded	N.Summerfield	FLIR Certified	61	Clear	0	FLIR GF320	None	Valve	10/9/2017	FLIR GF320	None
												pancake	10/9/2017		
												pop off	10/9/2017		
												stainless fitting (2)	9/22/2018		
												regulator	9/22/2018		
		12/11/2017	12:00	1:20	N.Summerfield	FLIR Certified	38	Clear	10	FLIR GF320	None	pop off (3)	1/9/2018	N/A	None
												level controller (2)	1/9/2018		
												quick exhaust	1/9/2018		
												stainless connection (3)	12/11/2017	FLIR GF320	