Facility	Location	Date of Survey	Beginning Time	End Time	Operator(s) Name Performing Survey	Operator(s) Training	Ambient Temperature (F)	Sky Conditions	Max Wind Speed	Monitoring Instrument Used	Any Deviations from Monitoring Plan	Number and Type of Components Leaking	Date of Successful Repair for Each Component	Remonitoring Instrument Used	Number Componen Delay of Give Exp W
RJ Smith	39.365733, -80.732951	8/10/2017	10:30	12:15	N. Summerfield	FLIR Certified	69	Clear	0	FLIR GF320	None	Quick Exhaust	8/16/2017	FLIR GF320	No
												Valtore box	8/11/2017		
												Quick Exhaust	8/10/2017		
												Stainless connection	8/10/2017		
												Pancake regulator	8/10/2017		
												Connection	8/10/2017		
		11/15/2017	8:30	10:30	N.Summerfield	FLIR Certified	31	Clear	1	FLIR GF320	None	pop off	11/16/2017	FLIR GF320	Nor
												regulator	11/16/2017		
												hammer union	11/15/2017		
												line connections	11/15/2017		
												stainless cylinder (2)	11/15/2017		
		3/16/2017	12:55	1:30	N.Summerfield	FLIR Certified	29	Clear	5	FLIR GF320	None	filter	3/16/2018	FLIR GF320	Non
		4/11/2017	9:30	10:15	N.Summerfield	FLIR Certified	37	Clear	5	FLIR GF320	None	stainless connection	3/16/2018		
		7/9/2018	10:25	11:30	N.Summerfield	FLIR Certified	75	Clear	2	FLIR GF320	None	stainless fitting	4/11/2018	FLIR GF320	Non
												threads	7/9/2018	FLIR GF320	Non
Rock Run	39.304841, -80.81482	10/17/2017	11:55	2:30	N.Summerfield	FLIR Certified	57	Clear	0	FLIR GF320	None	hammer union	10/31/2017	FLIR GF320	None
												threads	10/31/2017		
												stainless connection	10/31/2017		
												pancake (2)	10/31/2017		
												threads (3)	10/17/2017		
												stainless connections (3)	10/17/2017		
		3/12/2018	9:20	10:15	N.Summerfield	FLIR Certified	28	Snow	5	AVO	Camera away for repairs	NO LEAKS FOUND	N/A	N/A	N/A
		5/11/2018	12:15	1:15	N.Summerfield	FLIR Certified	67	Clear	5	FLIR GF320	None	solenoid	6/13/2018	FLIR GF320	1 waited on bat the came
												pancake	5/21/2018		
												threads (2)	5/11/2018		
		8/15/2018	10:10	11:40	N.Summerfield	FLIR Certified	67	Clear	1	FLIR GF320	None	solenoid	8/15/2018	FLIR GF320	None
												quick exhaust	8/15/2018		
Rush Fork	39.417142, -80.969564	7/18/2018	11:25	2:00	N.Summerfield	FLIR Certified	78	Clear	6	FLIR GF320	None	line connections	9/11/2018	FLIR GF320	1
												threads (2)	8/6/2018		
												threads	7/18/2018		
												regulator	7/18/2018		
Stewart	39.188493, -80.661604	8/17/2017	10:45	Not Recorded	N.Summerfield	FLIR Certified	75	Clear	0	FLIR GF320	None	valve	9/28/2017	FLIR GF320	None
												stainless connection (2)	8/17/2018		
												pop off	12/19/2017	FLIR GF320	None
		12/6/2017	9:30	10:30	N.Summerfield	FLIR Certified	32	Clear	5	FLIR GF320	None	NO LEAKS FOUND	N/A	N/A	N/A
		2/19/2018	11:30	12:00	N.Summerfield	FLIR Certified	56	Clear	5	AVO	Camera away for repairs	regulator	7/2/2018	FLIR GF320	None
												Rupture Disk	7/2/2018		
												stainless fitting (2)	6/6/2018		
		6/6/2018	1:00	1:45	N.Summerfield	FLIR Certified	64	Clear	5	FLIR GF320	None	valve	waiting for repair	FLIR GF320	None
												regulator (2)	9/5/2018		
												Stainless fitting	9/5/2018		
		9/5/2018	10:40	12:00	N.Summerfield	FLIR Certified	80	Clear	2	FLIR GF320	None	pop off	9/29/2017	FLIR GF320	None
Susie Jane	39.253808, -80.632219	9/14/2017	12:45	Not Recorded	N.Summerfield	FLIR Certified	61	Cloudy	5	FLIR GF320	None	pop off	1/3/2018	FLIR GF320	None
												NO LEAKS FOUND	N/A	N/A	N/A
		12/12/2017	8:30	9:30	N.Summerfield	FLIR Certified	32	Snow	10	FLIR GF320	None	NO LEAKS FOUND	N/A	N/A	N/A
		2/19/2018	8:45	10:00	N.Summerfield	FLIR Certified	56	Rain	5	AVO	Camera away for repairs	NO LEAKS FOUND	N/A	N/A	N/A
		5/30/2018	8:00	8:45	N.Summerfield	FLIR Certified	73	Clear	2	FLIR GF320	None	NO LEAKS FOUND	N/A	N/A	N/A
		8/22/2018	8:00	9:30	N.Summerfield	FLIR Certified	66	Cloudy	5	FLIR GF320	None	NO LEAKS FOUND	N/A	N/A	N/A