LDWSF
12.3.54 v6
09/03/86

"Rite in the Rain."
WEATHERPROOF

FIELD

NOTEBOOK NO. 351

Pioneer Construction
9/3/86

USEPA SF
1316396

9/3/86

Pioneer Construction
Materials Company

IN 1650
OUT 2200

Project Code : CDE-013C
Account Code : CDE-XOA

Lab # 86360100 - 124

Samples collected by Andy Hess
Photos by Jim Hileman
Log book Jim Hileman

86360104 1808 Andy & JRH

East end of washout trench at gate.

86360103 1812 Andy

Same location at 86360104

86360105 1820 Andy

Sample from tank with solids screen

86360106 1830 Andy

From 1st settling basin

86360108 1836 Andy

Below hole in wall just before 1st settling basin.

86360109 1845 Andy

Duwamish River at edge near screw Tank

86360~~108~~ 12 AH 1850 Andy

Solids below hole in wall

86360109 1853 Andy

Solid sample at edge of Duwamish just under water surface near screw Tank

86360110 1951 Andy
solids from screw tank

86360111 2008 Andy
Duwamish mid channel


This gate had several holes
solids screw
360103
360104
gates
settling pumps
1st
2nd
Truck wash ditch
wastes
sand Recovery Basin
360105
360106
solids
wastes
360110
wastes
gate
360107
360108
360112
Hole in wall
pump pipe
360109
Duwamish River
360111