Kitsap County Health
Grant Holdcroft Logbook Notes
for Kitsap Mystery Oil (Bremerton Gasworks Site)

BGWSF
1.5

Allaire farms 8/20/2010
Meeting.

Visited site w/ Kim Jones - PIC. Took 3 water samples. At base of fill, above, and below fill on Levolo Ck. Noted crack on top of fill w/ steam coming out of it. Took Photos of Crack. Delivered Samples to Twiss.

GAH.

9/23/2010

Thompson Oil Spill
Noon - Dave Z., GAH,
Visited Site. Oil on Beach
Tide coming in. 4x4 area
of heavy oil. Oily rock
collected. 20x20' Sheen on
water. Tide covering Spill.
Photos taken. Possibly from
uplands. Called Ecology.
off site 12:25. GPS Coord.
47.57829°
122.64233°

USEPA SF
1369901

Thompson Oil 9/24/2010

GAH, LF noon.

- Spots visible on beach. Hydrocarbon sheen. Sampled hole in beach dug w/ standard long handled shovel. mix of oil, sand, and water. Photos taken. Multiple holes dug to locate limits hydrocarbons in one spot only. Oil approximately 1-2" down in beach sediment. Gravel at 6-8". GPS hole position.. Moved stake to hole. Sampling from 1230 to 1240. 4oz jar.



Dug hole 2' in diameter -

GPS Coord. 47.57842°

122.64718°

GAH

Thompson Oil 10/1/2010

aka Port Washington Marina Oil

aka Kitsap Mystery Oil.

10:45 am - Inspected marina on report of sheen by DEM. Walked docks. Spoke to boat occupant. Strong odor of oil - same as previous site visit. Wind from ESE. Tide coming in. Some sheen on water in marina consistant w/ previously Ided location of oil on beach given tide & wind. Occupant stated old creosote plant possibly? Checked Pennsylvania Rd end. Spoke to Brian - SC fuels manager - He mentioned old coal Gasification Plant at Sesko site and remediation plan that fell through. Off site 11:30 AM

GAH