

Figure 4.7. Water level drawdown and recovery in Troll observation wells for the PTW-6 test.