

Figure 4.9. Water level drawdown and recovery from the Troll data loggers for the PTW-1 test.