DAM INSPECTION CHECKLIST
POSSUM POINT POWER STATION
POND ABC

INSPECTION DATE: FEB. 26, 2016

WEATHER: 39°F, MOSTLY CLOUDY

INSPECTED BY: K. AGEE

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	1012 → SAND BAGS + RIPRAP IN PLACE, AND NO STANDING WATER AGAINST SAND BAGS
Erosion	N	N	SEVERAL SAND BAGS RIPPED
Low Point, B dike*			
Flow	N	N	1015 → SAND BAGS IN PLACE AND NO STANDING WATER AGAINST SAND BAGS
Erosion	N	N	SEVERAL SAND BAGS ARE RIPPED
Outfall water surface El. (top of stoplogs to water)			1022 → NO STANDING WATER AGAINST WIER, WIER APPEARS TO BE DRY, NO FLOW THROUGH WIER.

* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.): LOW POINT, C DIKE → 1020 → SAND BAGS IN PLACE, SEVERAL SAND BAGS RIPPED, AND NO STANDING WATER AGAINST SAND BAGS
- STANDING WATER AT TOP OF PONDS EMBANKMENTS (AS NOTED ON FIGURE BELOW)
- STANDING WATER, WITHIN POND LIMITS, AT TOE OF EMBANKMENT OF POND C. SOME WATER AT TOE OF EMBANKMENT FOR PONDS A+B AS WELL.